

Form FTA-IR-1

United States Department of Transportation Federal Transit Administration

Agency/Department Information

Inspection Date	YYYY	MM	DD	Deport Number	20161101-WMATA-AD-1					
inspection Date	2016	11	01	Report Number						
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	RTRA	Sub- Dep				
Rail Agency Department	Name			Email	Office Phon	e	Ν	Mobile Phone		
Contact Information										
Inspection Location		Carmen Turner Facility 3500 Pennsy Drive, Landover MD								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	OPS-TNG-OBS					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

Inspection Activity #	1	Inspection S	ubject	Observation Audit of Radio Communication Training Course					Activity Co	ode	OP	PS	TNG	OBS	
Job Briefing Employee Name/Title	N/A	N/A				mpanied ector?	N/A	Out Brief Conducted	No	Time	070 103	-	Outside Shift	No	
Related Reports	No				Relat	ted CAPS /	Findings	N/A							
	Ref			Rule or	SOP		Standard		Other / T	ïtle		Chec	Checklist Reference		
Related Rules, SOPs, Standards, or Other	MSRP	MSRPH Genera			l Rules 1	.69–1.88		Х		х			Х		
standards, or other	Perma	anent Order		NO. T-1). T-16-10										
	Maii Trac	Yard	Sta	ition	осс	RTA Facility	Main Track	Yard	At-grade	e Tu	nnel	Elev	vated	N/A	
Inspection Location						х								х	
		Tra	:k			Chain Marker		From		То					
Line(s)	N/A	Nur	nber	N/A		and/or Station(s) N/A		N/A	N/A			4			
	Hea	d Car Numbe	r	Number	of Cars										
Vehicles		N/A		N,	'A	Equip	ment	N/A							
									Number	of Defect	:s			0	
Description		 al Observation The FW 		n ohserv	ad \\/\/\ A	TA Operati	ons "Radio C	Communication	Recomm	ended Fi	nding?			No	
Description						•	ev. 2 – July 2		Remedial Action Required?			ed?		No	
						,	,		Recomm	ended Re	einspec	tion?		No	

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

t and effective.	Digitally signed by Ambort DALET	
	DN: c=US, o=U.S. Government, ou=DOT	1
tor in Charge - Signature AMBUR DAI F	Headquarters, ou=FMCSAHQ, cn=AMBUR I	Date
r in bonn brie	DALEY	
	Date: 2016.11.18 07:50:09 -05'00'	
tor in Charge – Name Inspection Team		
Daley Tamara Powell, Chris DiFatta		
-		



	• The purpose of this course is to ensure that all WMATA employees,	
	contractors, and persons required to carry a radio understand radio	
	protocol and demonstrate comptetence in radio procedures.	
	 The rules that govern this course are MSRPH General Rules 1.69 – 	
	1.88, which establishes the proper way to communicate all radio	
	transmissions. Specifically, General Rule 1.79 describes radio protocol	
	for all users. This rule was recently modified per Permanent Order T-	
	16-10 Radio Protocols (issued July 19, 2016), which established and	
	formalized new radio procedures and verbiage that must be used.	
	• This course was revised to incorporate Permanent Order T-16-10	
	Radio Protocols requirements plus lessons learned from emergencies	
	at WMATA that resulted from radio communication errors between	
	personnel in field and the Rail Operations Control Center (ROCC).	
	• Participants were provided a copy of the most recent Safety Alert,	
	issued October 21, 2016, following a near miss incident.	
	The course was delivered as a Powerpoint presentation and included	
	scenario-based role play, video instruction, and modeling exercises.	
	 Participants were taught how to use the WMATA radio system and 	
	how to deliver and receive instruction using the standardized verbiage	
	established in Permanent Order T-16-10. The class also reinforced that	
	all radio users must begin their transmission with the required	
	identification, use word-for-word acknowledgements, and adhere to	
	the International Civil Aviation Organization (ICAO) standards for	
	communicating. Participants were taught the four parts to a	
	communicating. Participants were taught the four parts to a communication loop:	
	1. Introduction (e.g., positive ID, unit train number,	
	equipment ID, track number, and location)	
	2. <u>Reason for Message</u> (e.g., trouble, condition, relaying	
	information, requesting permission to perform an action)	
	3. <u>Response from Receiver</u> (e.g., grant permission, give	
	instruction, provide assistance or guidance)	
	4. <u>Closing the Communication</u> (e.g., "over" must be used to	
	signify turning control of the air time over to the other	
	person for reply, and ROCC shall signify the closing out of	
	the communication loop by using "out")	
	Participants were asked to demonstrate understanding of radio	
	communication protocols through role play exercises, which involved	
	scripted scenarios where the participants were required to identify the	
	missing part of the communication loop.	
	Note: During the class, participants posed questions related to communication	
	protocols, and there were several that the instructor was unable to answer. The	
	instructor has worked at WMATA for 1.5 years. The questions that went	
	unaddressed are documented below:	
	1 Are operators required to give a radio about to the DOCC Duit T. (f)	
	1. Are operators required to give a radio check to the ROCC Rail Traffic	
	Controller when he/she swings on to a new train or starts his/her	
	shift?	
	2. Should an operator give a radio check to the ROCC RTC when changing	
	Ops territory (i.e., changing from Ops 1 to 2 when changing	
	destination or to another rail line)?	
	3. Is it a requirement for operators to give hourly radio checks?	
	4. Is a confirmed report of high water still classified as a "life emergency"	
	situation? The DTS department has reportedly responded to incidents	
	of confirmed flooding alarms in the field, and are frequently told to	
	stand by when trying to relay this report to the ROCC RTC.	
	5. When the scheduled RWP protects are broadcast to the field, are	
	operators required to give a word-for-word read back to the ROCC	
	RTC? (This question was asked in response to recent near miss	
	incidents that involve roadway workers. Specifically, when personnel	
	request Foul Time or Exclusive Track Occupancy protection, how are	
	they assured that trains are aware of their location?)	
Remedial Action	N/A	



Washington Metropolitan Area Transit Authority

METRORAIL SAFETY RULES AND PROCEDURES HANDBOOK

PERMANENT ORDER

NO. T-16-10 Radio Protocols, Modification to General Rule 1.79

Date: Tuesday, July 19, 2016

TO: All Personnel

Permanent Order T-16-10 establishes new radio protocols to provide formal authorized standard verbiage to be used in communicating certain terms and acknowledgements. The new protocols also reinforce the need to restate, word for word, at all times, the communications received. This order modifies **General Rule 1.79**.

Modifications made to **General Rule 1.79** are shown below with additions underlined and highlighted.

Modifications made to General Rule 1.79:

1.79 Employees shall not take any action until they are positive that all radio transmissions or receptions are heard, fully understood and acknowledged. Individual radio transmissions shall, at all times, be repeated by the receiver so the transmitter can confirm the message was received completely and by the intended receiver. Whenever the transmitter has completed their transmission and is turning the airtime over to the receiving party for acknowledgement or reply, they are to end their communication with the word "over". Speed restrictions must always be acknowledged by each Train Operator, even when a blanket message is sent out from Central Control, through 100 percent word for word repeat back from the Operators to Central Control or the Tower.

Positive Identification must be established prior to transmitting a message. Positive identification includes the transmitter stating their Train/Equipment Number or Unit ID Number, location and track number at the beginning of a transmission and the receiver repeating back the Train/Equipment Number

or Unit ID Number, location and track number when acknowledging the radio call.

When communicating with Class I and Class II vehicles, employees are to identify the train ID or unit ID by the complete number series. This method of positive train/unit identification shall be consistently used when transmitting and acknowledging information. Examples: Train ID 404 shall be identified as "four zero four". Train ID 414 shall be identified as "four fourteen", instead of "four one four". Train 932 shall be identified as "nine thirty two". PM-32 shall be identified as "PM thirty two" instead of "PM three two".

When communicating location information related to Power Rooms only (TPSS or TBS), that is Alpha-Numeric (e.g. C-07, E-07, B-14), employees must use the International Civil Aviation Organization (ICAO) standard for communicating the "Alpha" character. For example: C-07 shall be identified as "C-Charlie- Zero Seven". E-07 shall be identified as "E-Echo-Zero Seven".

Letter	Word	Pronunciation
А	ALFA	AL FAH
В	BRAVO	BRAH VOH
С	CHARLIE	CHAR LEE (or) SHAR LEE
D	DELTA	DELL TAH
E	ECHO	ECK OH
F	FOXTROT	FOKS TROT
G	GOLF	GOLF
Н	HOTEL	HOH TELL
I	INDIA	IN DEE AH
J	JULIETT	JEW LEE ETT
К	KILO	KEY LOW
L	LIMA	LEE MAH
М	MIKE	MIKE
N	NOVEMBER	NO VEM BER
0	OSCAR	OSS CAH
Р	PAPA	PAH PAH

International Civil Aviation Organization (ICAO) Standard


Q	QUEBEC	KEH BECK
R	ROMEO	ROW ME OH
S	SIERRA	SEE AIR RAH
Т	TANGO	TANG GO
U	UNIFORM	YOU NEE FORM (or) OO NEE FORM
V	VICTOR	VIK TAH
W	WHISKEY	WISS KEY
X	XRAY	ECKS RAY
Y	YANKEE	YANG KEY
Z	ZULU	ZOO LOO

Below is a list of authorized terms and responses to be used, in all cases, as applicable, in communicating with the Rail Operations Control Center (ROCC):

TERM	DESCRIPTION
Central	Rail Operations Control Center (ROCC)
Copy	The transmission was heard and understood
Disregard	Canceling previous instructions
Hold	Hold your position - DO NOT MOVE until so instructed
Affirmative	Yes
Landline	Call by telephone, specified number or person
Out	Used by Central Control (ROCC). End of transmission,
	no reply is needed
<u>Over</u>	I am finished with my transmission and I am turning
	control of the air time over to you and I am awaiting your
	response
Proceed	Permission to move train
<u>Negative</u>	No
<u>Repeat</u>	Repeat all of your last transmission
Single	Controlled changes in the direction of traffic, on a single
Tracking	main line track segment, between selected
	interlockings.
Urgent (to be	Repeated three times consecutively (Urgent, Urgent,
<u>used in</u>	Urgent) to notify parties of a hazardous condition which
emergencies)	could result in death or injury, damage to property, or
	cause a serious disruption in operations.

Standby	STOP TRANSMITTING (Calling station should honor
	"standby" without question unless the calling station
	has an URGENT call to report) Wait for further
	instruction

As a means of ensuring that messages are not interrupted on the different talk group radio channels (OPS2, OPS3 etc.), when an employee is communicating with Central Control, Central will close out a communication loop by saying "Central, out". Central saying "out" signifies that no response is necessary or expected from the other party and is the end of a that communication. This then opens up the airway for another party in the same talk group to then begin their transmission.





Approve:

Chief Safety Officer System Safety and Environmental Management

Approve: Managing Director



Assistant General Manager Transit Infrastructure and Engineering Services



Inspection Form

Form FTA-IR-1

United States Department of Transportation Federal Transit Administration

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20161104-WMATA-CD-1					
inspection Date	2016	11	04	Report Number	20101104-WINATA-CD-1					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	OPMS	Sub- Dep	artment	RWP		
		Name		Email	il Office Phone			Aobile Phone		
Rail Agency Department										
Contact Information										
Inspection Location	Carmen Turner Facility									
In the station of the state of										

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	RWP-TNG-OBS					
Inspection Units	1					
Inspection Subunits	5					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

-														1
Inspection Activity #	1	Inspection Su	oject	Observa	ation of I	RWP Level	4 Training		Activity Co	ode	RW	/P	TNG	OBS
Job Briefing Employee Name/Title	N/A	N/A			Accon Inspec	npanied ctor?	No	Out Brief Conducted	No	Time	70 150	-	Outside Shift	No
Related Reports	N/A				Relate	ed CAPS / F	indings							
	Ref	Ref Rule or S			OP		Standard		Other / T	itle		Check	ist Refer	ence
Related Rules, SOPs, Standards, or Other	RWPN	RWPM												
	MSRP	MSRPH												
luces attack to action	Maiı Trac	Yard	Stat	tion C	DCC	RTA Facility	FTA Office		At-grade Tu		nnel Elev		vated N/A	
Inspection Location						х		Track Type						х
Line(s)	N/A	Track		N/A		Chain Ma	ker		From				То	
Line(s)	N/A	Numl	per	N/A		and/or Sta	ation(s)	N/A			N/A			
Makida a	Неа	d Car Number		Number o	of Cars			N1 / A						
Vehicles		N/A		N/A		Equip	ment	N/A						
Description					oadway Worker Protection (RWP) Level 4 class from					of Defect	s			0
		er 31 through I ble to WMATA		-				0	Recommended Finding?					No
	avana		person	inci, and it	. is requi	rea belore	an employe		Remedia	l Action R	equire	d?		No

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

Sufficient and effective.			
Inspector in Charge - Signature	AMBUR I DALEY	Digitally signed by AMBUR I DALEY DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY Date: 2016.11.21 21:39:13 -05'00'	Date
Inspector in Charge – Name Ambur Daley	Inspection Team Curtis Dougherty, Al Nepa, Kevin McD	onald, Tino Sahoo, Mike Vitale	

a Roadway Worker in Charge (RWIC).		
The RWP Level 4 course is five days long and builds upon the materials learned in the RWP Level 1 and 2 courses (there is no Level 3 course), as well as the experience of the students, who are required to have at least one year of experience on the WMATA roadway prior to taking this class.		
The RWP Level 4 course focuses on three main areas of responsibility for the RWIC: the job safety briefing, communication with the ROCC, and setup and oversight of the work zone. More specifically, an RWIC is responsible for communicating with the ROCC, reviewing the roadway access guide to establish a safe work area, providing a comprehensive job safety briefing prior to setting up the work area, ensuring that a work zone is safely established in compliance with the RWP manual and takes into account additional needs based on the access guide, coordinating activities throughout the work zone, and ensuring that the work area has been cleared and returning the track to revenue service.		
This class first covers the required RWIC responsibilities in the classroom and then uses role playing so that participants can practice giving job briefings and other communications to workers and the ROCC. Finally, the field portion of the training allows trainees to set up simulated work zones, working limits, and protections.	Recommended Reinspection?	No
At the conclusion of the class, students are required to demonstrate their mastery of the content by completing a RWP cardinal rules exam (100% correct requirement), a RWP general knowledge exam (92% correct requirement), and a practical exercise where the student must demonstrate a mastery of the job safety briefing, communication with the ROCC, and successful work zone setup and break down in a simulated roadway environment.	Recommended Reinspection:	NU
FWSO observed 4 students complete this course. The instructors were extremely knowledgeable about the subject matter and encouraged class participation to ensure all participants understood the material. Additionally, the instructors encouraged more experienced students to share their experiences on the roadway and made notes regarding potential improvements to the RWP program. The instructors clearly demonstrated the use of all safety equipment, proper work zone setup across all types of protections used at WMATA, effective communication with the ROCC, and how to conduct a proper job safety briefing.		
In addition to the RWP manual, the instructors provided the class with supplemental materials to help conduct a job safety briefing and communicate with the ROCC. These materials helped ensure that the students covered all required elements in a uniform fashion across every type of work zone setup allowed at WMATA.		

Inspection Form

Form FTA-IR-1

FOIA Exemption: All (b)(6)

United States Department of Transportation Federal Transit Administration

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	Number 20161105-WMATA-AD-1					
	2016	11	05	Report Number						
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	ROCC	Sub- Dep	Sub- Department TNG			
Rail Agency Department	Name			Email	Office Phon	e	Mobile Phone			
Contact Information										
Inspection Location	Carmen Turn	er Facility								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	ROCC-TNG-OBS					
Inspection Units	1					
Inspection Subunits	10					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

•															
Inspection Activity #	1	Inspec	tion Subje	ect	Bridge (Control	ler Training			Activity Co	ode	RO	сс	TNG	OBS
Job Briefing Employee Name/Title	N/A				Accompanied Inspector?			N/A	Out Brief Conducted	No	Time	080 160		Outside Shift	No
Related Reports						Relat	ted CAPS / F	indings							
	Ref Rule or SO			OP		Standard		Other / T	ïtle		Chec	klist Refe	rence		
Related Rules, SOPs, Standards, or Other															
Inspection Location	Main Track Yard Station OCC RTA Facility		FTA Office	Track Type	At-grade	e Tu	nnel	Ele	vated	N/A					
inspection Location							Х		Track Type						х
Line(s)	N/A		Track Numbe	r	N/A		Chain Mai and/or Sta		N/A	From To N/A					
	Hea	ad Car N	lumber	١	Number	of Cars									
Vehicles		N/A			N/A	١	Equip	ment	N/A						
										Number	of Defect	s			0
		•						raining Prog p of very exp		Recomm	Recommended Finding?				No
Description							, .	ations Depart		Remedial Action Required?					No
Description	10-da	ay refres	her consis	ted o	f classroo	om lect	ures and pra	actical simula	tions.	Recomm	ended Re	inspec	tion?		No

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective

sufficient and effective.			
Inspector in Charge - Signature		Digitally signed by AMBUR I DALEY	Date
	AMBUR I DALEY	DN: c=ÚS, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY	
Inspector in Charge – Name	Inspection Team	Date: 2016.11.14 14:08:40 -05'00'	
Ambur Daley	Chris DiFatta, Tamara Powell, Curtis D	ougherty	



The program was divided into six modules:	
Incidents and Emergency Course, which covered:	
 SOP # 1A – Command, control, and coordination of 	
emergencies on the rail system	
• SOP # 6 – Fire and smoke on the roadway	
• SOP # 24 – Sick customer on a train	
• SOP # 4A – Customer self-evacuation from trains	
• SOP # 4 – Customer evacuation from train	
• SOP # 9 – Train derailment	
 SOP # 15 – Absolute block/permissive block 	
 SOP # 14 – Bomb threat/suspicious or unattended package 	
 SOP # 37 – Hazardous material incident 	
 SOP # 42 – Hazardous chemical detection alarm procedures 	
 SOP # 38 – Unknown substance response procedure 	
• SOP # 8 - Fire and smoke in a station	
 SOP # 13 – Undesired uncoupling or pull apart of cars 	
• SOP # 27 – Flammable vapor alarm	
• SOP # 11 – Train collision	
 SOP # 34 – Defective trains Radio Communication Course, which covered: 	
 International Civil Aviation Organization (ICAO) phonetic alphabet 	
 alphabet Repeat back transmission by the receiver so transmitter can 	
 Repeat back transmission by the receiver so transmitter can confirm the message was received completely 	
 Radio checks Radio message formatting 	
Radio message formatting	
Controller Entry Skills and Tasks Course, which covered: Train provide the sectors	
 Train movement control 	
 Maintaining headway strategies 	
 Red signal overrun reviews 	
• Switch correspondence reviews	
Traffic Management Strategies Course, which covered:	
• Headway adherence	
 Single tracking 	
 Review of fan and tunnel exhaust procedures 	
• MSRPH, which covered:	
 Review of cardinal and general rules 	
 Updates of temporary and permanent orders 	
 Daily track characteristics/layout exercises from the Rules 	
and Simulations course of the Initial Controller Program	
Troubleshooting, which covered:	
 BRAKES ON fails to illuminate 	
 BRAKES OFF fails to illuminate 	
 Brakes in Emergency (BIE) – (train fails to charge) 	
 Air isolation procedure 	
 Total isolation procedure 	
 ALL DOORS CLOSED fails to illuminate 	
 Loss of speed commands 	
 Train does not operate in automatic 	
 Overspeed alarm procedure 	
Included in the Program were 10 simulations and 1 Final Exam that were part of the	
Incidents and Emergency Course. The students must obtain an 85% on the exam to	
pass the course.	
The Instructors had command of the classroom, materials, and the ability to convey	
their knowledge and experience to the students. They also did a great job	
encouraging students to actively participate in the program. There was excellent	
feedback from the students, and it appeared they were eager to comprehend the	
materials.	

Inspection Form

Form FTA-IR-1

Agency/Department Information

Federal Transit Administration

Inspection Date	YYYY	MM	DD	Report Number	20161106-WMATA-AD-1				
inspection Date	2016	11	06	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	TRST	Sub- Department		Production	
	Name			Email	Office Phone		Mobile Phone		
Rail Agency Department									
Contact Information									
Inspection Location	Southern Avenue Station, Green Line								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	ROCC-SAFE-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	1					
Recommended Finding	No					
Remedial Action Required ¹	Yes					
Recommended Reinspection	No					

Activity Summaries

-														
Inspection Activity #	1 l	nspection Sub	ect	Rail Op	erations	S Control Ce	nter - SAFE		Activity Co	ode	RO	CC S	AFE	OBS
Job Briefing Employee Name/Title	SAFE unit 20				mpanied ector?	No	Out Brief Conducted	No	Time	093 123		Dutside Shift	Yes	
Related Reports	N/A				Relat	ed CAPS / I	indings	N/A						
	Ref			Rule or S	OP		Standard		Other / T	ïtle		Checkl	ist Refer	ence
Related Rules, SOPs, Standards, or Other														
Standards, or other														
	Main Track	Yard	Stat	tion	CC	RTA Facility	FTA Office	Treads Treas	At-grad	e Tui	nnel	Eleva	ated	N/A
Inspection Location	х		>	ĸ				Track Type	x		х			
1:	Crear	Track		1		Chain Ma	rker		From			1	То	
Line(s)	Green L	Numbe	er	1		and/or St	ation(s)	Southern Ave	nue Station	nue Station South			nue Stat	ion
	Head	Car Number		Number	of Cars									
Vehicles		N/A		N/#	A	Equip	ment	N/A						
									Number of Defects 1				1	
Description		nspectors obse WMATA's qua				0		•	Recomm	Recommended Finding?				No
	execute		interry	y run scale	exercis	e senes (m	ock uisdster),	WINCH	Remedia	l Action R	equire	d?		Yes

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

sujjielent and ejjeetive.		
Inspector in Charge - Signature	Digitally signed by AMBUR I DALEY	Date
Λ		
A		
	Date: 2016.11.29 10:59:27 -05'00'	
Inspector in Charge – Name	Inspection Team	
Ambur Daley	Corwyn Foster, Al Nepa	



	 simulated a train emergency involving a train fire and smoke in a tunnel and included the evacuation of passengers and casualties. General observations: Prince George's County first responders did not have possession of a key to override the elevator for manual operation. Prince George's first responders struggled with the application of the Warning Strobe Alarm Device (WSAD) wayside paddles, specifically with the ground connection. 	Recommended Reinspection?	No				
Remedial Action WMATA should provide Prince George's County first responders a key for all system elevators and provide training for the proper use of the WSAD wayside paddles.							

Form FTA-IR-1

United States Department of Transportation Federal Transit Administration

Agency/Department Information

Increation Date	YYYY	MM	DD	Poport Number	20161107-WN		Г 1	
Inspection Date	2016	11	07	Report Number	20101107-001	ATA-CD	L-T	
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	TRST	Sub- Depai	rtment	Production
		Name		Email	Office Phone	e	Ν	Nobile Phone
Rail Agency Department								
Contact Information								
Inspection Location	Fort Totten,	Red Line, B-06	5					
Inspection Summary								
Inspection Activity #	1		2	3	4	5		6
Activity Code	TRK-RW	P-OBS	OPS-RI-OBS					
Inspection Units	1		1					
Inspection Subunits	1		3					
Defects (Number)	0		1					
Recommended Finding	Nc)	Yes					
Remedial Action Required ¹	Nc)	Yes					
Recommended Reinspection	Nc)	Yes					

Activity Summaries

Inspection Activity #	1	Insp	ection Subj	ect	Roadwa	ay Work	er Protec	tion – Job Safe	ty Briefing	Activity Co	de	TR	кĸ	RWP	OBS
Job Briefing Employee Name/Title	TRST	UNIT (6107– SAFE	20		Accompanied Inspector?			Out Brief Conducted	No	Time	080 100		Outside Shift	No
Related Reports						Related CAPS / Findings									·
	Ref				Rule or S	or SOP Standard				Other / T	itle		Chec	klist Refer	ence
Related Rules, SOPs, Standards, or Other	Temp T-16-:	pporary Order 5-12													
1	Mai Trac	Yard Stati		ion (OCC RTA Facility		FTA Office	T	At-grade	e Tui	innel E		vated	N/A	
Inspection Location	x			х	(Track Type	x					
			Track				Chain N	arker		То					
Line(s)	Red L	ine	Numbe	er	1		and/or	station(s)	B-06			B-06			
	Hea	d Car	Number		Number o	of Cars						1			
Vehicles		N/	'A		N/A	1	Equ	pment	N/A						
								nporary Order	-	Number of Defects					0
Description		Access to Safe Track Location, which Fort Totten platform without having t					h provides access to the work zone from the				Recommended Finding?				No
	FOILT	otten	placionniv	nulou	it naving t	o access the right of way.				Remedial Action Required					No

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge - Signature	CORWYN DALE FOSTER Did: cells, oeuS, Government, ou-DOT FRAAtlantaGA, ou-FRA FRAAtlantaGA, co-WWN DALE FOSTER Date: 2016.11.15 17:24:47 -05'00'	Date October 03, 2016
Inspector in Charge – Name Corwyn Foster	Inspection Team Corwyn Foster & Al Nepa	



	Prior to entering the Surge 10 work location, a briefing was provided by TRST Unit #6107 at the Safe Track Surge entrance at Fort Totten. The briefing was comprehensive and thorough. It included a WMATA level 1 ID check; safety rule review (3.67); red tag outage numbers; Mobile Command Center (MCC) telephone number; type of protection (inaccessible track); and locations of barriers, mats, hospital locations, and potential hazards.	Recommended Reinspection?	No
	At the Fort Totten platform location (CM 275+76, B-06), SOP 28 was superseded by Temporary Order Number T-16-12, which provided fence protection from the roadway on both sides to the surge working limits. Signage to contact MCC prior to entering and fencing location was compliant. No exceptions were taken with the briefing.		
	No exceptions were taken with the brennig.		
Remedial Action	N/A		

Inspection Activity #	2	Insp	ection Sub	ject	Ope	erations	s Ridin	ng Inspecti	on		Activity Co	de	OF	PS	RI	OBS
Job Briefing Employee Name/Title	N/A				Accompanied Inspector?		N/A	Out Brief Conducted	N/A	Time	0130 1530		Outside Shift	No		
Related Reports						R	Relate	d CAPS / I	indings							
	Ref				Rule or SOP Standard				Other / T	itle	klist Refe	rence				
Related Rules, SOPs, Standards, or Other	SOP															
Standards, or Other																
	Mai Trac		Yard	Sta	tion	000	с	RTA Facility	FTA Office		At-grade	ade Tunnel			vated	N/A
Inspection Location	x				х					Track Type					х	
	Green Line Track Chain Marker								From				То			
Line(s)		Blue Line Yellow Line			1		and/or Station(s) B-06						B-35			
	Hea	ad Car	Number		Num	ber of C	Cars									
Vehicles	5164	, 3129	, 6033			N/A		Equip	ment	N/A						
								•	•	ned on red line	Number	of Defect	s			1
			,					,	w line train n		Recomm	ended Fir	nding?			Yes
			complianc		served	a on yei	IOW III	ie train nu	imber 302, a	ll operators	Remedia	Action F	Require	d?		Yes
Description	the p	ortal e	entrance be	Yellow line train number 302, operator failed to signal (sound horn) at										Yes		
					0	0			erved betwee ut, or covere							
Remedial Action	To en	isure c		with	TRST	1000 st				e appropriate re	epairs to the	poor ligh	ting co	ndition	s identifi	ed betwee



Inspection Form

Form FTA-IR-1

Federal Transit Administration

Agency/Department Inform	nation										
Inspection Date	YYYY	MM	DD	Report Number	20161108-WN						
Inspection Date	2016	11	08	Report Number	20101108-001	//ATA-AD-1					
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	Track	Sub- Department					
	1	Name		Email	Office Phone	Mobile Phone					
Rail Agency Department Contact Information	cy Department										
Inspection Location	Surge 10 Wo	rge 10 Work Area - NOMA to Fort Totten									

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TRK-JSB-OBS	TRK-GEN-PI	TRK-RWP-PI	SAF-RAG-PI		
Inspection Units	1	1	1	1		
Inspection Subunits	1	1	1	1		
Defects (Number)	0	0	2	1		
Recommended Finding	No	No	Yes	Yes		
Remedial Action Required ¹	No	No	Yes	Yes		
Recommended Reinspection	No	No	Yes	Yes		

Activity Summaries

Inspection Activity #	1	Inspection Su	bject	Job Safe	ety Briefi	ng			Activity Co	ode	TR	K	JSB	OBS
Job Briefing Employee Name/Title	SAFE 2	206			Accon Inspec	panied tor?	Yes	Out Brief Conducted	No	Time	120 150		Outside Shift	No
Related Reports	N/A				Relate	d CAPS / F	indings	N/A				·		
	Ref			Rule or S	or SOP Standard				Other / T	ïtle		Checl	klist Refer	ence
Related Rules, SOPs, Standards, or Other	RWPN	Л												
Standards, or other	MSRP	Н												
In an action I continue	Maiı Trac	Yard	Sta	tion (DCC	RTA Facility	FTA Office	Tuesda Taura	At-grad	e Tui	nnel	Elev	vated	N/A
Inspection Location	x							Track Type	x					
Line(s)	В	Trac		1 and 2	,	Chain Ma	rker		·	То				
Line(s)	D	Num	ber	1 anu 2	2	and/or Sta	ation(s)	114+00			270+0	270+00		
	Неа	d Car Number		Number o	of Cars									
Vehicles		N/A		N/A	1	Equip	ment	N/A						
Description		received a co				0			Number	of Defect	s			0
	designated by the RWIC (Mobile Command) and the specific gang leader, SAFE 20 Each briefer reviewed all necessary information, including protection in place,								Recommended Finding?					No
		st hospital, ess					• •	•						No
	FWSO	FWSO was part of a mobile work gang that would be traveling through multiple								Recommended Reinspection?				No

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge - Signature	AMBURIDALEY DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBURIDALEY Date: 2016.11.17 09:46:07 - 05'00'	Date
Inspector in Charge – Name Ambur Daley	Inspection Team Chad Broski, Kevin McDonald, Mike Vitale	



	work areas during the inspection. Both briefers stressed that we would be contacting the gang leader for each area in order to pass through that area safely.	
	General Observations: Briefing did not include the locations and types of work being performed, only a mention that work is ongoing and we should be vigilant. All communication of work locations was made during radio transmissions with the RWIC when requesting permission to enter the roadway.	
Remedial Action	N/A	

Inspection Activity #	2	Inspect	tion Subj	ject	Work Z	one Ins	pection			Activity Co	ode	TR	к	GEN	PI
Job Briefing Employee Name/Title	SAFE 2	206					mpanied ector?	Yes	Out Brief Conducted	No	Time	120 150		Outside Shift	No
Related Reports	N/A					Relat	ed CAPS / F	indings	N/A						
	Ref				Rule or SOP Standard				Other / Title Ch				klist Refer	rence	
Related Rules, SOPs, Standards, or Other	RWPN	1													
otaliaalao, or other	MSRP	4													
Increasion Location	Mair Trac	1	Yard	Stati	on (осс	RTA Facility	FTA Office	Treak Ture	At-grade	e Tu	nnel Elev		vated	N/A
Inspection Location	x								Track Type	x					
Ling(a)	в		Track		1 and	2	Chain Mar	ker		From				То	
Line(s)	D		Numbe	er	1 anu .	2	and/or Sta	ation(s)	114+00			270+0	00		
	Hea	d Car Nu	umber	1	Number	of Cars									
Vehicles		N/A			N/A	4	Equip	ment	N/A						
	FWSO	perforn	ned an ir	nspecti	ion of the	e entire	SafeTrack w	vork area.	1	Number	of Defect	s			0
	Gener	al Ohser	rvations:							Recomm	ended Fir	nding?			No
	Gener				observed	inadeq	uate ballast	support at t	his chain	Remedia	l Action R	Require	d?		No
Description		studs.										Yes			
Remedial Action	N/A		5 area ne			e replu			• up.						

Inspection Activity #	3	Inspection Sub	ject	Work Zo	one Insp	ection			Activity Co	de	TR	К	RWP	PI
Job Briefing Employee Name/Title	SAFE 2	206			Accon Inspec	npanied ctor?	Yes	Out Brief Conducted	No	Time	120 150	-	Outside Shift	No
Related Reports	N/A				Relate	ed CAPS / F	indings	N/A						
	Ref			Rule or S	SOP Standard				Other / T		Chec	klist Refer	ence	
Related Rules, SOPs, Standards, or Other	RWPN	1												
Standards) of Other	MSRPI	Н												
	Mair Tracl	Yard	Stati	ion C	осс	RTA Facility	FTA Office		At-grade	e Tui	nnel	Elev	vated	N/A
Inspection Location	х							Track Type	х					
Line(c)	в	Track		1 and 2		Chain Ma	rker	From			То			
Line(s)	Б	Numb	er	1 anu 2		and/or Sta	ation(s)	114+00			270+0	00		
	Head	d Car Number		Number o	of Cars		_							
Vehicles		N/A		N/A		Equip	ment	N/A						
Description	FWSO	performed an i	nspect	ion of the	RWP se	et up for en	tire SafeTrac	k work area.	Number	of Defect	s			2



	The following items were noted.	Recommended Finding?	Yes
	Defects:	Remedial Action Required?	Yes
	 FWSO noted only one Warning Strobe and Alarm Device (WSAD) in place in the entire work area. WMATA must ensure that WSADs are placed in accordance with the RWP manual which states, "The WSAD shall be used anytime any roadway worker or equipment has the potential of making contact with the third rail or any associated parts or equipment attached to the third rail." This is especially important at the interlocking near Brentwood Yard, where there are energized third rails near the work area. FWSO noted that one of the red lanterns signifying the end of the work area at B2 114+00 was not functioning. Mobile Command sent an employee with new replacement lantern. 	Recommended Reinspection?	Yes
Remedial Action	WMATA must ensure that WSADs are properly installed within working limits.	1	1

Inspection Activity #	4	Inspe	ection Subj	ect	Work 2	Zone Ins	pection			Activity Co	ode	SA	١F	RAG	PI
Job Briefing Employee Name/Title	SAFE	206					mpanied ector?	Yes	Out Brief Conducted	No	Time	120 150		Outside Shift	No
Related Reports	N/A					Rela	ted CAPS /	Findings	N/A						
	Ref				Rule or	SOP		Standard		Other / T	ïtle		Che	cklist Refe	rence
Related Rules, SOPs, Standards, or Other	RWP	М													
Standards, or other	MSRI	РΗ													
	Ma Tra		Yard	Stat	ion	OCC	RTA Facility	FTA Office		At-grad	e Tu	nnel	Ele	evated	N/A
Inspection Location	x								Track Type	х					
1 (.)			Track		4	2	Chain Ma	rker		From				То	
Line(s)	В		Numbe	r	1 and	2	and/or Station		114+00	+00		270+	00		
	Hea	ad Car	Number		Number	of Cars									
Vehicles		N//	A		N/	Ά	Equip	ment	N/A						
								MATA's Road		Number	of Defect	s			1
								oadway wor	kers. In the tween 99+00	Recomm	ended Fi	nding?			Yes
Description									ver, the station	Remedia	l Action F	Require	d?		Yes
			85 are 101+ configuratio				way Access	Guide does r	ot accurately	Recomm	ended Re	einspec	tion?		Yes
Remedial Action		ATA mu way wo		nd re	evise the	Roadwa	y Access Gu	ide to more	accurately refle	ct the config	uration fo	or this a	area a	nd provide	clarity to

Photos:





7 ¾" wide tie



New nut style with more beveled edge





Low Crib Ballast at B2 138+00



Form FTA-IR-1

Agency/Department Information

Federal Transit Administration

	YYYY	MM	DD		204 644 00 11/1			
Inspection Date	2016	11	09	Report Number	20161109-WN	/IATA-A	D-1	
Rail Agency Name	Washington Authority	Metropolitan /	Area Transit	Rail Agency Department	TRST OPS SMNT	Sub- Department		Production RAIL ATC
		Name		Email	Office Phone	5	Ν	Nobile Phone
Rail Agency Department Contact Information								
Inspection Location	K-Line – Trac	k #1 – Dunn Lo	oring to Vienna					

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TRK-RWP-OBS	OPS-RC-OBS	TRK-GEN-OBS			
Inspection Units	1	1	1			
Inspection Subunits	2	7	1			
Defects (Number)	0	1	3			
Recommended Finding	No	No	No			
Remedial Action Required ¹	No	Yes	Yes			
Recommended Reinspection	No	Yes	No			

Activity Summaries

Inspection Activity #	1	Inspecti	ion Subj	ect	RWP Job	Safety	Briefing ar	nd On-Track I	Protection	Activity Co	de	TR	К	RWP	OBS
Job Briefing Employee Name/Title		Unit #207 Unit 6101				Accom Inspec	npanied ctor?	Yes	Out Brief Conducted	Yes	Time	100 133	-	Outside Shift	No
Related Reports						Relate	ed CAPS / I	indings							
	Ref				Rule or S	OP Standard				Other / T	Other / Title			cklist Refer	ence
Related Rules, SOPs, Standards, or Other	RWPN	N													
Standards, or other	MSRP	н													
	Maii Trac	Y	'ard	Stati	on C	осс	RTA Facility	FTA Office		At-grade	e Tur	nnel	Ele	evated	N/A
Inspection Location	х								Track Type	x					
Line(a)	K Line		Track		1		Chain Ma	rker		From				То	
Line(s)	K-Line	:	Numbe	r	1		and/or St	ation(s)	K1 CM653+00)		K1 CN	/1777+	-00	
	Hea	d Car Nu	mber	١	Number of Cars										
Vehicles		N/A			N/A		Equip	ment	N/A						

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge - Signature	AMBUR I DALEY	Digitally signed by AMBUR I DALEY DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY Date: 2016.11.14 10:50:8-05'00'	Date
Inspector in Charge – Name Ambur Daley	Inspection Team Robert Maniuszko		

	Job Safety Briefing:	Number of Defects	0
	 SAFE Unit #207 was the RWIC. All PPE and IDs were checked. 	Recommended Finding?	No
	 The Job Safety Briefing was led by SAFE Unit #207. 	Remedial Action Required?	No
Description	 TRST Unit #6101 provided watchman/lookout duties for the team. The area inspected included two caution areas. For the noise area, the watchman used an air horn and walked approximately 500 feet in front to provide adequate warning. For the crossover, the ROCC required the team to request foul time to traverse the interlocking. Each method provided ample time for the team. Train Approach Warning (TAW) was the primary method of protection. ROCC was on OPS #2. Closest hospital was Inova Fairfax. If there was an emergency we would use an ETS box and dial "0". Clearance would be toward the field side fence. No exceptions were taken to the Job Safety Briefing. On-Track Protection: The methods described above provided the team with adequate warning and ample time to clear to a position of safety. The watchman was equipped with a whistle and an air-horn. No exceptions were taken to the protection provided while on the roadway. 	Recommended Reinspection?	No
Remedial Action	N/A		

Inspection Activity #	2 In	spection Sub	ject	Rul	e Compl	iance C	Observat	tions			Activity Coo	de	O	PS	RC	OBS
Job Briefing Employee Name/Title		t #207 - RWI t 6101 - Esco				ccompa specto		Yes	Out Brief Conducted		Yes	Time	me 1000 133		Outside Shift	No
Related Reports					R	elated	CAPS / I	Findings								
	Ref			Rule	ule or SOP Standard				Other / Tit	tle		Che	cklist Refe	rence		
Related Rules, SOPs, Standards, or Other	Permane	nt Order		T-16	-07											
	Main Track	Yard	Stat	tion OCC		F	RTA acility	FTA Office			At-grade	Tu	unnel	Ele	evated	N/A
Inspection Location	X Track								Track Type		х					
Line(s)	K-Line	Track Numb	er	1		Chain Marker and/or Station(s) K1 CM653+00				rom		K1 CI	M777+	To 00		
	Head C	ar Number		Num	ber of Ca	ars										
Vehicles		N/A			N/A		Equip	ment	N/A							
		wing trains w	ere ob	oserve	ed to be	in com	pliance	with Perman	ent Order T-		Number o	of Defec	ts			1
	16-07:				Lord Contractor					1	Recommended Fine					No
	Time 1106				Lead Car Number 4039					Remedial Action R			Require	d?		Yes
	1110					6143										
	1145					2034				1						
	1203					3054	ļ									
	1220					3080)									
Description	1225					3029)									
	The follo	wing train wa	as not	in cor	npliance	with P	Permane	ent Order T-1	6-07:		D					Mark
	Time	0			d Car Nu			Comment		1	Recomme	naea k	einspec	tion?		Yes
	1124			310	7			Operator c	ame by in	1						
									0 mph. She							
									OCC that she							
				thought the speed limit was 20 mph. Train				it								
								Number wa								
Remedial Action	WMATA	should ensur	e that	the T	rain Ope	erator o	of Train	#904 is prop	erly counseled	on	Permanent	Order	T-16-07			

Inspection Activity #	3 I	Inspection Subj	ject	Track -	- Post Su	irge #9 Inspe	ection		Activity Co	ode	TR	K	GEN	OBS
Job Briefing Employee Name/Title		nit #207 - RWIC nit 6101 - Escor				mpanied ector?	Yes	Out Brief Conducted	Yes	Time	100 133		Outside Shift	No
Related Reports					Relat	ted CAPS / F	indings							
	Ref			Rule or	SOP		Standard		Other / T	ïtle		Checl	klist Refe	rence
Related Rules, SOPs, Standards, or Other	TRST 10	000												
Standards) of Other	MSRPH													
Inspection Location	Main Track	Yard	Statio	on	осс	RTA Facility	FTA Office	Track Type	At-grad	e Tu	nnel	Elev	vated	N/A
	Х							Thack Type	x					
Line(s)	K-Line	Track	Chain Mar	From				То						
Line(0)	IN LINE	Numbe	er	1		and/or Sta	ation(s)	K1 CM653+00)		K1 CN	Л777+ С	00	
Vehicles	Head	Car Number N/A	1	Number N/		Equip	ment	N/A						
	A.r	-		11/	A					(2
	Areas of Concern: 1. At K1 CM673+80, the cross bond between track 1 & 2 is not connected									of Defect	-			3
		on the trac								ended Fir	-	12		No
	2.			,		0	0		Remedial Action Required?					Yes
Description	Genera • • •	 The nut has almost backed off. SAFE Unit #207 called MOC and requested a manual 35 mph speed restriction from K1 CM738+00 to K1 CM750+00. TRST Supervisor notified the ERT Team. ROCC was also contacted by SAFE Unite #207. They imposed the speed restriction and made the required radio announcements. At approximately K1 CM754+00, the cable trough mounted on the wall has a dislodged cover that needs to be re-secured. eneral Observations: Crossties have been replaced. Ballast has been replaced, regulated, and tamped. Numerous rail joints have been eliminated. Third Rail Cover Boards have been replaced. Third Rail expansion joint cables have been replaced and are now supported on fiberglass Kindorf on the field side of the third rail. 											No	
Remedial Action		o exceptions were taken with the work that has been completed.												
Remetulal Action	VVIVIAL	A must lix the t	mee di	ieds UI (Loncein		z.							

Photos:






Figure 1 - K1 CM673+80 - Cross Bond not connected



Figure 2 - K1 CM744+00 - Right Rail Joint Bar Bolt Loose





Figure 3 - K1 CM754+00 Cable Trough Cover Dislodged



Form FTA-IR-1

Agency/Department Information

Federal Transit Administration

Inspection Date	YYYY	MM	DD	Report Number	20161109-WMATA-AD-2						
inspection Date	2016	11	09	Report Number							
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	Traction Power	Sub- Depa	artment	Cable Inspection			
	Name			Email	Office Phone	e	Ν	Nobile Phone			
Rail Agency Department Contact Information		I									
Inspection Location	E-Line Fort To	otten to Colum	ibia Heights, Tra	ack 1							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-JSB-OBS	TP-CI-OBS	SAF-RAG-PI	SAF-RC-OBS		
Inspection Units	1	1	1	1		
Inspection Subunits	1	1	1	1		
Defects (Number)	1	2	1	2		
Recommended Finding	Yes	Yes	Yes	Yes		
Remedial Action Required ¹	Yes	Yes	Yes	Yes		
Recommended Reinspection	Yes	Yes	Yes	Yes		

Activity Summaries

-									I					T
Inspection Activity #	1	Inspection Su	bject	Job Saf	ety Brief	ing			Activity Co	ode	T	þ	JSB	OBS
Job Briefing Employee Name/Title	TRPM	1271			Accon Inspec	npanied ctor?	Yes	Out Brief Conducted	No	Time	100 143		Outside Shift	No
Related Reports	N/A				Relate	ed CAPS /	Findings	N/A						
	Ref			Rule or S	r SOP Standard			Other / T	Other / Title			klist Refer	ence	
Related Rules, SOPs, Standards, or Other	MSRP	Н												
Standards, or other	RWPN	Л												
	Maiı Trac	Yard	Sta	ition	осс	RTA Facility	FTA Office	T	At-grade	At-grade Tunnel		nnel Elev		N/A
Inspection Location	х							Track Type			х			
Line(s)	E	Trac	c	1		Chain Marker		From		То				
Line(s)	E	Num	ber	T		and/or St	ation(s)	E06			E04			
	Неа	d Car Number		Number	of Cars									
Vehicles		N/A		N//	Ą	Equip	ment	N/A						
		Unit 1271 pro		-	, ,	-			Number	of Defect	s			1
Description		inspection tea				•	• •		Recommended Finding					Yes
Description					VIC did not know the maximum authorized established protections assuming 59 miles per			Remedial Action Require			d?		Yes	
	hour;	however, the	MAS in	the work	area was 65 mph as documented in WMATA's			Recommended Reinspect		tion?		Yes		

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are

sufficient and effective.		Digitally signed by AMBUR I DALEY	
Inspector in Charge - Signature	AMBURI	DN: c=US, o=U.S. Government,	Date
		Ou=DOT Headquarters,	
		ou=FMCSAHQ, cn=AMBUR I DALEY	
Inspector in Charge – Name	Inspection Team	Date: 2016.12.09 15:29:48 -05'00'	
Ambur Daley	Chad Broski, Curtis Dougherty, N	1ike Vitale	
-			



	MSRPH (Rule 3.84), "The normal operating speed for Class 1 vehicles on the mainline is that specified by the regulated speed indication and shall not exceed 59 mph except on the Green Line between Georgia Avenue - Petworth and Greenbelt, and between Anacostia and Branch Avenue where the normal operating speed is 65 mph as set by Performance Level 1."	
	The RWIC instructed the watchman to remain in a place of safety and be able to see and signal a train from at least 1320 feet away from the mobile work gang. This distance does not establish adequate protection based on the "ample time" definition at either 59MPH or 65MPH as workers are required to be in a position of safety not less than 15 seconds before a train or rail equipment moving at the maximum authorized speed on that track, can pass the location of the Roadway Worker. The RWIC must account for the time it takes Roadway Workers to clear plus the distance the train travels in 15 seconds at its maximum authorized speed.	
	The RWIC informed the crew that he would ask for an intermediate watchman if the situation required. The watchman tested his air horn and whistle to confirm they were functioning properly. Finally, the RWIC confirmed all RWP cards were up to date and all members of the work gang had the required personal protective equipment (PPE).	
Remedial Action	WMATA must ensure that the correct maximum authorized speed throughout the wo appropriate protections can be put in place. Also, WMATA must ensure proper appli	 briefings so that

Inspection Activity #	2	Inspe	ction Subje	ect	Cabl	e Inspecti	on Observat	ion		Activity Co	de	TF	>	CI	OBS
Job Briefing Employee Name/Title	TRPM	1 1271					ompanied ector?	Yes	Out Brief Conducted	No	Time	100 143	-	Outside Shift	No
Related Reports	N/A					Rela	ted CAPS / F	indings	N/A						
	Ref				Rule	or SOP		Standard	1	Other / T	itle		Chec	dist Refer	ence
Related Rules, SOPs, Standards, or Other	MSRP	ΡΗ													
Standards, or Other	RWPN	N													
Inspection Location	Maii Trac		Yard	Stati	ion	OCC	RTA Facility	FTA Office	Track Turne	At-grade	e Tui	nnel	Elev	vated	N/A
Inspection Location	x								Track Type			х			
Line(s)	Е		Track		1		Chain Ma	rker		From				То	
Line(s)	E		Numbe	r	1 1		and/or Sta	ation(s)	E06			E04			
Vehicles	Hea	nd Car N N/A	Number	1		er of Cars	Equip	ment	N/A						
	FWSC) observ	ved a TRPN	/I cabl	le insp	pection cre	ew inspecting	g expansion	cables and	Number	of Defect	s			2
								ghts). Inspec		Recomm	ended Fir	nding?			Yes
						0 1		tion for verif off the tunne	l floor as well	Remedia	Action R	equire	d?		Yes
Description	inspec FWSC Defec	ctions. D noted cts: 1. E. w 2. E al	1 two defec 1 244+00-2 vere obstru 1 196+00-1 llowing for	ts rela 240+0 cting 190+7 stanc	ated c 00 – Th the an '0 – Dr ding w	during the nree (3) pio rea betwe rains were vater and r	track walk. eces of conti en the runni completely	ng rail and th clogged in th up. FWSO n	ed rail (CWR) ne safety walk.	Recomm	ended Re	inspect	ion?		Yes
			VMATA mu	st rer	nove	CWR rails	from E1 244	+00 to E1 24	0+00 to allow u						
Remedial Action			VMATA mu etween E0				hey are clea		J+70 to allow w	ater to drain	, and mus	st inspe	ct the r	emaining	drains



Job Briefing Employee Name/Title	TRPM 127	1				mpanied ector?	Yes	Out Brief Conducted	No	Time	100 143		Outside Shift	No
Related Reports	N/A				Relat	ted CAPS / F	indings	N/A						
	Ref			Rule or	SOP		Standard		Other / T	ïtle		Che	cklist Refe	rence
Related Rules, SOPs, Standards, or Other	MSRPH													
Standards, or other	RWPM													
In a section I continue	Main Track	Yard	Stat	ion	OCC	RTA Facility	FTA Office	Tue de Teure	At-grad	e Tu	nnel	Ele	evated	N/A
Inspection Location	х							Track Type			х			
Line(s)	E	Track		1		Chain Ma	rker		From				То	
Line(s)	E	Numbe	er	1		and/or Sta	ation(s)	E06			E04			
	Head Ca	r Number		Number	r of Cars			21/2						
Vehicles	N	/A		N,	/A	Equip	ment	N/A						
	FWSO revi	ewed WMA	TA's R	loadway	Access (Guide. One o	discrepancy v	vas noted.	Number	of Defect	s			1
	Defect:								Recomm	ended Fir	nding?			Yes
Description		-143+00 is n	oted	as "Clea	r View" i	n WMATA's	Roadway Ac	cess Guide,	Remedia	l Action R	equire	d?		Yes
		ements for a						es not describe stricted View"		ended Re				Yes
Remedial Action								e E04 platform a ed as "Curve: Re					ide if nece	ssary.

Inspection Activity #	4	Inspe	ection Sub	ject	Gene	eral Safe	ety Cor	ncerns			Activity Co	de	SA	١F	RC	OBS
Job Briefing Employee Name/Title	TRPM	1271					compa specto		Yes	Out Brief Conducted	No	Time	100 14		Outside Shift	No
Related Reports	N/A					Re	lated	CAPS / F	indings	N/A				1		
	Ref				Rule c	or SOP			Standard		Other / T	itle		Cheo	klist Refe	rence
Related Rules, SOPs, Standards, or Other	MSRPI	Н														
standards, or other	RWPN	1														
Inspection Location	Mair Tracl		Yard	Stat	ion	осс		RTA acility	FTA Office	Track Type	At-grad	e Tu	nnel	Ele	vated	N/A
inspection Location	x									Пасктуре			Х			
Line(s)	E		Track		1		Ch	ain Ma	rker		From				То	
Line(s)	L		Numb	er	1		an	d/or Sta	ation(s)	E06			E04			
Vehicles	Head	d Car I	Number	_	Numbe	er of Ca	irs	Equip	mont	N/A						
Venicles		N/A	Ą		1	N/A		Lquip	inent	N/A						
	Two o	ther s	afety conc	erns v	vere no	oted by	FWSO	inspect	ors.		Number	of Defect	s			2
	Defect	ts:									Recomm	ended Fir	nding?			Yes
			ot maintai	ning 1	0 miles	s per ho	our whi	ile passi	ng work crev	vs as required	Remedia	l Action R	equire	d?		Yes
Description	restric 1030 - 1115 - 1126 - 1226 - 1239 - A TRST contra	tion: - Train - Train - FWS - FWS - FWS	n with trail o with lead O could no O could no O could no o could no v that walk were walk	ing can I car 7: ot iden ot iden ot iden sed pas	r 7040 122 Itify cal Itify cal Itify cal st the r le by si	r numb r numb r numb nobile v ide. The	er (loca er (loca er (loca work g ere was	ated at E ated at E ated at E ang (two 5 no mer	E1 202+00) E1 154+00) E1 149+00) D TRST inspec	h the speed ctors and one gang assigned work gang.	Recomm	ended Re	inspec	tion?		Yes



	1. WMATA must continue to emphasize compliance with T-16-07 and should consider providing train operators with a length of time to maintain 10 miles per hour once the last roadway worker is passed to ensure that the entire consist has passed the work
Remedial Action	gang. 2. WMATA must continue to emphasize to TRST proper RWP set up when using Train Approach Warning.



Photos:



CWR Pieces encumbering access to Safety Walk from the ROW





Standing Water due to clogged drains E1 196+00





Curve starting at 161+00



Federal Transit Administration

Form FTA-IR-1

Agency/Department Information

• • •								
Inspection Date	YYYY	MM	DD	Report Number	20161101 \\/\	4ATA A	ר 1	
inspection Date	2016	11	11	Report Number	20161101-WMATA-AD-1			
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	RTRA	Sub- Dep	artment	TNG
Rail Agency Department	I	Name		Email	Office Phon	e	Ν	Nobile Phone
Contact Information								
Inspection Location	Carmen Turn 3500 Pennsy	er Facility Drive Landove	er, MD 20785					

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TNG					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

Inspection Activity #	1	Inspec	tion Subje	ect	Safety S	Stand Do	wn			Activity Co	ode	RTI	RA	TNG	OBS
Job Briefing Employee Name/Title	N/A					Accor Inspe	npanied ctor?	N/A	Out Brief Conducted	No	Time	080		Outside Shift	No
Related Reports						Relate	ed CAPS /	Findings			I				
	Ref				Rule or S	OP		Standard		Other / T	ïtle		Chec	klist Refei	ence
Related Rules, SOPs, Standards, or Other										Permane T-16-07 F					
	Maiı Trac		Yard	Stati	on	occ	RTA Facility	FTA Office	Track Type	At-grad	e Tu	nnel	Elev	vated	N/A
Inspection Location							х		Track Type						х
Line(s)	N/A	·	Track		N/A		Chain Ma	rker		From				То	
Line(s)	N/A		Numbe	r	N/A		and/or St	ation(s)	N/A			N/A			
Vehicles	Hea	d Car N	umber	1	Number	of Cars	- E avria		N1/A						
venicies		N/A			N//	A	Equip	oment	N/A						
								own class at t		Number	of Defect	s			0
								ed WMATA e to the stude	mployee who	Recomm	ended Fi	nding?			No
Description						0	•	the class.	no. me	Remedia	Action F	Require	d?		No
							nt was diso ty Alert SA	cussed with a #16-10b.	review of	Recomm	ended Re	einspec	tion?		No

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective

Inspector in Charge - Signature	MBUR I DALEY	DALEY	Date
Inspector in Charge – Name Ambur Daley	Inspection Team Chris DiFatta	Date: 2016.11.14 11.03.13 -05'00'	



	 The instructor covered the following items during the class: Hot spots and locations No clearance zones Requesting foul time Radio communications ICAO phonic alphabet Advance watchman lookout and Speed vs. Need Chart Good faith challenge Operator procedures with workers on the track Near miss reporting 	
Remedial Action	N/A	

Form FTA-IR-1

United States Department of Transportation Federal Transit Administration

Agency/Department Information

	YYYY	MM	DD		204 64442 144		
Inspection Date	2016	11	13	Report Number	20161113-WN	/IATA-AD-1	
Rail Agency Name	Washington Authority	Metropolitan /	Area Transit	Rail Agency Department	OPS SAFE	Sub- Department	ROQT
Deil Ageney Department		Name		Email	Office Phone	e	Mobile Phone
Rail Agency Department Contact Information							
Inspection Location	west Fails Cr	iurch Yard – So	&I Building Brea	κκυυΜ			
inspection outlinity							
Inspection Activity #	1		2	3	4	5	6
• •	1 OPS-TNO	G-OBS	2	3	4	5	6
Inspection Activity #	_	G-OBS	2	3	4	5	6
Inspection Activity # Activity Code	OPS-TN	G-OBS	2	3	4	5	6
Inspection Activity # Activity Code Inspection Units	OPS-TNO 1	G-OBS	2	3	4	5	6
Inspection Activity # Activity Code Inspection Units Inspection Subunits	OPS-TNO 1		2	3	4	5	6
Inspection Activity # Activity Code Inspection Units Inspection Subunits Defects (Number)	OPS-TN0 1 1 0	,	2	3	4	5	6

Activity Summaries

Inspection Activity #	1	nspection Sub	ject	Safety S	Stand Do	and Down Training Observation			Activity Code		OPS		TNG	OBS
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?		N/A	Out Brief Conducted	Yes	Time	120 150	-	Outside Shift	Yes	
Related Reports	N/A				Related CAPS / Findings N/A									
Ref				Rule or S	OP Standard			Other / Title		Checklist Reference			ence	
Related Rules, SOPs, Standards, or Other	RWPM	RWPM												
Standards, or other	MSRPH			T-16-07,	rev. 1									
Inspection Location	Main Track	Yard	Stat	ion (CC	RTA Facility	FTA Office	Track Type	At-grad	e Tu	Tunnel		ated	N/A
						х								Х
Line(s)	N/A	Track Number N/A			Chain Marker and/or Station(s)		From			То				
	Head Car Number			Number of Cars							1			
Vehicles		N/A		N/A	A Contraction	Equip	ment N/A							
	General Observations:								Number of Defects				0	
Description	 Instructor provided a safety contact related to leaves on the roadwa and roads that become very slippery when wet. 								Recommended Finding?					No
	 The instructor provided an overview of the near-miss incident that 								Remedial Action Required?				No	
	occurred October 20, 2016.The presentation was provided in Power Point as a handout. (See								Recommended Reinspection?					No

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

sufficient and effective.		Digitally signed by AMBUR I DALEY	
Inspector in Charge - Signature		DN: c=US, o=U.S. Government, ou=DOT	Date
	AMBURIDALEY	Headquarters, ou=FMCSAHQ, cn=AMBUR	
		IDALEY	
Inspector in Charge – Name	Inspection Team	Date: 2016.11.16 09:43:55 -05'00'	
inspector in charge – Name			
Ambur Daley	Robert Maniuszko		
,			



	 attached.) The presentation covered the roles and responsibilities of the RWIC, RWP Rules, Exclusive Track Occupancy (ETO), Foul Time (FT), Radio Rules, Repeat Backs, Close Call Reporting, and the process for Good Faith Challenges. The presentation also included a discussion of the revised temporary order T-16-07. The FWSO inspector was the only participant in this presentation. The opportunity for discussion was provided. The instructor was knowledgeable of the RWP rules and requirements. She provided answers to questions and facilitated discussion. 	
	Note: There were no exceptions taken to any part of the presentation.	
Remedial Action	N/A	

Note:

There are three (3) attachments to this report.

- 1. Power Point Presentation
- 2. Near Miss Safety Bulletin
- 3. Permanent Order T-16-07, rev. 1



Introduction 2
► Safety Contact
► Introductions
Emergency Information
► Rules/Expectations

Purpose

- ▶ To inform and educate Roadway Workers in Charge (RWIC) on identifying Hot Spots including No Clearance Zones and the use of Foul Time (FT) to establish Exclusive Track Occupancy (ETO) Roadway Protection
- To inform all rail workers that safety is the foundation of all decision making within the Roadway Worker Protection program.
- To ensure Roadway Workers understand all procedures and know how to challenge the level of protection
- ► To ensure Roadway Workers and Rail Operators report any near misses

Agenda

- ▶ Review of October 20th Incident
- ▶ Review of RWP Rules
- Review of Good Faith Challenge
- Review of Safety Alert SA #16-10b
- Review of Revised Permanent Order No. T-16-07, Rev 1
- Near Miss/Confidential Close Call Reporting

- On Thursday, October 20th at 12:30 pm, two FTA inspectors and two escorts were conducting a walking inspection south of National Airport
 - ► The work crew was on Track 2 operating under Train Approach Warning (TAW)
 - The crew was walking through an identified hot spot
 - The watchman was 100 feet ahead of the other crew members
- Once the crew entered the hotspot, the watchman no longer had ample time to warn the other workers of approaching trains
- A train approached the work area. The crew was able to reach a place of safety. The train was not able to stop until having travelled through the area the crew was walking in.

- Conditions at the site required additional protection
- ▶ The RWIC failed to establish adequate protection
- ► These conditions require the workers to be in a place of safety until they clear the curve or the RWIC must declare FT
- > The rail operator failed to report the Near Miss to Rail Operations Control Center (ROCC) as required

Roadway Worker Protection

Hot Spots are locations on the railroad where additional Roadway Worker Protection is required

- Curves, hills and tunnels with limited visibility
- Bridge locations with limited or no clearance
- Track locations with limited or no visibility due to obstructions
- Tunnels with limited and close clearance
- Track locations with heavy outside noise
- Track locations with little or no clearance
- All Portals





No Clearance Zones

Areas on the roadway where there is no safe distance between trains or rail equipment and workers

- Do not have a safety walk that can be accessed without crossing the third rail
- ▶ Has a safety walk that is still within the dynamic envelope of the train



Requesting Foul Time to Cross Hot Spots

- When there are Hot Spots that are a danger to Roadway Workers, the WMATA Escort shall request Foul Time protection from the ROCC to cross that area
- Once all Roadway Workers are clear of the Hot Spot, the escort shall contact the ROCC and turn in the Foul Time



Requesting Foul Time

- ▶ Foul Time Protection Procedure is established by:
- Notifying ROCC of the need to STOP all rail traffic in a specific area; and
- Notifying ROCC for the reasons for stopping all rail traffic in a specific area; and
- 3. Receiving confirmation from ROCC that all rail traffic within the requested work zone has been <u>STOPPED</u>.



Radio Communications

- ▶ Using the radio is the standard for communication at WMATA
- Radio communication supports safe and efficient rail operation
- Not using a standardized and formal protocol for radio communications and broadcasting can have serious impacts on rail operations
- Using a standardized protocol will ensure clarity and consistency across user groups

Radio Communications Transmission

Each radio user is responsible for use of assigned radios and compliance with: $\label{eq:compliance}$

- Federal Communications Commission (FCC) Rules and Regulations
- WMATA Rules, Procedures, and General Notices
- Metrorail Safety Rules and Procedures Handbook (MSRPH) General Rules 1.69 thru 1.88 – provide requirements for when and how radio communication should be used
- MSRPH General Rule 1.8 requirement to immediately obtain additional information if a radio transmission is not understood

Radio Communications Protocol

- Required identification (MSRPH 1.78) all personnel must begin radio transmissions with:
 - ▶ Identifier: Train/Unit/Call Number or Name/Title
 - Location: Line, Track Number, Station, and/or Chain Marker

Radio Communications Repetition

Repetition – Ensuring clear communication

- Employee receiving a transmission <u>shall always repeat it</u> <u>back</u> to the person transmitting (MSRPH 1.79)
- If the repeat back is incorrect, the original sender needs to restate the message until an accurate repeat back is received
- Neither party should take any action until they are positive that all radio transmissions or receptions are <u>heard, fully</u> <u>understood, and acknowledged</u>

Radio Communications Repetition

- If a repeat back is not received correctly, attempt to spell the words or annunciate the letters using the International Civil Aviation Organization (ICAO) Phonetic Alphabet to assist with clarification
- Examples:
- ▶ K99 Kilo ninety-nine
- Drainage Pumping Station (DPS)- Delta-Papa-Sierra

Requesting Foul Time Protection



 Central, this is Unit (Track) 6061(six-zero-sixty-one) on the platform at Rhode Island Avenue, over

Requesting Foul Time Protection



Unit 6061 at Rhode Island Avenue, Central, go ahead with your message, over.

Requesting Foul Time Protection



Central, Unit 6061 requesting foul time to remove an object from the Roadway at Chain Marker Bravo One, 180+00 (one-eighty plus zero zero), over.





►Unit 6061 at Rhode Island Avenue, Central acknowledges your request for foul time at CM Bravo One, 180+00 to remove object from the roadway.

Is that affirmative unit 6061, over?





Unit 6061, all trains are stopped in your area. You are granted foul time between Rhode Island Avenue and Brookland stations CM Bravo One, 180+00

Contact central when you are back on the platform and clear of the Roadway. Your on track time is 1300hrs (thirteen hundred hours), over

Requesting Foul Time Protection



Central , Unit 6061, copy that I'm granted foul time between Rhode Island Ave and Brookland stations CM Bravo One, 180+00 ►


I will notify central when I am back on the platform and clear of the Roadway, my on track time is 1300hrs, over




▶ Unit 6061 this is central that's affirmative, out

Central, this is Unit 6061 on the platform at Rhode Island Ave,







7




Advance Watchman/L	ookou		30
 Watchman/Lookouts should be placed in locations which maximize the 	Speed (MPH)	Feet per second	Feet per 15 seconds
in locations which maximize the	10	14.7	221
amount of time workers have to get to	15	22.0	330
a place of safety before the approach	20	29.3	440
of trains or rail vehicles arrive at the	25	36.7	551
	30	44.0	660
work location	35	51.3	770
▶ If curves, a hill, noise or other	40	58.7	881
	45	66.0	990
interference obstructs the ability to	50	73.3	1,100
detect trains, use as many	55	80.7	1,211
Watchman/Lookouts as necessary to	60	88.0	1,320
ensure proper protection	65	95.3	1,430
	70	102.7	1,541

Advance Watchman/Lookouts

Advance Watchman/Lookout

- A qualified Watchman/Lookout who is in addition to the Work zone Watchman/Lookout
- Watchman/Lookouts shall ALWAYS be within sight and audible warning of the next or preceding Watchman/Lookout
- The sole duty of the Advance Watchman Lookout is to warn the work zone Watchman/Lookout of the approach of trains or rail equipment





Good Faith Challenge

Any Roadway Worker who determines that the level of protection is insufficient for the work area must make a Good Faith Challenge

- Employees are able present a Good Faith Challenge any time during the work period, and not just after the pre-job Roadway Job Safety Briefing
- They must immediately notify the RWIC of the on-track protection concern
- ▶ The RWIC shall try to resolve the on-track protection issue to the satisfaction of all

Good Faith Challenge

- The Roadway Worker who made the challenge has the right to remain clear of the Roadway until the issue has been resolved
- Any other Roadway Workers who are sympathetic to the challenge may remain clear
- If the issue cannot be resolved, the RWIC will request the next highest level of authority to respond

Good Faith Challenge

- The Responding Authority shall interview the concerned roadway worker and determine if :
 - The worker's statement of the Roadway safety protection or practice at the work location is accurate
 - \blacktriangleright The Roadway safety protection or practice at the work location complies with the RWPM
- ► The responding authority will document the Good Faith Challenge by completing form GFC-10
- The worker has the right to request SAFE to respond if they are not satisfied

Good Faith Challenge

Can I do a Good Faith Challenge for all safety concerns?

► All Roadway Workers are encouraged to bring safety concerns to supervision's attention, through the Gang Leader, RWIC or escort. Supervision must work to resolve safety concerns and escalate issues to management when they are unable to do so.

Revision to Permanent Order

Revised Permanent Order T-16-07, Rev.1 which requires equipment to operate at 10 mph or less when roadway workers are present on the same track

In work zones, Class II vehicles must not exceed 5 mph on the same track where workers are present

Operator Procedures

Operator Responsibilities

- Maintain a constant lookout
- > When persons are observed on the roadway
 - Sound the mainline horn with 2 long sounds
 - Immediately reduce the vehicle speed to 10 mph
- ▶ If personnel do not immediately clear and acknowledge, stop the
- train at least one car length away from the watchman's position Contact ROCC if acknowledgement is not received and await instructions before moving the train

Once the operator receives a proceed signal Verify that equipment and personnel are clear Acknowledge with two short mainline horn blasts Stop and switch to Mode 2, Level 1 if not in manual mode > Do not sound horn after making acknowledgement while travelling by the work gang Continue at 10 mph until clear of all personnel

- ▶ 10 mph must be maintained until the entire train has cleared the workers

Operator Procedures

Operator Procedures Workers on Opposite Trac

Operator Responsibilities through established work zones on the opposite track

- Maintain a constant lookout
- ▶ When persons are observed on the roadway
 - Sound the mainline horn with 2 long sounds
 - ▶ Immediately reduce the vehicle speed to 35 mph
- Proceed at 35 mph or lower or as directed by the RWIC or ROCC until the rail vehicle has passed the workers
- Be prepared to stop if conditions warrant

Operator Procedures Center Safety Walk

Locations where the place of safety is located between two parallel tracks

- When Roadway Workers are observed
 - Immediately reduce the vehicle speed to 10mph
 Maintain 10mph until the entire rail vehicle is past the workers
- Be prepared to stop within half the range of vision when observing Roadway Workers in the area
- ► The RWIC will avoid having two trains passing the work gang at the same time
- RWIC will ensure safety by stopping vehicle movement on the same track to allow a vehicle on the opposite track to pass first.

Center Safety Walks

- Dupont (A03) to Woodley Park (A04)
- National Airport Aerial Structure (C10 to CM 408+00)
- L Line Bridge (F03 to C07)
- Grosvenor Aerial Structure
- J Line Aerial Structures
 - Cameron Run
 - Eisenhower Avenue
 - Clermont Avenue
 - CSX Railroad

Operator Procedures Class II in Work Zones

Roadway Maintenance Machines (Class II) in established work zones

- ▶ Shall not be operated above 5 mph
- ► Operator shall be prepared to stop within ½ the range of visibility
- Operator shall be on the lookout for Roadway Workers, obstructions, broken rail and misaligned switches

Near Miss Reporting

- A $\ensuremath{\text{Near}}$ Miss is an unplanned event that did not result in injury or damage but had the potential to do so
- Near miss reporting is vital to preventing future fatal or catastrophic incidents
- Allows WMATA to identify and correct weaknesses in the system that led to the near miss
- Investigation results provide an opportunity to improve safety systems, training, communications and other hazard controls

Near Miss Reporting

MSRPH Rule 1.32

Employees involved in, witnessing, or informed of an accident or incident, **to include near misses**, on the Metrorall system shall inform their supervisor, Transit Police, ROCC and/or other appropriate authority as soon as possible, and shall file a written report

MSRPH Rule 4.1

Employees shall immediately report hazardous and/or unsafe conditions to their supervisor, including all near misses

Vear Miss Reporting

MSRPH Rule 3.87 as revised by T-16-07, Rev. 1

Rail vehicle operators shall maintain a constant lookout in the direction in which their vehicles are moving.

a. Rail Vehicle Operators shall report all near misses to ROCC.



Confidential Close Call Reporting

The Confidential Close Call System give employees a means to report near misses WMATA would not otherwise know about while maintaining anonymity and receiving protection from discipline

Information from your close call report makes the work environment safer and healthier for you and your co-workers. From your close call report, WMATA can identify and correct factors that contribute to accidents and/or injuries

Close Call Reporting

The Bureau of Transportation Statistics (BTS) administers a voluntary, confidential and non-punitive close call reporting system

- ▶ Supported by WMATA, ATU 689 and IBT 922
- Purpose is to improve transit safety through the report of incidents that WMATA would not otherwise know about
- Determines the root cause and develops preventative safety actions to prevent future occurrences

Close Call Re	porting 51
Report a Close Call by: Start the initial report within 16 Finish the report online within 2 	
10.0200000000	455

Summary 52 Remember All Roadway Workers must have the appropriate level of protection in place RWICs are responsible for the safety of workers and must adjust the level of protection according to the conditions Good Faith Challenges, Confidential Close Call and Near Miss reporting enhance the safety culture of WMATA





SA #16-10b

Washington Metropolitan Area Transit Authority Department of Safety and Environmental Management

Safety ALERT

October 25, 2016

Near Miss Roadway Worker Collision: Hot Spots Require Additional Protection

The Roadway Worker in Charge (RWIC) establishes the required level of protection for a work crew; however, all roadway personnel must perform Individual Train Detection (ITD) at all times to ensure their safety. Therefore, all personnel must follow cardinal rule RWPCR2:

• Employees shall expect, and be vigilant of, train or equipment movement in all directions at all times.

On Thursday, October 20, 2016, at approximately 1230 hours, a four-person inspection crew, operating under Train Approach Warning (TAW), and consisting of two Track and Structures escorts and two FTA inspectors reported a near miss incident on track #2 at chain marker C2 406+00. The inspection crew reported a train passed them in excess of the 10 mph speed restriction and did not signal using their mainline horn as required by Permanent Order T-16-07. The inspection crew was in the roadway at the time, but was able to reach a place of safety prior to the train reaching their location. The train stopped with the trailing car adjacent to the inspection crew. This area is identified as a Hot Spot in the Roadway Access Guide.

Preliminary information shows that one of the escorts was acting as a watchman and was located approximately 100 feet in advance of the roadway workers. The other escort was acting as the RWIC. A review of the incident and the Roadway Worker Protection Manual (RWPM) indicates that the inspection crew was not acting in compliance with the required level of protection for working in a HotSpot.

When working under TAW, a mobile work gang, defined as "a moving group of two or more workers engaged in a common task," is required to have designated Watchman/Lookout(s). The sole duty of the Watchman/Lookout is to provide ample warning for workers to clear to a place of safety. Ample Time requires workers to be in a place of safety no less than 15 seconds prior to the arrival of a train or rail equipment. In this instance, the inspection crew was in compliance with the Watchman/Lookout requirement prior to reaching the defined Hot Spot; however, when inspecting, performing maintenance, or walking in the roadway through a Hot Spot or any area that restricts the ability to see approaching trains, additional protection such as Foul Time, must be established.

In this instance, the work crew should have requested Foul Time to perform the inspection and/or established Exclusive Track Occupancy (ETO).

Foul Time: As defined in the Metrorail Safety Rules and Procedures Handbook (MSRPH), SOP #28 and RWPM page 43, **Foul Time is appropriate for short time periods in specific segments of track, such as blind spots and no clearance zones.** Establishing Foul Time requires three elements:

- 1. Notify ROCC of the need to STOP all rail traffic in a specific area
- 2. Provide a reason for stopping rail traffic (e.g., To measure gauge in a blind spot)
- 3. Wait in a place of safety until ROCC confirms that all rail traffic within the requested area has been stopped.

ETO: (*RWPM Page 22, Rule 1.76*) The RWIC shall invoke Exclusive Train Occupancy (ETO) when there are **blind spots or visual impediments** or No Clearance Zones and shall request ROCC to hold all vehicles at the preceding station using Foul Time (FT) until ETO Protection can be established.

• Note: In this case, additional Advanced Watchman/Lookouts would have been required to establish ETO based on the blind spot created by the curve and active movement on the adjacenttrack.

Good Faith Challenge: Roadway workers are encouraged to raise Good Faith Challenges any time there are unclear and/or unresolved on-track protection issues. Employees are empowered to make such claims and must remain clear of the roadway until the identified issue is resolved. Per the RWPM, "When a roadway worker determines that the roadway protection is insufficient in their work area, **they MUST immediately notify the RWIC**. The worker and the RWIC shall try to resolve On-Track protection issues."

In the event that the worker and RWIC cannot resolve the issue, the RWIC shall immediately request the next highest level of authority to respond to the scene. The request must be made from a place of safety. The responding authority will record the challenge on the GFC-10 form and attempt to resolve the issue. If the worker's concern remains unresolved after being shown that the work area is compliant with the RWPM and MSRPH, this must be noted on the form and forwarded to SAFE for response to the worker within 10 working days. Copies of all completed GFC-10 forms must be delivered to SAFE, the General Superintendent or Director of the division, the superintendent, employee file, Local 689, and Training.

Near Miss Reporting: In the event that a near miss incident occurs, it must be reported as per MSRPH cardinal rule 1.32:

• Employees involved in, witnessing or informed of an accident or incident, <u>to include near misses</u>, on the Metrorail system shall inform their supervisor, Transit Police, ROCC, and/or other appropriate authority as soon as possible, and shall file a written report.

Washington Metropolitan Area Transit Authority Department of Safety and Environmental Management


Advance Watchman/Lookouts

Speed vs. Need Watchman/Lookouts & Needed Work Limits

Speed (MPH)	Feet per second	Feet per 15 seconds
10	14.7	221
15	22.0	330
20	29.3	440
25	36.7	551
30	44.0	660
35	51.3	770
40	58.7	881
45	66.0	990
50	73.3	1,100
55	80.7	1,211
60	88.0	1,320
65	95.3	1,430
70	102.7	1,541

Watchman/Lookouts should be placed in locations which maximize the amount of time workers have to get to a place of safety before the approach of trains or rail vehicles arrive at the work location.

If curves, hill, noise or other interference obstruct the ability to detect trains, use as many Watchman/Lookouts as is necessary to ensure proper protection.



If additional information is required, contact your Regional Safety Officer or call the Safety Hotline

on



Washington Metropolitan Area Transit Authority

METRORAIL SAFETY RULES AND PROCEDURES HANDBOOK

PERMANENT ORDER

NO. T-16-07, Rev. 1: 10 MPH for Rail Vehicle Speed Restriction on Tracks where Workers are Present Date: Wednesday, October 26, 2016

TO: All Personnel

Permanent Order **T-16-07**, **Rev. 1** supersedes Permanent Order T-16-07. Permanent Order **T-16-07**, **Rev. 1** requires a **10 MPH** Speed Restriction on tracks where personnel are present on the same track. In work zones, Class II vehicles must not exceed **5 MPH**.

Permanent Order T-16-07, Rev. 1 modifies:

Operating Rule 3.87:

- 3.87 Class I and Class II Rail Vehicle Operators shall maintain a constant lookout in the direction in which their vehicles are moving. When Rail Vehicle Operators observe persons on the roadway, they shall:
 - a. Sound mainline horn (2 Long Sounds) to warn those people of the vehicle's approach and immediately reduce the train's speed to 10 MPH. When personnel are located on the same track as the operating rail vehicle, and they do not physically clear the roadway to a place of safety and appropriately acknowledge the horn signal; the Rail Vehicle Operator shall bring the vehicle to an immediate stop one car length away from the watchman's position. The Rail Vehicle Operator shall contact the Rail Operations Control Center (ROCC) and await their instructions before moving the vehicle. Rail Vehicle Operators shall report all near misses to ROCC.
 - b. Upon receiving the appropriate proceed signal from the watchman/lookout on the roadway, and verifying that all personnel and equipment are clear of the roadway, the Rail Vehicle Operator shall:
 - acknowledge the proceed signal with two short mainline horn blasts

(individuals on the roadway do not have to continually proceed trains after the Rail Vehicle Operator's acknowledgement);

- stop and switch to Mode 2, Level 1 if not already in manual mode;
- · discontinue sounding train horn after acknowledgement, and;
- continue at **10 MPH** until the entire train is past personnel.

Notice: Rail Vehicles Operating on Opposite Track of established work zones: Clearing of the track shall not apply to roadway workers with designated watchman/lookouts working on the opposite track unless directed by the RWIC or ROCC. If applicable, the Roadway Workers shall acknowledge the approaching train by facing the train and giving/displaying the proceed signal. The Rail Vehicle Operator shall acknowledge with two <u>short</u> horn blasts and proceed at no more than 35 MPH or at a lower regulated speed or as directed by the RWIC or ROCC <u>and be prepared to stop if</u> <u>conditions warrant.</u>



Important: Class II Rail Vehicle Operators are reminded of the following RWP Cardinal Rule and MSRPH Operating Rule 3.83 which state in part:

RWPCR 7 – Rail Roadway Maintenance Machines (RMM) shall not operate at speeds more than **5 MPH** within any working limits and shall be prepared to stop within ½ the range of visibility, be on the lookout for Roadway Workers, obstructions, broken rail and misaligned switches.

MSRPH OR 3.83 - The maximum authorized speed of Class II vehicles is that which is specified by the equipment manufacturer or as specified by ROCC, and in all cases shall not exceed 30 MPH.



Notice: The following areas have a place of safety located between the centers of two (2) parallel tracks. Rail Vehicle Operators must reduce the speed of their train to **10 MPH** until the entire train is past the workers and be prepared to stop within half their range of vision when observing Roadway Workers in this area. RWIC will ensure their work gang's safety by stopping train movement on the same track the rail vehicle is operating on if train moving on the opposite track is passing at the same time:

- Dupont to Woodley Park A03 A04
- National Airport Aerial Structure C10 to chain marker 408+00
- J Line Aerial Structures
 - Cameron Run
 - Eisenhower Ave
 - Clermont Ave

- CSX Railroad
- L Line Bridge F03 to C07
- Grosvenor Aerial Structure



Important: Hot spots are locations on the railroad where additional Roadway Worker Protection is required!

These physical locations include a variety of conditions, including:


- · Curves, hills and tunnels with limited visibility
- Tunnels with limited and close clearance
- Track locations with heavy outside noise
- Track locations with limited or no clearance
- Bridge locations with limited or no clearance
- Track locations with limited or no visibility due to obstructions
- All Portals

Operating Rule 3.164:

- 3.164 When flagging protection is observed on the roadway or by communication from ROCC, the Rail Vehicle Operator shall:
 - Reduce speed to not more than 10 MPH upon observing employees and be prepared to stop one car length away from the roadway flag person or watchman/lookout signal;
 - b. Change to low beam headlights; and
 - c. Operate at no more than **10 MPH** until the entire consist is clear of personnel on the roadway unless directed otherwise by the RWIC or ROCC.

PERMANENT ORDER T-16-07, Rev. 1

val of Pormanent Order T-16-07, Rev. 1



Director, ROCC Chair, Rail Rule Book Committee



Assistant General Manager RAIL

				1	1	
61		/	10.00	1	- Contraction of the second	
Cóno	cur:	/	8.3	/		
			1			

Managing Director Department of Rail Transportation

Approved:

Chief Safety Officer Department of Safety and Environmental Management

Attachment: Permanent Order T-16-07



Washington Metropolitan Area Transit Authority

METRORAIL SAFETY RULES AND PROCEDURES HANDBOOK

PERMANENT ORDER

NO, T-18-07 Introduction of 10 MPH Speed Restriction on Tracks where Workers are Present Date: Friday, June 24, 2016

TO: All Personnel

Permanent Order T-16-07 introduces a 0 MPH Speed Restriction on tracks where personnel are present.

Additions to rules and procedures are shown in bold and underline text; deletions are struck-through.

MSRPH Operating Rule 3.87

- 3.87 Rail vehicle operator and maintain a constant product in the direction in which their vehicle oper moving. When rail or endors observe persons on the roadway, they shall.
 - a. Solud resniline horn (2 Line Sounds) to warn those people of the vehicle's approach. Upersound do not physically clear the roadway and appropriate acknowledgement of the horn signal is not received, the vehicle shall be (not horn an immediate stop and the train operator shall contact the tail Operators Control Center (ROCC) and await their instructions berge rowing the train. Train Operators shall report all near misses to ROCC.



Groce: Opposite Track Trains: Clearing of the track True snaw a ply to gang(s) with designated watchman/lookouts working on the opposite track. The watchman/lookout Roadway workers shall acknowledge the approaching train by facing the train and giving/ displaying the proper proceed/clear signal. The Train Operator shall acknowledge with two <u>short</u> horn blasts <u>and be prepared to stop if</u> <u>conditions warrant it</u>. The gang shall not have to clear the tracks.

PERMANENT ORDER T-16-07

Page 1 of 3

- Upon receiving the appropriate proceed/clear signal from the watchman/lookout on the roadway, and verifying that all personnel and equipment are clear of the roadway, the Train Operator shall
- acknowledge the proceed/clear signal with 2 short mainline horn blasts (individuals on the roadway do not have to continually proceed
- trains after the Train Operator's acknowledgement); stop and switch to Mode 2, Level 1 if not already in manual mode;
- Stop and switch to wood 2, been if in not already in manual mode
 discontinue sounding train hom after acknowledgement, and;
- · continue at 35 10 mph until clear of personnel on either track.

MSRPH Operating Rule 3.164:

b.

3.164 When flagging protection is observed on the receivar or by communication from ROCC, the Train Operator shall:

- Reduce speed to not more than 35 mmph and be prepared to stop at roadway flag person or watchy ant/ockounsignal;
- b. Change to low beam headlight.
- Operate at no more than 16 10 mph unless directed otherwise by the RWIC or ROCC.

MSRPH SOP #28 PROTECTION FOR ROLDWAY WORKERS AND ESTABLISHMENT OF HIRD BAIL POWER OUTAGES IND WORK AREAS ON THE ROADWAY:

28.5.12.1.1 Collidion with ROCC, the application of a shunt strap on the work track accordance with the estillion point affic direction. The shunt strap(s) shall be upplied at a track acad in that will assure trains enter and travel a significant portion of ne work area at a speed not to exceed 10 mph. At less one train on each pack shall be allowed to operate through the affected area to point we that the desired speed has been achieved before work begins. The shunt strap must be verified by ROCC prior to the start of any waveled work and remain in place until the work is complete and all crew men them have cleared to the safety walk or other known clearance area. The shuft strap shall not be placed or removed in front of a train than the before the affected area.

PERMANENT ORDER T-16-07

Page 2 of 3

PERMANENT ORDER T-16-07, Rev. 1

Form FTA-IR-1

United States Department of Transportation Federal Transit Administration

Agency	/Department	Information
-ASCIICY/	Department	mormation

Inspection Date	YYYY	MM	DD	Papart Number							
inspection Date	2016	11	14	Report Number	eport Number 20161114-WMATA-AD-1						
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	ROCC	Sub- Dep	N/A				
Rail Agency Department	Name			Email	Office Phone M			Nobile Phone			
Contact Information											
Inspection Location	Carmen Turner Facility										
	3500 Pennsy	3500 Pennsy Drive, Hyattsville, MD 20785									

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	ROCC-RC-OBS					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

Inspection Activity #	1	Inspec	tion Subje	ect	Rules Compliance & Safety Management Inspection (SMI) Required Actions Observation of Rail Traffic Controllers (RTC)							ode	ROC	c	RC	OBS
Job Briefing Employee Name/Title	N/A	N/A				Accompanied Inspector?			N/A	Out Brief Conducted	Yes	Time	1330 173		Outside Shift	No
Related Reports	Safety Management Inspection (SMI), Final Report, June 17, 2015									ons: R-1-2-a, Finding R-6 (R-1-6-a & R-1-6-b), R-1-7-b, R- , and Finding R-14					R-1-7-b, R-	
	Related Rules, SOPs, Standards, or Other MetroRail Safety Rules and Procedures Handbook				Rule or S	OP			Standard		Other / T	itle		Checklist Reference		
					Section 1 (Radio Us Operatio Rules 1.6	sage an n):):			x		x				
	Perm	anent O	rder		NO. T-16-10											
Inspection Location	Ma Tra		Yard	Stati	ion C	DCC	RT Faci		Main Track	Yard	At-grade Tu		nnel	Elev	vated	N/A
inspection Location						х										х
Line(s)	N/A		Track	-	N/A				Chain Marker			From			То	
			Numbe	-			and/or Station(s) N/A			N/A						
Vehicles	Hea	ad Car N	umber		Number c	of Cars	rs Equipment N/A									
venicies		N/A			N/A			Equipr	nent							
Description											Number	of Defect	s			0

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge - Signature	AMBURIDALEY	Digitally signed by AMBUR I DALEY DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY Date: 2016.12.05 19:08:32 -05'00'	Date
Inspector in Charge – Name Ambur Daley	Inspection Team D Tamara Powell		



an manone m	aministration		
	An FWSO inspector met with the Assistant Superintendent of the Rail Operations Control Center (ROCC) to notify him that she would be conducting an observation	Recommended Finding? Remedial Action Required?	No
	of the Rail Traffic Controllers (RTC) at the OPS 2 console, which controls and over- sees operations on the Silver, Orange, and partial Blue lines. The following observations were conducted:	kemedial Action kequired?	NO
	 The FWSO inspector observed the radio transmissions and performance of two RTCs. RTC #1, the Button Controller, has been employed at WMATA for 10 years, with 1 year in the ROCC. RTC #2, the Radio Controller, was an external hire and has 3 years at WMATA in the ROCC. The FWSO inspector's observation and compliance check focused mainly on ROCC required actions and radio usage and operation (General Rules, #1.69 – 1.88 and Permanent Order T-16-10). The observation and compliance check was based on several findings from the SMI report, as well as rules from the MetroRail Safety Rules and Procedures Handbook. 		
	Observations related to SMI report findings:		
	 R-1-2-a: "WMATA must complete and maintain required annual recertifications for Rail Traffic Controllers." One of the two RTCs recently completed the ROCC's Bridge Training, the two-week recertification program for RTCs. 		
	 R-1-6-a: "WMATA must establish and enforce a proper protocol for language and terminology that is used over the radio – to include 100 percent word-for-word read-back for safety-related instructions and unusual train movements." Starting at 1004 hours, Track and Power personnel began calling the RTC over the radio to request permission to access the Right- of-Way (ROW) to perform maintenance activities. The RTCs ensured all requests were received properly through 		
	read-backs. Power and Track personnel each performed word-for- word confirmation of walking rights on the ROW. The RTC closed out each transmission by acknowledging, "That is a good copy," over the radio.	Recommended Reinspection?	No
	 <i>R</i>-1-6-b: "As part of <i>R</i>-1-6-a, WMATA must establish an approach for communicating and managing all speed restrictions that require two-way communication between the ROCC and train operator and take full advantage of available electronic AIM system features." Per policy, RTCs must conduct hourly radio broadcasts that include a full read out of the roadway worker protections (RWP), time confirmation, rule of the day, cardinal rule 1.79, and all operational anomalies in place. RTCs must also broadcast RWP announcements every twenty minutes. The required hourly broadcasts were observed on or near each 		
	 hour, and the RWP announcements were observed at 20 – 30 minute intervals. RTCs also maintained a written log of all personnel on the ROW and recorded all call on/call off times. Additionally, the ROCC Director and supervisory staff have tools in place to monitor compliance with this directive. When there is a lapse in controller compliance, RTCs are required to maintain and submit written logs that document all announcements broadcasted during their shift. All reports that are reviewed for compliance must contain the types of broadcasts made during each shift, such as ROW access and level of protection, and the times must be recorded. This logging process remains in place until satisfactory compliance of all RTCs is achieved. 		
	 R-1-7-b: "WMATA must enhance RTC reference materials to direct internal operations at the ROCC, includingand internal ROCC administrative policies and procedures." Per WMATA rules and policy (see Permanent Order T-16-10 and Operations Radio Communication Training), the ROCC has implemented a scripted reminder regarding proper radio usage that must be broadcast hourly to all RTCs. The reminder includes 		





Inspection Form

United States Department of Transportation Federal Transit Administration

Form FTA-IR-1

Agency/Department Information

Insurantian Data	YYYY	MM	DD	Depert Number	20161116-WMATA-AD-1					
Inspection Date	2016	11	16	Report Number	20101110-0010		J-1			
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	TRST OPS POWR SAFE POWR SAFE					
Rail Agency Department Contact Information		Name		Email	Office Phone	3	N	Nobile Phone		
Inspection Location	J-Line – Van I	Dorn to France	nia-Springfield	– Track 1						

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	SAFE-RWP-OBS	TRK-GEN-OBS	OPS-RC-OBS			
Inspection Units	1	1	1			
Inspection Subunits	2	2	13			
Defects (Number)	2	25	0			
Recommended Finding	No	No	No			
Remedial Action Required ¹	Yes	Yes	No			
Recommended Reinspection	No	Yes	No			

Activity Summaries:

Inspection Activity #	1	Inspec	tion Subj	ect	RWP – J	ob Safe	ty Briefing	and Field Im	olementation	Activity Co	de	SAI	FE	RWP	OBS
Job Briefing Employee Name/Title	SAFE #207 – RWIC SAFE #307 – Watchman/Lookout			Accon Inspec	npanied ctor?	Yes	Out Brief Conducted	Yes	Time 100		-	Outside Shift	No		
Related Reports						Related CAPS / Findings									
	Ref Rule or S			OP		Standard		Other / T	ïtle		Che	cklist Refer	ence		
Related Rules, SOPs, Standards, or Other	MSRPH														
Standards, or other	RWP	VPM													
	Mai Trac	Yard Sta		Stat	ion (DCC	RTA Facility	FTA Office		At-grade	e Tu	nnel	El	evated	N/A
Inspection Location	х								Track Type	х					
Line(a)	J-Line		Track		1		Chain Ma	rker		From			То		
Line(s)	J-LING		Numbe	er	1		and/or Station(s) J1 C		J1 CM694+00 J1 CM8			1885+	\$85+00		
	Hea	nd Car N	umber		Number o	umber of Cars									
Vehicles	N/A N/A			Equipment		N/A									

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are

sufficient and effective.		Digitally signed by AMBUR I DALEY	
Inspector in Charge - Signature	AMBURI	DN: c=US, o=U.S. Government,	Date
		ou=DOT Headquarters, ou=FMCSAHQ,	
		cn=AMBUR DALEY	
Inspector in Charge – Name		Date: 2016.11.18 14:16:26 -05'00'	
Ambur Daley	Robert Maniuszko		

	Concerns:	Number of Defects	2
	 A No Clearance Area exists between J1 CM762+00 to CM767+00. This area is not denoted in the Access Guide. There is an overhead bridge 	Recommended Finding?	No
	with a high support wall that blocks the view around a curve. The fence	Remedial Action Required?	Yes
Description	 is labeled as "No Clearance". The FWSO team requested and was granted Foul Time to traverse this area. During this inspection, particularly upon approach to the No Clearance Area and the bridge with the high support wall with a blocked view, it was apparent that the Advanced Watchman was put at risk in order to maintain his position several hundred feet ahead of the mobile work group. The Advanced Watchman was moving through these locations under Individual Train Detection (ITD) to protect the rest of the work group. This is a lesser protection than what is required in the Access Guide for employees in this location. 		
		Recommended Reinspection?	No
	 General Observations: At one point during the walk the FWSO team met up with ATC employees. These employees had an individual located in the Train Control Room with a radio. This individual was able to warn the workers of the approaching trains long before the train came into view. This methodology could prove to be useful to other groups as the RWP program matures. The Job Safety Briefing was comprehensive. The hot spots, hazards, clearance areas, communication, and Access Guide were used as part of the discussion. No exception was taken to the Job Safety briefing. 		
Remedial Action	WMATA must update its Access Guide to accurately reflect the physical characteristic	s of the track between J1 CM694+00	and CM885+00.

Inspection Activity #	2 Ins	pection Subj	ect	Surge #	8 Walkt	hroug	;h – Tra	ack 1		Activity Code TRK GEN					OBS
Job Briefing Employee Name/Title	SAFE #207 SAFE #307	7 – RWIC 7 – Watchma	n/Loo	kout		mpanio ector?	ied	Yes	Out Brief Conducted	Yes	Voc Timo			Outside Shift	No
Related Reports	20160910	-WMATA-RP	M-1	Related CAPS / Findings							I				
	Ref	Rule or SOP Standard						Other / T	ïtle		Check	list Refe	ence		
Related Rules, SOPs, Standards, or Other	TRST1000														
Standards, or Other	MSRPH														
Increation Location	Main Track	Yard	Stati	ion (осс	RT. Facil		FTA Office	Treak Ture	At-grade	e Tu	nnel	Elev	ated	N/A
Inspection Location	х								Track Type	x					
Line(s)	J-Line	Track		1		Chair	n Mar	ker		From To					
Line(s)	J-LINE	Numbe	er	1		and/	or Sta	tion(s)	J1 CM694+00	00 J1 CM885+00					
Vehicles	Head Ca	r Number	I	Number o	of Cars		Equipn	nont	N/A						
venicles	N	I/A		N/A	4		quipi	nent	N/A						
	Concerns:									Number	of Defect	s			25
	1.	Several coll cover board						nity of J1 CN	1731+00. The	Recomm	ended Fi	nding?			No
	2.				•			ent to J1 CM	826+20. The	Remedia	l Action I	Require	d?		Yes
Description	3. 4. 5. 6. 7.	A heater co repaired. Ti employees. The majoriti moved to t below. There are 1 the ground could pose Three locat dislodged.	ntrol p he box See p y of th he field 7 loca in poc a dang ions w tion, c	panel box is open 1 hoto belo ne third r d side of tions who or conditi ger to em vere foun	k labeled to weat ow. ail expa the thir ere the tion. The pployees d where	d HC-JC her an nsion o d rail. Heater boxes s, espe e the tl	03-52- nd poss cables One e r Cont s are cl ecially hird ra	xception, se rol Fuse Box learly marke in inclement ail anchor ar	ot been t by replaced and e photo res are lying on rd 750Vdc and t weather.	Recommended Reinspection? Ye					Yes



	General Observations:	
	Crossties have been replaced.	
	 Ballast has been added, tamped, and regulated as necessary. 	
	• All ETS Boxes have been repaired, and each box now has a working blue	
	light and clearly identified label.	
Remedial Action	WMATA must complete repairs on the 25 items noted in the concerns above.	

Inspection Activity #	3 li	nspection Sub	ject	Rule	Complian	ice – T-16-07	7, Revision 1		Activity C	ode	OP	S	RC	OBS
Job Briefing Employee Name/Title		07 – RWIC 07 – Watchm	an/Loc	Accompanied bkout Inspector?		Yes	Out Brief Conducted	Yes	Time	1000 140	-	Outside Shift	No	
Related Reports					Related CAPS / Findings									
	Ref Rule or SOP Stand				Standard	1	Other /	Title	klist Reference					
Related Rules, SOPs,	MSRPH				07, Rev. 1									
Standards, or Other														
	Main Track	Yard	Stat	ion	OCC	RTA Facility	FTA Office		At-grac	le Tu	nnel	Elev	ated	N/A
Inspection Location	х							Track Type	x					
1:	1.1.5.0.0	Track		1		Chain Ma	rker		From To					
Line(s)	J-Line	Numb	er	1		and/or St	ation(s)	J1 CM694+00	0 J1 CM885+00)		
	Head	Car Number		Numbe	er of Cars									
Vehicles		N/A		١	N/A	Equip	ment	N/A						
	The Foll	owing Trains	were o	bserve	d to be in	compliance	with Perma	nent Order T-	Number	of Defect	s			0
	16-07, F	16-07, Revision 1.							Recomm	nended Fii	nding?			No
		Lead	Car #				Time					40		
	3029					1019			Remedia	al Action F	cequirec	ar		No
	3002					1024								
	6057					1030								
	3171					1050								
	6111					1100								
Description	2058					1103								
beschption	3099					1105								
	5072					1109			Recomn	nended Re	inspect	tion?		No
	8004					1112								
	6144					1133								
	6082					1157								
	3029					1225								
	3166 1248													
	Note: N	Note: None of the trains passing on the active or adjacent track were found to be												
	non-cor	npliant with P	erman	ent Or	der T-16-0	07, Revision	1.							
Remedial Action	N/A													





Figure 1 - J1 CM723+90 - Heater Control Fuse Box



Figure 2 - J1 CM726+50 - 3rd Rail Anchor Arm Off



Figure 3 - J1 CM731+60 - 3rd Rail Anchor Arm Off



Figure 4 - J1 CM769+80 - Heater Control Fuse Box



Figure 5 - 3rd Rail Expansion Cables still track side



Figure 6 - J1 CM777+40 - Heater Control Fuse Box





Figure 7 - J1 CM781+50 - Heater Control Fuse Box



Figure 8 - J1 CM784+00 - Heater Control Fuse Box



Figure 9 - J1 CM789+60 - Heater Control Fuse Box



Figure 10 - J1 CM797+00 - Heater Control Fuse Box



Figure 11 - J1 CM812+00 - Heater Control Fuse Box



Figure 12 - J1 CM819+00 - Heater Control Fuse Box





Figure 13 - J1 CM824+80 - Heater Control Fuse Box



Figure 14 - J1 CM826+00 - 3rd Rail Anchors



Figure 15 - J1 CM826+20 - End Approach No Coverboard



Figure 16 - Pile of contact shoe adjacent to J1 CM826+20



Figure 17 - J1 CM827+00 - Heater Control Fuse Box



Figure 18 - J1 CM828+00 Left Rail - One C-Bond Detached





Figure 19 - J1 CM834+50 - Heater Control Fuse Box



Figure 20 - J1 CM842+70 - Heater Control Fuse Box



Figure 21 - Heater Control Box - HC-J03-52-3 - still not repaired



Figure 22 - J1 CM850+30 - Heater Control Fuse Box



Figure 23 - J1 CM858+00 - Heater Control Fuse Box



Figure 24 - J1 CM865+60 - Heater Control Fuse Box





Figure 25 - J2 CM865+60 - Heater Control Fuse Box

Form FTA-IR-1

Agency/Department Information

Federal Transit Administration

Inspection Date	YYYY	MM	DD	Report Number	20161117-WMATA-AD-1					
inspection Date	2016	11	17	Report Number	20101117-WWATA-AD-1		D-1			
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	TRST Sub- Department Product NCS			Production NCS		
	Name			Email	Office Phone	9	Mobile Phone			
Rail Agency Department										
Contact Information										
Inspection Location	Surge #10 – F	Surge #10 – Rhode Island Avenue (B04) to Brookland – CUA (B05)								
Inspection Summary										

Inspection Form

Þ y

Inspection Activity #	1	2	3	4	5	6
Activity Code	TRK-RWP-OBS	TRK-GEN-OBS	IT-GEN-OBS			
Inspection Units	1	1	1			
Inspection Subunits	1	1	1			
Defects (Number)	0	0	1			
Recommended Finding	No	No	No			
Remedial Action Required ¹	No	No	Yes			
Recommended Reinspection	No	No	No			

Activity Summaries

Inspection Activity #	1	Inspec	tion Subj	ect	RWP – J	ob Safe	ety Briefing	and Work Zo	ne Set-up	Activity Co	de	TR	K	RWP	OBS
Job Briefing Employee Name/Title	Unit #6216 provided the briefing			efing	Accompanied Inspector?		No	Out Brief Conducted	No	Time	080 113	-	Outside Shift	No	
Related Reports						Related CAPS / Findings									
	Ref Rule			Rule or S	ОР		Standard		Other / T	Other / Title			klist Refer	ence	
Related Rules, SOPs, Standards, or Other	RWPN	RWPM													
	MSRP	н													
	Maiı Trac		Yard	Stat	ion C	осс	RTA Facility	FTA Office	Treads Truce	At-grade	e Tui	nnel	Elevated		N/A
Inspection Location	х								Track Type	x		х		x	
			Turd				Ch - 1 - N 4 -			From			То		
Line(s)	B-Line	2	Track Numbe	er	1&2		Chain Mar and/or Sta		B1 CM133+00 B2 CM210+00				CM210+00 CM117+00		
Makida .	Неа	d Car N	umber		Number o	of Cars	.		D1 / A						
Vehicles		N/A			N/A		Equipment N/A								
Job Safety Briefing											Number of Defects				0
Description Unit #6216 provided the b				riefing.				Recommended Finding?				No			

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are , sufficient and effective

Inspector in Charge - Signature	MBURIDALE	Digitally signed by AMBUR I DALEY DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY Date: 2016.11.18 19:49:11 -05'00'	Date
Inspector in Charge – Name Ambur Daley	Inspection Team Chris DiFatta, Robert Maniuszko		

	• Mobile Command Center (MCC) is the RWIC for the area.	Remedial Action Required?	No
	 MCC is located at Brentwood Yard. MCC is using radio channel OPS #12. MCC direct phone number is The entire area is Inaccessible track. There is no train movement within the work zone. There are three red tags in place for the area: 2016303504A 2016303506A 2016303507A The work area is protected by wooden ties chained to the rails along with shunts and lanterns. Each work area is delineated by an end of work mat. There are several hot spots in the area. Roadway Maintenance Machines are moving in the area and may move in both directions. Closest hospitals are Providence and Washington hospitals. General Observations: There were multiple work zones set up within the work area. There were red strobes and end of work mats in each area. Warning Strobe and Alarm Devices (WSAD) were observed in the work area. Several were checked for calibration. All were found to be in calibration. 	Recommended Reinspection?	No
Remedial Action	N/A		

Inspection Activity #	2	Inspection Sub	ject	Track General Observations			Activity Code		TR	K	GEN	OBS		
Job Briefing Employee Name/Title	N/A			Accor Inspe	npanied ctor?	No	Out Brief Conducted	No	Time	0800 1130		Outside Shift	No	
Related Reports			Relat	1										
Related Rules, SOPs, Standards, or Other	Ref Rule			Rule or SOP Standard			Other / Title Chee			Check	ecklist Reference			
	TRST 1000													
	MSRPH													
Inspection Location	Main Track	Yard	Static	on C	DCC	RTA Facility	FTA Office	Treek Ture	At-grad	e Tui	nnel	Eleva	ated	N/A
	х							Track Type	x		х	×		
Line(s)	B-Line Track			1&2	Chain Mar		rker		From			То		
Line(s)	D-LITE	Number I & Z and/or Stati		ation(s)	B04	B05								
Vehicles	Head Car Number Number o													
	N/A N/A			Equipment N/A										
	 General Observations: Extensive repairs have been made in the station platform area. Crews were observed pouring new grout pads to the east of Rhode Island Station on Track 2. 							Number of Defects					0	
								Recommended Finding?					No	
								Remedial Action Required?					No	
Description	 New Grout pads have been poured throughout the Rhode Island Station area. New Fasteners and stud bolts are being installed. ETS boxes have been repaired or replaced at several locations. Rail joints are being eliminated. Third Rail expansion joint cables have been removed from the track side. They have been replaced on the field side of the third rail. Insulators are being replaced. Cover boards are being replaced. All defects that have not been repaired to date are spray painted orange. The B04 interlocking has been completely replaced. 						Recommended Reinspection?				No			



	• The ballast has been filled and shaped as necessary.	
	No Exceptions were taken to the observed work area.	
Remedial Action	N/A	

Inspection Activity #	3	Inspect	ection Subject ETS Box Observations A					Activity Co	de	Т	Г	GEN	OBS			
Job Briefing Employee Name/Title	N/A	N/A				Accompanied Inspector?		No	Out Brief Conducted	No	No Time		0 – 30	Outside Shift	No	
Related Reports						R	elated (CAPS / F	indings							
	Ref				Rule	or SOP			Standard		Other / T	itle		Che	cklist Refer	ence
Related Rules, SOPs, Standards, or Other																
Inspection Location	Mair Trac		Yard	Sta	tion	осс		RTA acility	FTA Office	Track Type	At-grade	e Tur	nnel	Ele	evated	N/A
	х			Track Type					х		х		х			
Line(s)	B-Line		Track		1.8	. 2	Ch	ain Mai	ker		From				То	
Line(3)	D-LINE		Numbe	r	10	(2	an	d/or Sta	ation(s)	B04			B05			
Vehicles	Hea	d Car Nu	umber		Numb	per of Ca	ars	Equip	mont	N/A						
venicles		N/A				N/A		Lquip	ilent	N/A						
	Conce										Number	of Defect	s			1
	1	L. At	B2 CM18	6+15	5 the E	TS box o	does no	t have a	label or inte	rnal map.	Recomm	ended Fir	nding?			No
	Gener	al Obsei	rvations:								Remedia	l Action R	equire	d?		Yes
Description		 Several ETS boxes have been repaired or replaced. Blue Lights were all in service. There were two new boxes at the portal area that are currently out of service. The boxes are tagged out of service. These installations appear to be a part of the surge activity. 							No							
Remedial Action	Action WMATA must label and add the interior map in the ETS box identified above.															

Photos:



Figure 1 - New Grout Pads at B04





Figure 2 - New Grout Pads being poured east of B04



Agency/Department Information

Federal Transit Administration

Increation Data	YYYY MM DD Beaut Number				20161117-WMATA-WP-1				
Inspection Date	2016	11	17	Report Number	20101117-0010	/IA I A-W	/P-1		
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	OPMS	Sub- Dep	artment		
		Name		Email	Office Phone	5	Ν	/lobile Phone	
Rail Agency Department Contact Information									
Inspection Location	Carmen Turner Facility, Landover, MD								
Inspection Summary									

Inspection Activity # 1 2 3 4 5 6 **Activity Code RWP-TNG-OBS Inspection Units** 1 **Inspection Subunits** 1 Defects (Number) 1 **Recommended Finding** Yes Remedial Action Required¹ Yes **Recommended Reinspection** No

Activity Summaries

Inspection Activity #	1	Insp	pection Subj	ject			own Traini er Collision	ng for the Nea	ar Miss	Activity Co	ode	RW	/P	TNG	OBS
Job Briefing Employee Name/Title	N/A			Accor Inspe	npanied ctor?	N/A	Out Brief Conducted	No	Time	130 140	-	Outside Shift	No		
Related Reports						Relate	ed CAPS /	Findings							
	Ref				Rule or S	OP		Standard		Other / T	ītle		Check	list Refer	ence
Related Rules, SOPs, Standards, or Other	WMA	ATA M	1SRPH		SOP #28										
Standards, or other	WMA	ATA R	WP Manual												
In a section of a section	Mai Trac		Yard	Stati	ion (DCC	RTA Facility	FTA Office	Tuesda Taures	At-grade Tu		nnel	Eleva	ated	N/A
Inspection Location							х		Track Type						х
line(a)	NI / A		Track		NI / A		Chain Ma	rker		From				То	
Line(s)	N/A		Numbe	er	N/A		and/or St	ation(s)	N/A			N/A			
	Hea	ad Ca	r Number		Number	of Cars									
Vehicles		Ν	/A		N/A	1	Equip	ment	N/A						
			•	bserved WMATA's Safety Stand Down Training on November en Turner Facility. The Safety Stand Down was for a "near					1						
Description						·				Recomm	ended Fir	nding?			Yes
	11155,	III W		way w	UINEL WA	ker was nearly struck by a train on October 20, 2016.				Remedial Action Required?			d?		Yes

Inspector in Charge - Signature WINSLOW L. POV	VELL	Digitally signed by WINSLOW L. POWELL DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FTAHQ, cn=WINSLOW L. POWELL Date: 2016.12.12 07:23:10-05'00'	Date
Inspector in Charge – Name	Inspection Team		
Winslow Powell	Chad Broski		



	The training was presented by an experienced instructor, and it consisted of a PowerPoint presentation, instructional handouts and an opportunity to ask questions. The instructor did a good job explaining the rules by providing real-world examples. This particular training class was one of many being offered to the approximately 6,000 WMATA employees required to attend. To accommodate the large number of employees and varying work schedules, the classes were running daily and hourly at multiple locations throughout the WMATA system for a couple of weeks. All employees were required to sign-in on a roster sheet to obtain credit for attending the class. Subjects that were discussed in training included the near miss Safety Alert (SA #16- 10b); Permanent Order No. T-16-07, Rev. 1. Radio protocols were also reviewed (<i>MSRPH</i> 1.8; 1.69-1.88). FWSO found that Permanent Order No. T-16-07, Rev. 1 utilizes rules from the <i>MSRPH</i> and can present unclear instructions pertaining to the duties of a Watchman/Lookout vs. Roadway Flag Person (RFP). For example, MSRPH Operating Rule 3.164 combines the terminology of 'flagging protection' with a 'watchman/Lookout signal.' It reads (in part), "when flagging protection is observed on the roadway or by communication from ROCC, the Rail Vehicle Operator shall: (a) reduce speed to not more than 10 MPH upon observing employees and be prepared to stop one car length away from the roadway flag person or watchman/Lookout signal .' The Watchman/Lookout sole duty, in accordance with the <i>WMATA RWP Manual</i> , is to warn roadway workers of approaching rail vehicle Operator in spredicated on obtaining the appropriate sight distance for the maximum allowable train speed. This rule can make it confusing to a Rail Vehicle Operator if they are expecting a signal from the WAtATA <i>RWP Manual</i> . The notice stated: "The following areas have a place of safety 10 coated between the centers of two (2) parallel tracks. Rail Vehicle Operators must reduce the speed of their train to 10 MPH untit the en	Recommended Reinspection?	No
Remedial Action	identified in the WMATA RWP Manual. N/A		
Reffection Action	רויי –		

Federal Transit Administration

, Senell Department mon									
Inspection Date	YYYY	MM	DD	Report Number	20161110 \//	10T0 01	1		
inspection date	2016	11	18	Report Number	Report Number 20161118-WMATA-AD-1				
Rail Agency Name	Washington Authority	Metropolitan A	rea Transit	Rail Agency Department	ROCC	Sub- Dep	artment	N/A	
Rail Agency Department		Name		Email	Office Phone	е	N	Nobile Phone	
Contact Information									
Inspection Location	Carmen Turn 3500 Pennsy	1	ille, MD 20785						

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	ROCC-RC-OBS					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

Inspection Activity #	1	Inspec	tion Subj	ect		equired		y Manageme oservation of	nt Inspection Rail Traffic	Activity Co	ode	ROC	C	RC	OBS
Job Briefing Employee Name/Title	N/A				mpanied ector?	N/A	Out Brief Conducted	Yes	Time	1000 160		Outside Shift	No		
Related Reports			gement In eport, Jur	•		Relat	ed CAPS /	Findings		Required Actions: (R-1-2-a); (R-1-6-a) & (R-1-6-b); (R-1-7-b); (R-1-8 (R-1-9-a); and Finding R-14				; (R-1-8-a);	
	Ref				Rule or S	SOP		Standard		Other / T	ïtle		Check	list Refer	ence
Related Rules, SOPs, Standards, or Other		rocedur	fety Rules es	Rules Section 1 (Radio Us Operation Rules 1.69			on): X				Х			х	
	Perm	anent O	rder		NO. T-16	5-10									
Increation Location	Ma Tra		Yard	Stat	ion	осс	RTA Facility	Main Track	Yard	At-grad	e Tu	nnel	Eleva	ated	N/A
Inspection Location						х									х
Line(a)	NI / A		Track		NI / A		Chain Ma	irker		From				То	
Line(s)	N/A		Numbe	er	N/A	A and/or Station(s) N/A					N/A				
	Hea	ad Car N	umber		Number	of Cars									
Vehicles		N/A			N/A	Ą	Equip	Equipment N/A							
Description	An F\	VSO insp	pector co	nduct	cted an observation of the Rail Traffic Controllers (RTC) at Number of Defects 0						0				

sufficient and effective.		Digitally signed by AMBUR I DALEY	
Inspector in Charge - Signature	AMBUR I DALEY	DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY Date: 2016.12.05 18:57:19 -05'00'	Date
Inspector in Charge – Name	Inspection Team		
Ambur Daley	Tamara Powell		



the Rail Operations Control Center (ROCC) at the OPS 1 console, Red Line.	Recommended Finding?	No
SafeTrack was in effect with 3 rd rail power de-energized from New York Avenue to Fort Totten. The following observations were conducted:	Remedial Action Required?	No
Fort rotten. The following observations were conducted.		
 The FWSO inspector observed the radio transmissions and performance of two RTCs. RTC #1, the Button Controller, has been employed at WMATA for 37 years, with 15 years in the ROCC. RTC #2, the Radio Controller, has been employed at WMATA for 14 years, with 3 months (qualified) as an RTC in the ROCC. The FWSO inspector's observation and compliance check focused mainly on ROCC required actions and radio usage and operation (General Rules, #1.69 – 1.88 and Permanent Order T-16-10). The observation and compliance check was based on several findings from the SMI report, as well as rules from the <i>MetroRail Safety Rules and Procedures Handbook</i>. 		
Observations related to SMI report findings:		
 <i>R-1-2-a: "WMATA must complete and maintain required annual recertifications for Rail Traffic Controllers."</i> Both RTCs were in compliance with this required action. RTC #1 has been recertified, but has not taken the RTC Bridge Training. RTC #2 was recently qualified as an RTC and had taken RTC Bridge Training. 		
 <i>R-1-6-a: "WMATA must establish and enforce a proper protocol for language and terminology that is used over the radio – to include 100 percent word-for-word read-back for safety-related instructions and unusual train movements."</i> The FWSO inspector reviewed six crews on RWP protect list. Callon period took place from 1004 to 1048 hours. All crews requested Train Approach Warning (TAW) level of protection. The RTCs ensured all requests were received properly through read-backs. Power and Track personnel each performed word-forword confirmation of walking rights on the ROW. 	Recommended Reinspection?	Νο
 <i>R-1-6-b:</i> "As part of <i>R-1-6-a</i>, WMATA must establish an approach for communicating and managing all speed restrictions that require twoway communication between the ROCC and train operator and take full advantage of available electronic AIM system features." Per policy, RTCs must conduct hourly radio broadcasts that include a full read out of RWP protections, time confirmation, rule of the day, cardinal rule 1.79, and all operational anomalies in place. RTCs must also broadcast RWP personnel protection announcements every twenty minutes. The required hourly broadcasts were observed on or near each hour, and the RWP personnel protection announcements were observed at 20 – 30 minute intervals. RTCs also maintained a written log of all personnel on ROW and recorded all call on/call off times. Per ROCC protocol and training, visual protection icons (blue man blocking device/blue line indications) were activated on the AIM system to indicate personnel presence on ROW. Note: This is still a visual aid only; it does not provide an electronic block to prevent train routing into a protected black/track. 		
 R-1-7-b: "WMATA must enhance RTC reference materials to direct internal operations at the ROCC, includingand internal ROCC administrative policies and procedures." Per WMATA rules and policy (see Permanent Order T-16-10 and Operations Radio Communication Training), ROCC has implemented a scripted reminder regarding proper radio usage that must be broadcast hourly to all RTCs (see above). The FWSO inspector observed that all hourly announcements were made on or near the hour. The announcements contained slow speed locations (due to leaves), RWP protect list, elevator/escalator outages, and radio protocol (the "over" and 		



 "out" requirements). The FWSD inspector observed inconsistent use of "over" and "out" in radio communication loops among RFCs. This was discussed in a meeting with the Director, and the will put monitoring took in plate to ensure compliance. (See FWSD report 20161122-WMATA-AD-3.) R-1-8-a: "WMATA must establish a clear policy that prohibits distractions from the use of cell phones and after electronic devices in the ROCC." The FWSD inspector did not observe any RTC or other ROCC personnel in violation of said policy at any time during entire period of observation. R-1-9-a: "Until such time as electronic transfer records are implemented. WMATA must ensure that its RTC use paper-based logs with formal signatures." The FWSD inspector observed a shift transfer for one RTC, which occurred at 1200 hours. The RTC notlifed the releving employee of all operating conditions and anomalies, as well as all RWP protects in effect during time of transfer. The releving employee of all operating conditions of duties. R-1-4: "While it has improved, the quality of WMATA's radio system is still poor in some locations." The FWSD inspector observed to RTCs address a 7 series train with troible code. RTC and enterprists to troubleshoot issue with the Querator. He then turned to this colleague for assistance. The RTC later information is a meeting with the received an a Abnuc currue on the 7 series or 1.5 years ago and wanted a refresher course. The FWSD inspector observed the RTCs address a 7 series train with troible code. RTC and enterprists to troubleshoot issue with the Querator. He then turned to this colleague for assistance. The RTC later is informed the RVSD inspector and the received an abnuc currue on the 7 series or 1.5 years ago and wanted a refresher course. The FWSD inspector constated the RTCC address a 7 series train with troible code. RTC collide the Core constatod the address a regioned is	redefai Transit A		
 from the use of cell phones and other electronic devices in the ROCC. The FWSO inspector did not observe any RTC or other ROCC personnel in violation of said policy at any time during entire period of observation. R-19-a: "Until such time as electronic transfer records are implemented, WMATA must ensure that its RTC use paper-based logs with formal signatures." The FWSO inspector observed a shift transfer for one RTC, which occurred at 1300 hours. The RTC notified the relieving employee of all operating conditions and anomalies, as well as all RWP protects in effect during time of transfer. The relieving employee logged into the Advanced Information Management (AIM) system before taking over operations of duties. R-14: "While it has improved, the quality of WMATA's radio system is still poor in some locations." The FWSO inspector observed poor radio communication on one occasion during time of monitoring. Train operators and personnel eventually received the radio transfission, but required a few read-backs until fully understood and acknowledged. Additional observations: The FWSO inspector observed the RTCs address a 7 series train with trouble code. RTC made attempts to troubleshoot issue with the Operator. He than trund to his colleague for assistance. The RTC later informed the FWSO inspector that he received an 8-hour course on the 7 series. (See FWSO report 20161122-WMATA-3-3) At approximatel that all RTCs have gone through training and were provided troubleshooting guides. Additionally, RTCs will so the staing are resisend that all scale that and resise. The FWSO inspector protector source deprections of protector suites of this responsibilities, He immediately requested a landline call to inform the person that his request was within the SafeTrack designated area and model and the collary of the source of this responsibilities. The immediately requested a landline call to inf		 The FWSO inspector observed inconsistent use of "over" and "out" in radio communication loops among RTCs. This was discussed in a meeting with the Director, and she will put monitoring tools in place to ensure compliance. (See FWSO report 20161122-WMATA- 	
 WMATA must ensure that its RTC use paper-based logs with formal signatures." The FWSO inspector observed a shift transfer for one RTC, which occurred at 1300 hours. The RTC notified the relieving employee of all operating conditions and anomalies, as well as all RWP protects in effect during time of transfer. The relieving employee logged into the Advanced Information Management (AIM) system before taking over operations of duties. R-14: "While it has improved, the quality of WMATA's radio system is still poor in some locations." The FWSO inspector observed poor radio communication on one occasion during time of monitoring. Train operators and personnel eventually received the radio transmission, but required a few read-backs until fully understood and acknowledged. Additional observations: The FWSO inspector observed the RTCs address a 7 series train with trouble code. RTC made attempts to troubleshoot issue with the Operator. He then turned to his colleague for assistance. The RTC later informed the FWSO inspector consulted the ROC Director for clarification in a meeting with her on her findings from three comprehensive RTC shift observations. The FWSO inspector consulted the ROC Director for clarification in a meeting with her on her findings from three comprehensive RTC shift observations. The Director stated that all RTCs have gone through training and were provided troubleshooting guides. Additionally, RTCs will soon be taking a refresher course on the 7 series. (See FWSO report 20161122-WMATA-AD-3.) At approximately 155 hours, a Power Department unit called on to request permission to enter ROW at 81-211 (outside of Brookland). The RTC realized area of RWP protection was outside of the scope of his responsibilities. He immediately requested a landine call to inform the person that his request was within the SafeFTrack designated area and directed him to call on to Mobile Command 14. 		 from the use of cell phones and other electronic devices in the ROCC." The FWSO inspector did not observe any RTC or other ROCC personnel in violation of said policy at any time during entire 	
 still poor in some locations." The FWS0 inspector observed poor radio communication on one occasion during time of monitoring. Train operators and personnel eventually received the radio transmission, but required a few read-backs until fully understood and acknowledged. Additional observations: The FWS0 inspector observed the RTCs address a 7 series train with trouble code. RTC made attempts to troubleshoot issue with the Operator. He then turned to his colleague for assistance. The RTC later informed the FWS0 inspector observe that he received an 8-hour course on the 7 series car 1.5 years ago and wanted a refresher course. The FWS0 expector cosulted the ROCC Director for clarification in a meeting with her on her findings from three comprehensive RTC shift observations. The Director stated that all RTCs have gone through training and were provided troubleshooting guides. Additionally, RTCs will soon be taking a refresher course on the 7 series. (See FWS0 report 20161122-WMATA-AD-3.) At approximately 1555 hours, a Power Department unit called on to request permission to enter ROW at B1-211 (outside of Brookland). The RTC realized area of RWP protection was outside of the scope of his responsibilities. He immediately requested a landline call to inform the person that his request was within the SafeTrack designated area and directed him to call on to Mobile Command 14. 		 WMATA must ensure that its RTC use paper-based logs with formal signatures." The FWSO inspector observed a shift transfer for one RTC, which occurred at 1300 hours. The RTC notified the relieving employee of all operating conditions and anomalies, as well as all RWP protects in effect during time of transfer. The relieving employee logged into the Advanced Information Management (AIM) system before 	
 The FWSO inspector observed the RTCs address a 7 series train with trouble code. RTC made attempts to troubleshoot issue with the Operator. He then turned to his colleague for assistance. The RTC later informed the FWSO inspector that he received an 8-hour course on the 7 series car 1.5 years ago and wanted a refresher course. The FWSO inspector consulted the ROCC Director for clarification in a meeting with her on her findings from three comprehensive RTC shift observations. The Director stated that all RTCs have gone through training and were provided troubleshooting guides. Additionally, RTCs will soon be taking a refresher course on the 7 series. (See FWSO report 20161122-WMATA-AD-3.) At approximately 1555 hours, a Power Department unit called on to request permission to enter ROW at B1-211 (outside of Brookland). The RTC realized area of RWP protection was outside of the scope of his responsibilities. He immediately requested a landline call to inform the person that his request was within the SafeTrack designated area and directed him to call on to Mobile Command 14. 		 still poor in some locations." The FWSO inspector observed poor radio communication on one occasion during time of monitoring. Train operators and personnel eventually received the radio transmission, but required a few 	
 trouble code. RTC made attempts to troubleshoot issue with the Operator. He then turned to his colleague for assistance. The RTC later informed the FWSO inspector that he received an 8-hour course on the 7 series car 1.5 years ago and wanted a refresher course. The FWSO inspector consulted the ROCC Director for clarification in a meeting with her on her findings from three comprehensive RTC shift observations. The Director stated that all RTCs have gone through training and were provided troubleshooting guides. Additionally, RTCs will soon be taking a refresher course on the 7 series. (See FWSO report 20161122-WMATA-AD-3.) At approximately 1555 hours, a Power Department unit called on to request permission to enter ROW at B1-211 (outside of Brookland). The RTC realized area of RWP protection was outside of the scope of his responsibilities. He immediately requested a landline call to inform the person that his request was within the SafeTrack designated area and directed him to call on to Mobile Command 14. 		Additional observations:	
 request permission to enter ROW at B1-211 (outside of Brookland). The RTC realized area of RWP protection was outside of the scope of his responsibilities. He immediately requested a landline call to inform the person that his request was within the SafeTrack designated area and directed him to call on to Mobile Command 14. 		 trouble code. RTC made attempts to troubleshoot issue with the Operator. He then turned to his colleague for assistance. The RTC later informed the FWSO inspector that he received an 8-hour course on the 7 series car 1.5 years ago and wanted a refresher course. The FWSO inspector consulted the ROCC Director for clarification in a meeting with her on her findings from three comprehensive RTC shift observations. The Director stated that all RTCs have gone through training and were provided troubleshooting guides. Additionally, RTCs will soon be taking a refresher course on the 7 series. (See FWSO report 20161122-WMATA-AD-3.) 	
		 request permission to enter ROW at B1-211 (outside of Brookland). The RTC realized area of RWP protection was outside of the scope of his responsibilities. He immediately requested a landline call to inform the person that his request was within the SafeTrack designated area and 	
	Remedial Action		



Federal Transit Administration

Form FTA-IR-1

Agency/Department Information

Inspection Date	YYYY	MM	DD	Donort Number	20161121-WMATA-AD-1			
Inspection Date	2016	11	21	Report Number				
Rail Agency Name	Washington Authority	Metropolitan A	rea Transit	Rail Agency Department	TRST	Sub- Department		Production
Name				Email	Office Phone		Ν	Nobile Phone
Rail Agency Department Contact Information								
Inspection Location	Yellow, Silver, Blue, Orange Lines							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	OPS-RI-OBS					
Inspection Units	1					
Inspection Subunits	4					
Defects (Number)	3					
Recommended Finding	No					
Remedial Action Required ¹	Yes					
Recommended Reinspection	No					

Activity Summaries

Inspection Activity #	1	Inspe	ction Subj	ect	Train Op	perator	Compliance	e Observatio	n	Activity Co	de	OP:	S	RI	OBS
Job Briefing Employee Name/Title	N/A					Accon Inspe	npanied ctor?	No	Out Brief Conducted	N/A	Time	0830 1430		Outside Shift	No
Related Reports						Relate	ed CAPS / F	indings							
	Ref				Rule or S	ОР		Standard		Other / T	ïtle		Check	list Refer	ence
Related Rules, SOPs, Standards, or Other	SOP														
1	Maii Trac		Yard	Stat	ion C	occ	RTA Facility	FTA Office	T	At-grade	e Tui	nnel	Elevated		N/A
Inspection Location	x			х					Track Type	x		x	x		
									From			То			
Line(s)	Yellov Silver, Orang Lines	Blue,	Track Numbe	r	1&2		Chain Marker and/or Station(s)		Greenbelt L'Enfant Plaza Largo Town Center Metro Center			Gallery Place Largo Town Center Metro Center West Falls Church			
	Hea	d Car N	Number		Number c	of Cars		_							
Vehicles		N/A	١		N/A		Equip	ment	N/A						
Description										Number	of Defect	s			3

Inspector in Charge - Signature A	MBURIDALEY	DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY Date: 2016.12.08 10:26:27 -05'00'	Date
Inspector in Charge – Name Ambur Daley	Inspection Team Alexander Nepa, Kevin McDonald		

	The FWSO team observed operations for the following trains, and no exceptions	Recommended Finding?	No
	 were taken: Yellow line train number 308 between Greenbelt and Gallery Place. 	Remedial Action Required?	Yes
	 Silver line train number 601, lead car number 5166, between L'Enfant Plaza and Largo Town Center. The FWSO team observed operations for the following trains, and found the following defects: 		
	 Blue line train number 403, lead car number 7216, between Largo Town Center and Stadium-Armory. At the portal between Largo Town Center Station and Morgan Blvd. Station, the operator failed to sound horn upon entering the portal. Orange line train number 901, lead car number 3118, between Stadium Armory and East Falls Church. Operator failed to sound horn upon entering the portal between East Falls Church and Ballston-MU. At CM R2-344+00, operator failed to sound horn as train approached an ATC work crew on the tracks. The operator did stop to pick up the work crew and take them back to East Falls Church Station but failed to signal upon approaching them. 	Recommended Reinspection?	No
Remedial Action	WMATA must ensure that the train operators who failed to sound their horns are pro	perly counseled on the SOP requiren	nents.

Agency/Department Information

Federal Transit Administration

Inspection Date	YYYY	MM	DD	Report Number	20161121-WMATA-AD-2				
Inspection Date	2016	11	21	Report Number					
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	ROCC	Sub- Department		N/A	
Rail Agency Department	Name			Email	Office Phone		N	Mobile Phone	
Contact Information									
Inspection Location		Carmen Turner Facility 3500 Pennsy Drive, Hyattsville, MD 20785							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	ROCC-RC-OBS					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	NO					

Activity Summaries

Inspection Activity #	1	Inspect	tion Subj	ect	Rules Compliance & Safety Management Inspection (SMI) Required Actions Observation of Rail Traffic Controllers					Activity Co	ode	ROO	cc	RC	OBS	
Job Briefing Employee Name/Title	N/A			Accompanied Inspector?		N/A	Out Brief Conducted	Yes	Time	1500 200	-	Outside Shift	No			
Related Reports	Safety Management Inspection (SMI), Final Report, June 17, 2015			Relat	ed CAI	d CAPS / Findings Required Action (R-1-9-a); and			ions: (R-1-2-a); (R-1-6-a) & (R-1-6-b); (R-1-7-b); (R-1-8-a); I Finding R-14); (R-1-8-a);			
	Ref				Rule or S	SOP			Standard		Other / T	ïtle		Checklist Reference		
Related Rules, SOPs, Standards, or Other		rocedure	ety Rules es		(Radio L Operatio	1 – General Rules isage and X on): X 59 – 1.88			x			x				
	Perm	anent Or	rder		NO. T-16	5-10										
	Mai Trac		Yard	Stat	ion	220	RT/ Facil		Main Track	Yard	At-grad	e Tui	nnel	Ele	evated	N/A
Inspection Location						х										х
line(a)			Track		N/A		Chair	n Mar	ker		From		То			
Line(s)	N/A		Numbe	r	IN/A		and/	or Sta	tion(s)	N/A			N/A			
	Hea	ad Car Nu	umber		Number	of Cars										
Vehicles		N/A			N/A		E	quipn	nent	N/A						
Description							1				Number	of Defect	s			0

sujjicient unu ejjective.		Digitally signed by AMBUR I DALEY	
Inspector in Charge - Signature	AMBUR I DALEY	Distany signed by AMBORT DALL1 Dist.edUS, eUS, Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I -DALEY Date: 2016.12.05 18:43:30 -05'00'	Date
Inspector in Charge – Name	Inspection Team		
Ambur Daley	Tamara Powell		



An FWSO inspector conducted an observation of the Rail Traffic Controllers (RTC) at	Recommended Finding?	No
the Rail Operations Control Center (ROCC) at the OPS 3 console, on the Yellow, Green, and partial Blue lines. The following observations were conducted:	Remedial Action Required?	No
 The FWSO inspector observed the radio transmissions and performance of two RTCs. RTC #1, the Button Controller, is an outside hire with previous transit experience who has been employed at WMATA in the ROCC for 5.5 years. RTC #2, the Radio Controller, is also an outside hire, and has served over 3 years at WMATA as an RTC. Lastly, there was a third RTC that relieved RTC #1, who has been employed at WMATA for 10 years, with 4 years served at the ROCC. The FWSO inspector's observation and compliance check focused mainly on ROCC required actions and radio usage and operation (General Rules, #1.69 – 1.88 and Permanent Order T-16-10). The observation and compliance check was based on several findings from the SMI report, as well as rules from the <i>MetroRail Safety Rules and Procedures Handbook</i>. Observations related to SMI report findings: 		
 R-1-2-a: "WMATA must complete and maintain required annual recertifications for Rail Traffic Controllers." Both RTCs were in compliance with this required action. RTC #1 has been recertified, and is currently enrolled in the RTC Bridge Training course. RTC #2 has very recently completed Bridge Training, and was jointly recertified during the training course. 		
 R-1-6-a: "WMATA must establish and enforce a proper protocol for language and terminology that is used over the radio – to include 100 percent word-for-word read-back for safety-related instructions and unusual train movements." During the afternoon rush hour, the FWSO inspector observed RTC #2 during each radio broadcast, all of which were in compliance with this directive. RTC ensured each unit or operator repeated back each instruction, clearance, or operating instruction with 100 percent word-for-word read back, as required. There were no exceptions taken. Starting at 1909 hours, units began calling on to the ROW to request RWP protection. The RTC ensured all requests were received properly through read-backs. FWSO inspector observed one instance where a Power department unit (who was reportedly a new hire to the agency) attempted to call on with an incomplete RWP protect request. He did not clearly define limits of request delarance and protect and was not in compliance with 100 percent read-back. The RTC promptly requested a landline call and reinstructed personnel on proper protocols, by requesting the chain marker location for the power room for which access was requested. When the RTC was satisfied the unit had met all requirements, he granted access to the ROW. Power personnel then performed a word-for-word confirmation of walking rights on the ROW, and confirmed identification of all hot spots. The RTC closed by acknowledging all radio check request as, "That is a good copy," and turned over or closed out each transmission with "over" and "out" until conclusion of the communication loop. R-1-6-b: "As part of R-1-6-a, WMATA must establish an approach for communication between the ROCC and train operator and take full advantage of available electronic AIM system features." Per policy, RTCs must conduct hourly radio broadcasts that include a full read out of ROW protections (if applicable), time confirmation, rule	Recommended Reinspection?	No



Federal Transit A	aministration	
	hour, and the ROW personnel protection announcements were	
	observed at 20 – 30 minute intervals. RTCs also maintained a	
	written log of all personnel on ROW and recorded all call on/call off	
	times.	
	 Per ROCC protocols and training, visual protection icons (blue man blacking during (blue ling indications) were activated on the ANA 	
	blocking device/blue line indications) were activated on the AIM	
	system to indicate personnel presence on ROW. Note: This is still a	
	visual aid only; it does not provide an electronic block to prevent	
	train routing in/onto a protected block/track.	
	• R-1-7-b: "WMATA must enhance RTC reference materials to direct	
	internal operations at the ROCC, includingand internal ROCC	
	administrative policies and procedures."	
	 FWSO inspector made a random visual notation of reference 	
	guides located at the OPS 3 console. Reference materials observed	
	include the following: Standard Operating Procedures (SOP)	
	manual, Troubleshooting Guide/Procedure Checklist manual, RWP	
	manual, Power Reconfiguration manual, OPS 3 resource binder,	
	and an hourly broadcast memorandum (scripted reminder).	
	 Per WMATA rules and policy (see Permanent Order T-16-10 and 	
	Operations Radio Communication Training), the ROCC has	
	implemented a scripted reminder regarding proper radio usage	
	that must be broadcast hourly to all personnel (see above).	
	 FWSO inspector observed that all hourly announcements were 	
	made on or near the hour. The announcements contained slow	
	speed locations (there were several locations listed on the lines),	
	RWP protect list, elevator/escalator outages, and radio protocol	
	(the "over" and "out" requirements), and any other pertinent	
	operating anomalies.	
	• R-1-8-a: "WMATA must establish a clear policy that prohibits distractions	
	from the use of cell phones and other electronic devices in the ROCC."	
	 The FWSO inspector did not observe any RTC or other ROCC 	
	personnel in violation of said policy at any time during entire	
	period of observation.	
	• R-1-9-a: "Until such time as electronic transfer records are implemented,	
	WMATA must ensure that its RTC use paper-based logs with formal	
	signatures."	
	• There was one shift transfer during period of observation at 1726	
	hours. The relieving employee took over button controller duties.	
	• The RTC notified the relieving employee of all operating conditions	
	and anomalies in effect during time of transfer. The relieving	
	employee logged into the Advanced Information Management	
	(AIM) system before taking over operations of duties.	
	D 14. (While it has improved the sublit of the AATA!	
	 R-14: "While it has improved, the quality of WMATA's radio system is still poor in some locations." 	
	 still poor in some locations." The FWSO inspector observed very poor radio communication 	
	 The FWSO inspector observed very poor radio communication sporadically during entire time of monitoring. 	
	 All three OPS frequencies were bleeding over into each other throughout the rush hour. 	
	 Train operators and personnel eventually received the radio 	
	transmission, but required a few read-backs until fully understood	
	and acknowledged. RTC kept a written note of all units and train	
	operators that were able to identify, but unable to transmit	
	message. The RTC took his time addressing each transmission until	
	the list of pending transmissions was exhausted.	
	and not of pertains transmissions was condusted.	
	Additional observations:	
	• The FWSO inspector observed severe service delays during the entire	
	shift on all lines operating in OPS 3 jurisdiction. The slow speed areas	
	served as a major contribution to this operating anomaly. Causes for the	
	slow speed areas were as follows: hot spots, defective ties, and rail	





Inspection Form

Form FTA-IR-1

United States Department of Transportation Federal Transit Administration

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20161122 \//	1ATA A	ח 1		
inspection Date	2016	11	22	Report Number	20161122-WMATA-AD-1				
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	TRST -Operations	Sub- Dep	artment	Production - SAFE	
	l	Name		Email	Office Phone	e	Ν	Nobile Phone	
Rail Agency Department Contact Information									
Inspection Location Yellow and Red lines, Rhode Island platform									
Inspection Summary									

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	OPS-RI-OBS	TRK-RWP-OBS				
Inspection Units	1	1				
Inspection Subunits	3	3				
Defects (Number)	0	0				
Recommended Finding	No	No				
Remedial Action Required ¹	No	No				
Recommended Reinspection	No	No				

Activity Summaries

Inspection Activity #	1	Inspection S	ıbject	Train R	de Obser	rvation			Activity Co	de	OPS	S	RI	OBS
Job Briefing Employee Name/Title					Accom Inspec	panied tor?	No	Out Brief Conducted	N/A	Time	1000 1400	1	Outside Shift	No
Related Reports					Related CAPS / Findings									
	Ref			Rule or	SOP		Standard		Other / T	ïtle		Check	ist Refer	ence
Related Rules, SOPs, Standards, or Other	SOP													
Standards, or other														
lucus sticus I consticus	Main Track	Yard	rd Station OC		220	RTA Facility	FTA Office	Tuesda Taura	At-grade	e Tui	nnel	Eleva	ated	N/A
Inspection Location	x			x				Track Type	x		x	×		
									From				То	
			le .			Chain Ma	kor	Greenbelt			Fort To	otten		
Line(s)	Yellow	line Nun		1&2		and/or Sta		Fort Totten			King St	t – Old	Town	
						,		King St – Old	Town			y Place		
								Gallery Place			Rhode	e Island	station	
Vahialaa	Head	l Car Numbei		Number	of Cars	Faulta	mont	NI/A						
Vehicles		N/A		N/.	Ą	Equip	ment	N/A						
Description	•	FWSO in	spector	s boarded	the Yello	w line to k	(ing St. for tr	ain ride	Number	of Defect	S			0

sujjicient und ejjective.		2	
Inspector in Charge - Signature		Digitally signed by AMBUR I DALEY	Date
	AMBURIDALEY	DN: c=US, o=U.S. Government, ou=DOT	
		Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY	
		Date: 2016 12 05 19:55:47 -05'00'	
Inspector in Charge – Name	Inspection Team		
Ambur Daley	Alexander Nepa, Kevin McDonald		



	 observations. No exceptions. FWSO inspectors then boarded train 303 to Gallery Place. No exceptions. 	Recommended Finding? Remedial Action Required? Recommended Reinspection?	No No No
Remedial Action	N/A		

Inspection Activity #	2	Insp	ection Sub	ject	RWP Ir	spectio	n of Surge /	Area		Activity Co	de	TR	K	RWP	OBS	
Job Briefing Employee Name/Title	TRST 6	6101					mpanied ector?	No	Out Brief Conducted	Yes	Time	1000 1400		Outside Shift	No	
Related Reports						Related CAPS / Findings										
	Ref				Rule or	r SOP Standard				Other / Title				Checklist Reference		
Related Rules, SOPs, Standards, or Other	SOP															
Standards, or other																
Inspection Location	Mair Trac		Yard	Stati	ion	осс	RTA Facility	FTA Office	Track Type	At-grade	e Tu	nnel	Ele	evated	N/A	
Inspection Location	x								ттаск туре					x		
Line(s)	Pod Li	no	Track		1 8 2		Chain Ma	rker		From				То		
Line(s)	Red Li	Red Line Number 1 & 2					and/or Station(s) Rhode Island A			Avenue		Fort	Fotton			
Vehicles	Hea	d Car	Number		Number	of Cars	- Fault		NI/A							
venicies		N/	/Α		N/.	A	Equip	oment	N/A							
										Number	of Defect	s			0	
	•							llery Place an Surge work f	d took the bus	Recomm	ended Fir	nding?			No	
			0					serving work		Remedia	l Action R	Require	d?		No	
Description		•	#10 entran 1 ID check; telephone	ce. The safety numbe ital loc	e briefing rule rev er; type c ation, ar	g was co iew (4.5 of prote nd pote	omprehensi 59); red tag ction (IT); a	ve. It include outage numb nd locations o		Recomm	ended Re	inspec	tion?		No	
Remedial Action	N/A									1						



Inspection Form

Form FTA-IR-1

United States Department of Transportation Federal Transit Administration

Agency/Department Information

Inspection Date 2016 11 22 Report Number 20101122-WINATA-AD-2 Rail Agency Name Washington Metropolitan Area Transit Authority Rail Agency Department OPMS Sub- Department Rail Agency Department Contact Information Name Email Office Phone Mobile Phone	Inspection Date	YYYY MM	DD	Report Number	20161122 \\/\	1 A T A A	د ח			
Rail Agency Name Authority Department OPMS Sub- Department Name Email Office Phone Mobile Phone Rail Agency Department Image: Compartment Mobile Phone	inspection Date	2016 11	22	Report Number	20161122-WMATA-AD-2					
Rail Agency Department	Rail Agency Name	• ·	Transit	• .	OPMS	Sub- Dep	artment			
		Name		Email	Office Phone	2	N	1obile Phone		
	• • •									
Inspection Location Carmen Turner Facility, Landover, MD	Inspection Location	Carmen Turner Facility, Landov	er, MD							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	RWP-TNG-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	1					
Recommended Finding	Yes					
Remedial Action Required ¹	Yes					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1	nspection Sub	ject	RWP Le	vel 1 an	d 4 Trainin	g Observatio	n	Activity Co	ode	RW	/P	TNG	OBS
Job Briefing Employee Name/Title	N/A	N/A			Accompanied Inspector?		N/A	Out Brief Conducted	No	Time	080 160		Outside Shift	No
Related Reports					Related CAPS / Findings									
	Ref			Rule or S	OP		Standard		Other / T	ïtle		Chec	klist Refe	rence
Related Rules, SOPs, Standards, or Other	WMAT	A RWP Manual												
standards, or other														
lucus stiens to eastien	Main Track	Yard	ard Station O		CC	RTA Facility	FTA Office	Tuesda Taura	At-grade Tunnel		nnel	Elevated		N/A
Inspection Location						х		Track Type						х
Line(s)	N/A	Track		N/A		Chain Marker			From				То	
Line(s)	N/A	Numbe	er	N/A		and/or Station(s) N/A					N/A			
Mahtala a	Head	Car Number		Number	of Cars	F . 1								
Vehicles		N/A		N/A	A	Equip	ment	N/A						
									Number	of Defect	s			1
Description					TA's Roadway Worker Protection (RWP) Level 1			Recommended Finding?					Yes	
Description						Irner Facility on November 7, 2016 and were taught by experienced instructors and			Remedial Action Required			d?		Yes
	consist	ed of classroom	n lectu	ures and p	ractical	simulation	s. The instruc	ctors had	Recomm	Recommended Reinspection?				Yes

Inspector in Charge - Signature	AMBURIDALEY	Digitally signed by AMBUR I DALEY DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FMCSAHQ, cn=AMBUR I DALEY Date: 2016.12.01 11:43:48 -05'00'	Date
Inspector in Charge – Name Ambur Daley	Inspection Team Chad Broski		



command of the classroom, materials, and the ability to convey their knowledge and experience to the students. They also encouraged students to actively participate in the program.	
RWP Level 1 training is a one-day (8 hour) course that is provided to all employees who require general access to the roadway for any reason. This is the minimum level of proficiency to allow individuals to enter the roadway accompanied by a Roadway Worker in Charge (RWIC). RWP Level 4 training is typically a five-day course, and it is provided to all employees who are responsible for providing RWP in the capacity of a RWIC.	
The WMATA Roadway Worker Protection Manual is one of the main reference materials used in RWP Level 1 and Level 4 training. However, FWSO found some conflicting or confusing points in the WMATA Roadway Worker Protection Manual, dated June 1, 2014, with regard to Key Personnel, Roadway Worker Protection, and Hot Spots and No Clearance Zones.	
 Key Personnel The Watchman/Lookout duty, as defined in 2.1 and 2.2, conflicts with the protocols described in 2.16 and 2.23-2.31. FWSO believes that the Watchman/Lookout has been confused with the Roadway Flag Person (RFP) in sections 2.16 and 2.23-2.31. The following excerpts show the discrepancies within the manual: 	
 2.1. Employees assigned as Watchman/Lookout shall not perform any other duties while in this capacity. 2.2. A Watchman/Lookout's sole duty is to warn the personnel of approaching rail vehicles. 	
 2.16. Watchman/Lookouts shall ensure that all personnel are clear of the dynamic outline of any train or rail equipment BEFORE giving a proceed signal. 2.23. Watchman/Lookouts shall signal the train or rail equipment only when authorized by the RWIC and it is safe to proceed. 2.24. Watchman/Lookouts shall face the oncoming traffic to be flagged if it is safe to do so. 2.25. Watchman/Lookouts shall, if authorized by the RWIC and it is safe to do so, give the proceed signal by moving their arm straight up and down in a vertical motion. 2.26. Watchman/Lookouts shall NEVER give a proceed signal unless absolutely sure all personnel are in a place of safety 	
and the tracks are clear for travel through the working limits. 2.27. Watchman/Lookouts shall NEVER give a proceed signal to oncoming traffic on an adjacent track when the adjacent track is a separate working zone. 2.28. A single Watchman/Lookout shall give the proceed signal to trains or rail equipment on the adjacent track only if it is safe to do so.	
 2.29. A Watchman/Lookout needing to signal trains or rail equipment to proceed shall face oncoming traffic to be flagged once the RWIC authorizes rail vehicle movement through the work zone and shall give the proceed signal by moving their arm straight up and down in a vertical motion. No proceed signal shall be given if the tracks are not clear for traffic. 2.30. A Watchman/Lookout needing to signal trains or rail 	
 2.30. A Watchman/Lookout needing to signal trains or rail equipment to STOP shall face the oncoming traffic to be flagged and shall stop a train or rail vehicle by waving their arm back and forth horizontal to the tracks. The Watchman/Lookout shall continue this action until the train or rail equipment comes to a complete stop. 2.31. A Watchman/Lookout needing to signal trains or rail equipment to Slow Down shall slow down the train or rail 	

0

	vehicle, on either track, by extending their arm horizontal to the track. The arm must be fully extended with the hand clutched into a fist.
	 b) The rules pertaining to the Roadway Worker-In-Charge (RWIC) further compound the confusion between the duties of a Watchman/Lookout vs. the Roadway Flag Person by stating the following:
	 1.55. In a mobile work gang, the RWIC shall designate one employee as Watchman/Lookout to signal approaching vehicles on the occupied track to provide work zone protection, and assign a RWP Qualified person to acknowledge trains on the adjacent track. 1.56. The RWIC of a mobile work gang shall maintain the ability to stop trains or rail equipment moving through the working limits by:
	1.56.1. Installing a shunt and lanterns, or 1.56.2. Using a Watchman/Lookout doubling as a Roadway Flag Person (RFP), or 1.56.3. Placing prohibit exits on interlocking switches (ONLY qualified Automatic Train Control (ATC) personnel with the permission of ROCC can take Local Control of interlocking's).
	 1.56.4. The RWIC of a mobile work gang, not using shunting protection, must use a RFP. 1.56.5. The RWIC of a mobile work gang shall maintain the ability to communicate with ROCC at all times. 1.57. The RWIC of a mobile work gang, not using shunting
	protection, must use a Watchman/Lookout doubling as a RFP.
2. Rc	 a) Train Approach Warning (TAW) Protection is the use of Watchman/Lookouts. Under TAW Protection, the Watchman/Lookout's sole duty is to detect the approach of train and rail equipment and provide ample warning to the roadway workers to clear to a place of safety before the arrival of any rail vehicle. Similar to what we found in the Key Personnel section of the RWP Manual, TAW rules and procedures 4.1 and 4.2, which define the Watchman/Lookout duties under TAW, conflicts with the duties described in 4.16 and 4.23-4.31.
	 b) Exclusive Track Occupancy (ETO) Protection is the authority issued by ROCC to the RWIC to control a specific area of the roadway within specified working limits, whereby the exclusive authority to permit train and rail equipment traffic through any given work limits rests solely with the RWIC. The rules and procedures for ETO Protection, as outlined in the RWP manual, are vastly different than TAW Protection.
	 According to the RWP manual, one method of establishing ETO Protection is to place a Roadway Flag Person at each entrance to the track within working limits with the capability to STOP or proceed trains through the work limits at the direction of the RWIC. The RWP manual outlines the means that a Roadway Flag Person would use to stop a train, which is not included in the rules for Watchman/Lookouts. The
3. Но	current WMATA RWP rules merge the responsibilities of the Watchman/Lookout with the Roadway Flag Person. ot Spots and No Clearance Zones
5. 10	 a) Hot Spots are defined in the RWP Manual (in part) as physical locations on the railroad where additional RWP is required due to limited visibility (i.e. curves, obstructions, etc.), heavy noise, and/or close clearance.
	 b) Hot Spots rule 1.5 requires the RWIC to invoke ETO Protection when there are "visual impediments or blind



	Protection for visual impediments or blind spots. Additionally, Hot Spots rule 1.4 refers the RWIC to the Roadway Access Guide to determine any and all Hot Spots contained within their working limits. However, the Roadway Access Guide does not use the term "Hot Spots". Instead, it shows three levels of minimum protection, and the "Danger Areas" (i.e. blind spots) make no reference to invoke ETO Protection. Instead, it gives the RWIC the option to use TAW Protection or Roadway Flag Person, which contradicts Hot Spots rule 1.5 in which ETO is the only option provided. c) Rule 1.79 in the Roadway Worker-In-Charge section further creates ambiguity by stating, "The RWIC shall request ROCC to communicate their location to all approaching trains and rail equipment when traversing through visual impediments or blind spots and the RWIC shall request ETO Protection if the work gang stops in areas where there are visual impediments or blind spots." The ambiguous nature of the rules pertaining to the duties of the Watchman/Lookout vs. Roadway Flag Person and the rules governing TAW Protection -especially for Hot Spots—can be misleading and left to interpretation. This lack of clarity may reduce the effectiveness of the Good Faith Challenge policy, create confusion between rail vehicle operators and roadway workers, and ultimately lead to complacency.
Remedial Action	WMATA should ensure that the rules pertaining to the duties of the Watchman/Lookout vs. Roadway Flag Person and the rules governing TAW Protection vs. ETO Protection—especially for Hot Spots—are clarified in the 2016 revision to the Roadway Worker Protection Manual.

Agency/Department Information

Federal Transit Administration

0 // 1										
Inspection Date	YYYY	MM	DD	Report Number	20161122-WMATA-AD-3					
inspection Date	2016	11	22	Report Number	20101122-WIVIATA-AD-3					
Rail Agency Name	Washington Authority	Metropolitan /	Area Transit	Rail Agency Department	ROCC	Sub- Department N/A		N/A		
Rail Agency Department		Name		Email	Office Phone	5	Ν	Mobile Phone		
Contact Information										
Inspection Location Carmen Turner Facility 3500 Pennsy Drive, Hyattsville, MD 20785										

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	ROCC-RC-MTG					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

Inspection Activity #	1	Inspe	ction Subj	ect	Rules Compliance & Safety Management Inspection (SMI) Required Actions Observation of Rail Traffic Controllers						de	ROC	c	RC	MTG
Job Briefing Employee N/A Name/Title							mpanied ector?	N/A	Out Brief Conducted	Yes	Time	1500 170	-	Outside Shift	No
Related Reports	ts Safety Management Inspection (SMI), Final Report, June 17, 2015						Related CAPS / Findings Required Action				ions: R-1 through R-14				
	Ref				Rule or	SOP		Standard		Other / T	itle		Check	klist Refere	ence
Related Rules, SOPs, Standards, or Other	and P Hand 2016 2016 2016	rocedu book; 1114-W 1118-W 1121-W	/MATA-AC /MATA-AC /MATA-AC	A-AD-1; Section Rules (R A-AD-1; Operation A-AD-1; Rules 1.			ection 1 – General ules (Radio Usage and peration): ules 1.69 – 1.88			x			Х		
	-	anent C	Drder		NO. T-1	6-10	DTA	N 4 - 1 -							
Inspection Location	Mai Trac		Yard	Stati	on (DCC	RTA Facility	Main Track	Yard	At-grade	e Tu	nnel	Elev	vated	N/A
						х									х
Line (a)	NI / A		Track		Chain Mar			ker		From			То		
Line(s)	N/A		Numbe	er	N/A		and/or Sta	ition(s)	N/A			N/A			
Vehicles	Hea	nd Car N	lumber	1	Number o	of Cars	Equip	nent	N/A						

Inspector in Charge - Signature	AMBURIDALEY Headquarters, ou=DALEY DALEY Headquarters, ou=FMCSAHQ, cn=AMBURI DALEY Date: 2016.12.05 18:12:33-05'00'	Date
Inspector in Charge – Name Ambur Daley	Inspection Team Tamara Powell	

Description Number of Defects Description Number of Defects Recommended Reinspection? Recommended Reinspection?	0 No
three recent rules compliance observations she conducted at all three Ops stations in the ROCC. The observations focused on controller and ROCC staff rules compliance with MetroRail Safety Rules and Procedures Handbook (MSRPH), recent permanent orders regarding radio protocols, and the Safety Management Inspection (SMI) required actions. The FWSO inspector discussed a few issues in regard to training, radio protocol and usage, troubleshooting, and general practice. Remedial Action Required? General overview of discussion: All staff were observed in compliance with the cell phone ban policy. There were no violations observed at any time. Overall there were no noise-related disruptions at the ROCC. Radio reception was barely adequate, most notably during observation on 11/21/16. The Director stated the radio communication team is working on the issue, and the radio system replacement will be complete in 2017. The ROCC Director reported that all ROCC staff and personnel are in compliance with the agency's recertification requirements. There are no RTCs out of compliance with this mandate. Additionally, the ROCC had just completed its 3rd course cycle for RTC Bridge Training. Generally, there are four RTCs scheduled per class. They are currently compiling an overall schedule to train the entire staff. All RTCs are currently RWP Level IV certified.	No
In the ROCC. The observations focused on controller and ROCC staff rules Remedial Action Required? compliance with MetroRail Safety Rules and Procedures Handbook (MSRPH), recent permanent orders regarding radio protocols, and the Safety Management Inspection (SMI) required actions. The FWSO inspector discussed a few issues in regard to training, radio protocol and usage, troubleshooting, and general practice. Image: Compliance with MetroRail Safety Rules and Procedures Handbook (MSRPH), recent Inspection (SMI) required actions. The FWSO inspector discussed a few issues in regard to training, radio protocol and usage, troubleshooting, and general practice. General overview of discussion: All staff were observed in compliance with the cell phone ban policy. There were no violations observed at any time. Overall there were no noise-related disruptions at the ROCC. Radio reception was barely adequate, most notably during observation on 11/21/16. The Director stated the radio communication team is working on the issue, and the radio system replacement will be complete in 2017. The ROCC Director reported that all ROCC staff and personnel are in compliance with the agency's recertification requirements. There are no RTCs out of compliance with this mandate. Additionally, the ROCC had just completed its 3rd course cycle for RTC Bridge Training. Generally, there are four RTCs scheduled per class. They are currently compiling an overall schedule to train the entire staff. All RTCs are currently RWP Level IV certified. Recommended Reinspection?	110
Description compliance with MetroRail Safety Rules and Procedures Handbook (MSRPH), recent permanent orders regarding radio protocols, and the Safety Management Inspection (SMI) required actions. The FWSO inspector discussed a few issues in regard to training, radio protocol and usage, troubleshooting, and general practice. General overview of discussion: All staff were observed in compliance with the cell phone ban policy. There were no violations observed at any time. Overall there were no noise-related disruptions at the ROCC. Radio reception was barely adequate, most notably during observation on 11/21/16. The Director stated the radio communication team is working on the issue, and the radio system replacement will be complete in 2017. The ROCC Director reported that all ROCC staff and personnel are in compliance with the agency's recertification requirements. There are no RTCs out of completen class. They are currently compiling an overall schedule to train the entire staff. All RTCs are currently RWP Level IV certified. Recommended Reinspection? 	No
observed RTCs experience difficulty in troubleshooting a 7K series train with an operational defect. In response, the Director said that the ROCC is currently finalizing a 2-day training course of the 7K train series. The program is still in draft and will be rolled out at the ROCC by the beginning of 2017. The FWSO inspector was able to view the draft. • FWSO inspector informed ROCC Director of an observation regarding radio usage and protocol. (See FWSO inspection report 20161118- WMATA-AD-1.) The FWSO inspector observed inconsistent use of "over" and "out" in radio communication loops among RTCs, which is required by Permanent Order T-16-10. The FWSO inspector noted this was observed generally with the exception of one RTC. The Director of ROCC and the FWSO inspector acknowledged challenges in changing behavior and past practices. The Director will monitor for policy compliance moving forward.	No

FOIA Exemption: All (b)(6)

United States Department of Transportation Federal Transit Administration

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20161122-WMATA-WP-1					
inspection Date	2016	11	22	Report Number	20101122-WWATA-WP-1					
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	RTRA	Sub- Department RAIL		RAIL		
Rail Agency Department	I	Name		Email	Office Phone	е	N	Mobile Phone		
Contact Information										
Inspection Location	Shady Grove	Yard								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	OPS-GEN-MTG					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summaries

Inspection Activity #	1	Inspe	ction Subj	ect	Gene	eral M	eeting v	vith Red	Line Supervi	sor	Activity Co	de	OF	s	GEN	MTG
Job Briefing Employee Name/Title	N/A					A	Accompany	anied	Yes	Out Brief Conducted	Yes	Yes Time		0 – 00	Outside Shift	No
Related Reports						R	Related	CAPS / F	indings							
	Ref	Ref Rule o			or SOP			Standard		Other / T	itle		Che	cklist Refe	ence	
Related Rules, SOPs, Standards, or Other																
	Mai Trac		Yard	Stat	ion	000	F	RTA acility	FTA Office	T	At-grade	e Tu	nnel	Ele	evated	N/A
Inspection Location			х							Track Type	x					
Line(s)	A-Line	e	Track Numbe	r	Yd. ⁻	Tracks	-	nain Maı nd/or Sta			From To					
	Hea	ad Car N	Number		Numbe	er of C										
Vehicles		N/A	A		Ν	N/A		Equip	nent	N/A						
	Gene		ervations:							1	Number	of Defect	s			0
			uperintenc otices to a				l distrib	uting Sat	ety Bulletins	and RTRA	Recomm	Recommended Finding?				No
Description					,		atures f	rom eacl	n employee d	on completed	Remedial Action Required?					No
Description		• F\ fr	orms and b WSO inspe	ulleti ctor r	ins to d reviewe	emon ed Rai	istrate a I Superv	in under visor Dai	standing of t y Activity Re	he material. ports (RSDAR) be working as	Recomm	ended Re	einspect	tion?		No

Inspector in Charge - Signature		Date
WINSLOW L. POWELL	Digitally signed by WMSLOW L POWELL Other cutS c=US Secomment, ou=PTAHQ, cn=WINSLOW L POWELL Dide: 2016.12.06 1257:14-05'00'	
Inspector in Charge – Name	Inspection Team	
Winslow Powell	Robert Maniuszko	



	 FWSO and Superintendent walked through the yard. Rail Roadway Maintenance Machines (RMM) were observed to be chocked as required. The yard in the area of vehicle lay-up was clear and free of debris. No exceptions were taken to this yard, and the practices employed by this Superintendent appear to meet or exceed the requirements of RTRA. 	
Remedial Action	N/A	



Agency/Department Information

Federal Transit Administration

		1	-	1						
Increation Data	YYYY	MM	DD	Poport Number	20161120 \					
Inspection Date	2016	11	29	Report Number	20161129-WMATA-CF-1					
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	TRST	Sub- Department	ткім			
		Name		Email	Office Phone	2	Mobile Phone			
Rail Agency Department Contact Information										
Inspection Location	A Line (Red)	from A-01 (N	letro Center) to A	-15 (Shady Grove) - #2 t	rack.					
Inspection Summary										
Inspection Activity #	1		2	3	4	5	6			
Activity Code	TRK-RI	-OBS								
Inspection Units	1									
Inspection Subunits	1									

Activity Summaries

Recommended Finding

Remedial Action Required¹

Recommended Reinspection

Defects (Number)

5

Yes

Yes

Yes

Inspection Activity #	1 I	nspection Sub	ject	Track U	ltrasonic	(UT) Testi	ng		Activity Co	ode	TR	K	RI	OBS
Job Briefing Employee Name/Title		/R	WIC L	evel 4	Accon Inspec	npanied ctor?	Yes	Out Brief Conducted	Yes	Time	213 043		Outside Shift	Yes
Related Reports	N/A				Relate	ed CAPS / I	Findings	N/A						·
	Ref			Rule or S	OP		Standard		Other / T	ïtle		Check	list Refer	ence
Related Rules, SOPs, Standards, or Other	TRST 10	TRST 1000												
standards, or other	RWPM													
lucus sticus I consticus	Main Track	Yard	Stat	ion (DCC	RTA Facility	FTA Office	Treak Treas	At-grad	e Tui	nnel	Elev	ated	N/A
Inspection Location	х							Track Type	x		х			
1:		Track		2		Chain Ma	rker		From				То	
Line(s)	A	Numb	er	2		and/or St	ation(s)	A01			A15			
	Head	Car Number		Number o	of Cars									
Vehicles	N/A N/A Equipment N/A													
Description		ccompanied t		•					Number	of Defect	s			5
	testing track.	on the A Line ((Red) f	rom A-01	(Metro	Center) to	A-15 (Shady	Grove) - #2	Recomm	ended Fir	nding?			Yes
	track.	Remedial Action Required? Yes									Yes			

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge - Signature	

Inspection Team Corwyn Foster, Al Nepa, Kevin McDonald

CORWYN DALE FOSTER

Digitally signed by CORWYN DALE FOSTE**Pate** DN: c=US, o=U.S. Government, ou=DOT FRAAtlantaGA, ou=FRA FRAAtlantaGA, o=CORWYN DALE FOSTER Date: 2016.12.09 12:12:27 -05'00'

Inspector in Charge – Name Corwyn Foster

Form FTA-IR-1 Version date: 8/26/16



	 The TGV can perform both track geometry and UT testing at the same time; and both geometry and UT testing was conducted during this survey. There were three UT and two TGV exceptions found during this inspection. A2 233 +69 Bolt Hole Crack on the right rail. (UT) A2 400 + 30 Defective Plant Weld on the left rail. (UT) A2 916 + 98 Detail Fracture 35% on the left rail. (UT) A2 712-+71 Narrow gage. The gage measured 55.85 inches. The narrow gage was caused by positive cant of the both the left and right rails. The cant positive cant is a direct result of deteriorating crossties. (TGV) A2 798 + 55 Narrow gage. The gage measured 55.85 inches. The narrow gage was caused by positive cant of the both the left and right rails. The cant positive cant is a direct result of deteriorating crossties. (TGV) 	Recommended Reinspection?	Yes
Remedial Action	 WMATA must repair Bolt Hole Crack on the right rail at A2 233 +69. WMATA must repair Defective Plant Weld on the left rail at A2 400 + 30. WMATA must repair Detail Fracture 35% on the left rail at A2 916 + 98. WMATA must repair narrow gauge at A2 712-+71. WMATA must repair narrow gauge at A2 798 + 55. 		

Inspection Form

Form FTA-IR-1

Agency/Department Information

Federal Transit Administration

, Beney, Department mon										
Increation Date	YYYY	MM	DD	Depart Number	20161120 14/1	4 A T A \A/	/D 1			
Inspection Date	2016	11	29	Report Number	20101129-001	20161129-WMATA-WP-1				
Rail Agency Name	Washington Authority	Metropolitar	n Area Transit	Rail Agency Department	Track Sub- Department					
	1	Name		Email	Office Phone	e	N	1obile Phone		
Rail Agency Department Contact Information										
Inspection Location	D and G Junc	tion (D98) to	Potomac Ave. (E	007)						
Inspection Summary										
Inspection Activity #	1		2	3	4	1	5	6		
Activity Code	TRK-JSB	-OBS	TRK-WI-PI							
Inspection Units	1		1							
Inspection Subunits	1		1							
Defects (Number)	0		2							

Activity Summaries

Recommended Finding

Remedial Action Required¹

Recommended Reinspection

No

No

No

Yes

Yes

Yes

Inspection Activity #	1	Inspection Sub	ject	Job 9	Safety Bri	efing			Activity Co	de	TR	K	JSB	OBS
Job Briefing Employee Name/Title	TRST 5	5			Accompanied Inspector?		Yes	Out Brief Conducted	No	Time	120 150		Outside Shift	No
Related Reports	N/A				Rela	ted CAPS	/ Findings	N/A						
	Ref			Rule o	or SOP		Standard	Other / T	itle		Checl	klist Refer	ence	
Related Rules, SOPs, Standards, or Other	RWPN	1												
	MSRP	Н												
Increation Location	Mair Trac	Yard	Stat	ion	OCC	RTA Facility	FTA Office	Trock Turne	At-grade	e Tu	nnel	Elev	vated	N/A
Inspection Location	x							Track Type			х	х		
Line(a)		Track		1		Chain N	arker		From				То	
Line(s)	D	Numb	er	1		and/or	Station(s)	D and G Junct	tion (D98) Potomac Ave. (D07)					
Makida a	Hea	d Car Number		Numb	er of Cars			N1/A						
Vehicles		N/A		I	N/A	Equ	ipment	N/A						
									Number	of Defect	s			0
	TRST 5 provided a comprehensive job safety briefing to the work gang prior to accessing the right of way (ROW) at the D and G Junction. The briefing outlined the No											No		
Description		imits of the insp						0	Remedia	l Action F	Require	d?		No
	Warning with Foul Time in red areas), the required personal protection equipment (PPE), a review of hotspots, and a review of hazards which would be encountered on the ROW. TRST 5 inspected all employees and FWSO members to ensure all									No				

Inspector in Charge - Signature			Date
WINSLOW L. PC	WELL	Digitally signed by WINSLOW L POWELL DN: c=US, o=US. Government, ou=DOT Headquarters, ou=FTAHQ, cn=WINSLOW L POWELL Date: 2016 12:04:33 - 05'00'	
Inspector in Charge – Name	Inspection Team		
Winslow Powell	Chad Broski, Mike	e Vitale	



Remedial Action N/A Inspection Activity II 2 Inspection Subject Remedial Action Verification Activity Code THK WI PI Job Briefing Employee Name/Tritle TSST 5 Accompanied inspector Yes Out Briefing Conducted No Tme 1200- 1500 Outside Shift No Related Reports N/A Related CAPS / Findings N/A Tme 1200- 1500 Shift No Related Reports N/A Related CAPS / Findings N/A N/A Description Detection Status Ofter / Title Detection Status Related Reports N/A Related Reports N/A Chain Marker and/or Statuon() Ofter / Title Detection Status Detection Status N/A Une(s) p Track Yard Status OCC Relation () Data G Junction ()28) Potomac Ave. ():027) Vehicles N/A N/A N/A N/A Recommended Finding? Yes PVSO performed a track inspection from the D and G junction ()98) to the Potomac Ave. Status to follow up on open remedial action 752, requirements for speed remedial action 752, requirement for Coll 22:400 and D1 Coli 22:400 and				E was in pl with the b		that al	I RWP t	raining was	current. No	exceptions						
Job Briefing Employee Tist 5 Accompanied Inspector? Yes Out Briefi Conducted No Time 1200- 1500 Outside Shift No Related Reports N/A Rel regords N/A Related CAPS / Findings N/A No Time 1200- 1500 Outside Shift No Related Rules, SOPs, Standards, or Other Rel Rule or SOP Standard Other / Title Checklist Reference Inspection Location Max Track Yard Station OCC RTA FTA FTA Track Type At grade Tunnel Elevated N/A Line(s) D Track 1 Chain Marker ma/or Station(s) D and G Junction (D98) Potomac Ave. (D07) Vehicles Head Car Number Number of Cars Equipment N/A N/A Recommended Finding? Yes SafeTrack sarge. FWSO performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to folow up on open remedial action 52, requiring WMATA to secure safety catvalk panels on the aerial structure at the D and J CM212400. Nome of Defects 2 PWSO used remedial action 52, FWSO noted several SW-31 fasteners which will need to be ropaced from D1 2024200 to D1	Remedial Action															
Employe RETS 5 Accompaned Particle Yes Out Brief Conducted No Time 1200- 1200 Outside Shift No Related Report N/A Related Report Related Action Particle No Time 1200- 1200 Outside No Related Rules, SOP Standards, or Other Ref Rule or SOP Standard Other / Title Checklist Reference Main Inspection Location Main X Yard Station OCC RTA Relative / Office Track Type At grade Tunnel Elevated N/A Une(s) D Track Number 1 Chain Marker and/or Station(s) Track Type Potomac Ave. (D07) Vetomac Ave. (D07) Vehicle N/A N/A Rumber of Cars Equipment N/A Recommended Finding? Yes SafeTrack Surge. FWSO performat artack inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open emedial action 252, requiring WMATA to secure safety catwalk panels on the aerial structure at the D and G junction. N/A Recommended Finding? Yes Description FWSO descreption the arelos 22, which requiried W	Inspection Activity #	2	Inspe	ection Subj	ect	Remedi	ial Actic	n Verificati	on		Activity Co	de	TR	K	WI	PI
Related Rules, SOPS Standards, or Other Standard, or Other Standar	Employee	TRST	5					•	Yes		No	Time	-			No
Related Rules, SOPs, Standards, or Other PWPM Image: Control of the second	Related Reports	N/A					Relat	ed CAPS / I	Findings	N/A						
Standards, or Other MVMM Main Yard Station OCC RTA Pacifity FTA Office Track Type At-grade Tunnel Elevated N/A Inspection Location D Track Varid Station OCC RTA Pacifity FTA Office Track Type At-grade Tunnel Elevated N/A Une(s) D Track Number 1 Chain Marker and/or Station(s) D and G Junction (D98) D and G Junction (D98) Potomac Ave. (D07) Vehicles Head Car Number Number of Cars Equipment N/A N/A Equipment N/A PWSO performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open remedial action from the D and G junction. N/A N/A Recommended Finding? Yes FWSO performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open remedial action 52, requiring WMATA to secure safety from the base between D1 CM321490 and D1 CM221400. N/A Recommended Finding? Yes Description FWSO also closed remedial action 52, requiring WMATA to sing and Close the rail share to move the rail from the BOW, and it is still in place in this location. Additional/WATA V/YSO wano the tradist share to move the rail and c		Ref			F	Rule or S	SOP		Standard		Other / T	tle		Check	list Refere	ence
MSRPH Main Inspection Location Track Main Track Yard Station OCC RTA Facility Office FTA Office Track Type At-grade Turnel Elevated N/A Line(s) p Track Number 1 Chain Marker and/or Station(s) Track Type At-grade Turnel Elevated N/A Vehicles N/A Number of Cars Number of Cars Fujionent N/A Fujionent N/A Vehicles N/A N/A N/A Fujionent N/A Recommended Finding? Yes SafeTrack surge. - FWSO located remedial action 752, requiring WMATA to scure safety catwalk panets on the aerial structure at the D and G junction N/A Number of Defects 2 PWSO performed bias to able to close remedial action 752, requiring WMATA to scure safety catwalk panets on the aerial structure at the D and G iunction N/A Number of Defects 2 PWSO performed bias to able to close remedial action 752, requiring WMATA to scure safety catwalk panets on the aerial structure at the D and G iunction N/A Number of Defects 2 PWSO performed action XBU MMATA to scure safety catwalk panets on the aerial structure at the D and G iunction N/A Number of Defects 2 Description - FWSO located remedial action 252, whicho the OWATA to mitigate numerous stud bolts that are locate catw		RWPN	N													
Inspection Location Track Varid Station OCC Facility Office Track Type At-grade Tunnel Elevated N/A Line(s) D Track N/A Image: Station Static Static Station Static Statis Static Static Static Static Statis Static Static S		MSRP	н													
X Track Number 1 Chain Marker and/or Station(s) From X X Uehicles Head Car Number N/A Equipment N/A N/A Potomac Ave. (D07) Vehicles Head Car Number N/A Equipment N/A N/A PWSD performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station follow up on open remedial actions from the previous SafeTrack surge. N/A N/A N/A PWSD beformed a track inspection from the D and G junction (D98) to the Potomac Ave. Station follow up on open remedial action structure at the D and G junction. N/A N/A Perform the base between D1 CM321490. Ferom the base between D1 CM321490. N/A Recommended Finding? Yes Potomac Ave. Station to follow up on open remedial action 752, requiring WMATA to secure safety catwalk panels on the aerial structure at the D and G junction. Number of Defects 2 POtomac Ave. Station to able to close remedial action 753, which required WMATA to remover all from the ROW from D1 CM 221400 to D 1 CM 191400. FWSO vas not able to close remedial action 793, which required WMATA to remover all from the ROW from D1 CM 221400 to D 1 CM 191400. FWSO overfiled that WMATA has not removed the rail from the ROW, and it is still in place in the location. Recommended Reinspection? Additional/br. FWSO associated to be replaced from D1 268400 to the end of the aerial structure. N/A N/A • While following up on remedial action 822, FWSO noted sev	Inspection Location			Yard	Statio	n (осс			Track Type	At-grade	- Tui	nnel	Elev	ated	N/A
Line(s) D Number 1 Line(s) D and G Junction (D98) Potomac Ave. (D07) Vehicles Head Car Number Number of Cars Equipment N/A N/A N/A Vehicles N/A N/A N/A N/A N/A N/A FWSO performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open remedial actions from the previous SafeTrack surge. FWSO closed remedial action 752, requiring WMATA to secure safety catwalk panels on the aerial structure at the D and G junction. Number of Defects 2 FWSO sol closed remedial action 752, requiring WMATA to secure safety catwalk panels on the aerial structure at the D and G junction. FWSO sol closed remedial action 752, related to improperly installed stud bots in sporadic locations between D1 202+00 and D1 CM212+00. Remedial Action Required? Yes Description FWSO was not able to close remedial action 793, which required WMATA to remover there and action 793, which required WMATA to remover there and the rail from the ROW, and it is still in place in this location. Recommended Reinspection? Recommended Reinspection? Additional observations: While following up on remedial action 822, FWSO noted several SW-31 fasteners which will need to be replaced from D1 268+00 to the end of the aerial structure. A to 11 189+00, FWSO noted two instanc																
Vehicles Head Car Number N/A Number of Cars N/A Equipment N/A FWSD performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open remedial actions from the previous SafeTrack surge. N/M Number of Defects 2 FWSD performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open remedial actions from the previous SafeTrack surge. Number of Defects 2 FWSD closed remedial action 752, requiring WMATA to secure safety catwalk panels on the aerial structure at the D and G junction. Remedial Action Required? Yes FWSO also closed remedial action 752, requiring WMATA to mitigate numerous stude bolts that are loose/exceeding the 3" height from the base between D1 CM321+80 and D1 CM212+00. Remedial Action Required? Yes Obscription FWSO was not able to close remedial action 793, which required WMATA to remover ail from the ROW from D1 CM 221+00 D1 CM 191+00. FWSO verified that WMATA has not removed the rail from the ROW, and it is still in place in this location. Recommended Reinspection? Additional observations: While following up on remedial action 822, FWSO noted several SW-31 fasteners which will need to be replaced from D1 268+00 to the end of the aerial structure. At D1 189+00, FWSO noted two instances of a bundle of cable secured to the pull bar for the safety catwalk. This obstructs a track walker's ability to safety clear the ROW. Finally, the work group reported a pull apart in the thridr ai	Line(s)															
Vehicles N/A N/A Equipment N/A FWSO performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open remedial actions from the previous SafeTrack surge. Number of Defects 2 FWSO closed remedial action 752, requiring WMATA to secure safety catwalk panels on the aerial structure at the D and G junction. Remedial Action Required? Yes FWSO also closed remedial action 752, requiring WMATA to mitigate numerous stud bolts that are loose/exceeding the 3" height from the base between D1 CM321+80 and D1 CM212+00. FWSO also closed remedial action 725, related to improperly installed stud bolts in sporadic locations between D1 202+00 and D1 206+00. While this condition does not meet WMATA's requirements for speed restriction, the quality of work in this area should be examined and corrections should be made. Recommended Reinspection? Additionally, FWSO was not able to close remedial action 725, related to improperly in fraguler dWMATA to remover all from the ROW from D1 CM 221+00 to D1 CM 191+00. FWSO verified that WMATA has not removed the rail from the ROW, and it is still in place in this location. Recommended Reinspection? Additional observations: While following up on remedial action 822, FWSO noted several SW-31 fasteners which will need to be replaced from D1 268+00 to the end of the aerial structure. At D1 189+00, FWSO noted two instances of a bundle of cable secured to the pull bar for the safety catwalk. This obstructs a track walker's ability to safety cater the ROW. Finally, the work group reported a pull apart in the third rail just		Number and/or Station(s) D and G Junction (D98) Potomac Ave. (D07)														
PWS0 performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open remedial actions from the previous SafeTrack surge. Recommended Finding? Yes • FWS0 closed remedial action 752, requiring WMATA to scure safety catwalk panels on the aerial structure at the D and G junction. Pws0 Yes • FWS0 also closed remedial action 822, which required WMATA to mitigate numerous stud bolts that are loose/exceeding the 3" height from the base between D1 CM321+80 and D1 CM212+00. Yes • FWS0 was not able to close remedial action 725, related to improperly installed stud bolts in sporadic locations between D1 202400 and D1 206+00. While this condition does not meet WMATA's requirements for speed restriction, the quality of work in this area should be examined and corrections should be made. Recommended Reinspection? • Additionally.FWS0 was not able to close remedial action 793, which required WMATA to remove rail from the ROW from D1 CM 221+00 to D1 CM 191+00. FWS0 werified that WMATA has not removed the rail from the ROW, and it is still in place in this location. • While following up on remedial action 822, FWS0 noted several SW-31 fasteners which will need to be replaced from D1 268+00 to the end of the aerial structure. At D1 189+00, FWS0 noted two instances of a bundle of cable secured to the pull bar for the safety catwalk. This obstructs a track walker's ability to safely clear the ROW. Finally, the work group reported a pull apart in the third rail just outside the Potomac Ave. station platform on track 1. TRST 5 notified the Raii Operations Control Center (ROCC) and instituted a 15 mile per hour	Vehicles	Неа	Equipment N/A													
	Description	N/A N/A FWSO performed a track inspection from the D and G junction (D98) to the Potomac Ave. Station to follow up on open remedial actions from the previous SafeTrack surge. Number of Defects • FWSO closed remedial action 752, requiring WMATA to secure safety catwalk panels on the aerial structure at the D and G junction. Remedial Action Required? • FWSO also closed remedial action 822, which required WMATA to mitigate numerous stud bolts that are loose/exceeding the 3" height from the base between D1 CM321+80 and D1 CM212+00. Remedial Action Required? • FWSO was not able to close remedial action 795, related to improperly installed stud bolts in sporadic locations between D1 202+00 and D1 206+00. While this condition does not meet WMATA's requirements for speed restriction, the quality of work in this area should be examined and corrections should be made. Recommended Reinspection? • Additionally, FWSO was not able to close remedial action 793, which required WMATA to remove rail from the ROW from D1 CM 221+00 to D1 CM 191+00. FWSO verified that WMATA has not removed the rail from the ROW, and it is still in place in this location. Recommended Reinspection? Additional observations: • While following up on remedial action 822, FWSO noted several SW-31 fasteners which will need to be replaced from D1 268+00 to the end of the aerial structure. At D1 189+00, FWSO noted two instances of a bundle of cable secured to the pull bar for the safety catwalk. This obstructs a track walker's ability to safely clear the ROW.										Yes Yes				



Photos:



Bundle of cables stored on safety walk at D1 198+00





Rail Break noted just outside the Potomac Ave. station



FOIA Exemption: All (b)(6)

Form FTA-IR-1

Agency/Department Information

Federal Transit Administration

In a station Date	YYYY	MM	DD	Dement Number	20161120 14/	4 A T A \A	(D 2		
Inspection Date	2016	11	29	Report Number	20161129-WN	/1A1A-W	VP-Z		
Rail Agency Name	Washington Authority	Metropolita	n Area Transit	Rail Agency Department	TRST	Sub- Dep	artment	Productio	on
Dell Annua Deventurent	Name Email Office Phone								ne
Rail Agency Department Contact Information									
Inspection Location	Surge 11, K-L	ine – Track ‡	#1 – East Falls Chu	rch (EFC) to West Falls	Church (WFC)				
Inspection Summary									
Inspection Activity #	1		2	3	4		5		6
Activity Code	TRK-GE	N-OBS	TRK-RWP-OBS						
Inspection Units	1		1						
Inspection Subunits	1		2						
Defects (Number)	0		0						
Recommended Finding	Nc)	No						
Remedial Action Required ¹	Nc)	No						
Recommended Reinspection	No)	No						
Activity Summaries		·							
Increation Activity # 1	Increation Su		ack Conoral Obcor	wations	Activity Co	do	TPK	GEN	0

Inspection Activity #	1	Inspection Sub	ject	Track Ge	eneral C	Observatior	IS		Activity Co	de	TRK		GEN	OBS
Job Briefing Employee Name/Title	Track Unit #6014 provided the briefing Mobile Command Center (MCC) was the RWIC SAFE Unit #203 provided the Escort				Inspector? No Condu		Out Brief Conducted	No	Time	133 160	-	Outside Shift	No	
Related Reports					Relate	ed CAPS / I	indings							
	Ref			Rule or S	ОР		Standard		Other / T	itle		Check	dist Refer	ence
Related Rules, SOPs, Standards, or Other	MSRPI	Н		4.159										
Standards, or other	TRST 1	.000												
	Mair Tracl	Yard Station			occ	RTA Facility	FTA Office		At-grade	e Tui	nnel	Elev	rated	N/A
Inspection Location	х							Track Type	x					
line (a)	K-Line	Track		1		Chain Ma	rker		From			1	То	
Line(s)	K-Line	Numb	er	1		and/or St	ation(s)	K1 CM405+78			K1 CN	/443+0	0	
	Head	d Car Number		Number c	of Cars									
Vehicles		N/A		N/A		Equip	ment	N/A						
Description	_					1		1	Number	of Defect	s			0
	Conce		r arriv	ed on the	nlatforr	m four (4)	compressed	as cylinders	Recomm	ended Fir	nding?			No
	vvnen	When FWSO inspector arrived on the platform, four (4) compressed gas cylinders Remedial Action Required? No											No	

Inspector in Charge - Signature WINSLOW L. PO	Digitally signed by WINSLOW L POWELL DN: c=US, o=US. Government, ou=DOT Headquarters, ou=FTAHQ, cn=WINSLOW L POWELL Date: 2016.12.06 13:25:46-05'00'	Date
Inspector in Charge – Name Winslow Powell	Inspection Team Robert Maniuszko	



were observed standing on the platform without being properly secured. Two (2 the cylinders were Oxygen and two (2) were Acetylene. These cylinders were located next to each other without proper separation. (See photo below.) WMA MSRPH Rule 4.159 states, "Oxygen/fuel gas and liquids cylinders shall be positio and secured so as to prevent their being struck by moving equipment, or coming contact with the third rail or other electrical circuits." In addition, OSHA 1910.25 (4)(iii) states, "Oxygen cylinders in storage shall be separated from fuel-gas cylinders or combustible materials (especially oil or grease), a minimum distance 20 feet". SAFE unit #203 immediately notified the Mobile Command Center and the gang leader was notified. The gang leader was aware of the requirement to separate cylinders but had been out on the roadway and did not witness the cylinders. General Observations: • WMATA was observed replacing crossties, fasteners, and tie plates. • The workers were also replacing third rail cover boards as well a re-gaging the rails. • All of the rail stringers scheduled for replacement on track #1 were in place at the time of the visit. WMATA plans to de-stress the rails Thursday, December 1, 2016. • The FWSO inspector noted a number of "non-conforming" crossies i the work zone. WMATA has not provided documentation that these belong on mainline track. Per the	ATA aned g in 53 e of the ing g as as a h h ties d, a	No
---	---	----

Inspection Activity #	2	Inspection	Subject	: RV	/P Ge	eneral Ob	oservation	5		Activity Co	de	TR	K	RWP	OBS	
Job Briefing Employee Name/Title	briefing Mobile was the	Jnit #6014 p g c Command e RWIC Init #203 pr	Center	(MCC)	CC) Accompanied No			Out Brief Conducted	No	Time	133 160	-	Outside Shift	No		
Related Reports	Related CAPS / Findings															
	Ref Rule or SOP Standard Other / Title										itle		Cheo	cklist Refer	ence	
Related Rules, SOPs, Standards, or Other	MSRPH	ł	4.90													
Standards, or other	RWPM															
luce estimate antice	Track		tation	C	DCC	RTA Facility	FTA Office	Treads Treas	At-grade	e Tur	nnel	Ele	evated	N/A		
Inspection Location	x								Track Type	х						
Line(s)	K-Line	Tra	ick mber	1			Chain Marker and/or Station(s) K1 CM405+			From		K1 CN	To K1 CM443+00			
	Head	l Car Numb	er	Num	iber c	of Cars										
Vehicles		N/A			N/A		Equip	ment	N/A							
			·							Number	of Defect	s			0	
	Concerns:									Recomm	ended Fir	nding?			No	
Description	•		unt stra	p at the	e east	end of t	he work a	rea was not o	connected.	Remedia	l Action R	equire	d?		No	
		· ·		'		nit #203 as requi		Iobile Comm	and and the	Recommended Re-inspection? No					No	

Photos:



Figure 1 - Un-secured Oxygen CGC alongside Un-secured Acetylene CGC





Figure 2 - K1 CM417+40 - 7 1/2" Crosstie



Figure 3 - Shunt Strap not attached at East End of the Work Zone





Figure 3 - RWP Work Zone Set-up - East End of Work Zone



Figure 4 - Roadway Maintenance Machines - properly chocked



Agency/Department Information

Federal Transit Administration

Agency/Department mom	lation											
Increation Date	YYYY	MM	DD		Report Number	20161120 14/04070 14/0 1						
Inspection Date	2016	11	3	30		20161130-WMATA-WP-1						
Rail Agency Name	Washington Authority	Metropolita	an Area Tra	ansit	Rail Agency Department	Track	Sub- Department					
		Name			Email	Office Phone	e	Mobile Phone				
Rail Agency Department Contact Information												
Inspection Location	Pentagon Cit	y to Nation	al Airport									
Inspection Summary												
Inspection Activity #	1		2		3	4	5	6				
Activity Code	TRK-JSB-OBS		TRK-WI-PI									
Inspection Units	1		1									
Inspection Subunits	1		1									
Defects (Number)	0		2	2								
Recommended Finding	Nc)	Ye	es								

Activity Summaries

Remedial Action Required¹

Recommended Reinspection

No

No

Yes

Yes

Inspection Activity #	1	Inspe	ection Subj	ject	Job	Safet	y Brief	ing			Activity Co	de	TR	K	JSB	OBS	
Job Briefing Employee Name/Title	TRST	5					Accor Inspe	npanied ctor?	Yes	Out Brief Conducted	No	Time	110 123	-	Outside Shift	No	
Related Reports	N/A						Relate	ed CAPS / F	indings	N/A							
	Ref	Ref Rule or					SOP Standard			Other / T		Cheo	cklist Refe	rence			
Related Rules, SOPs, Standards, or Other																	
	MSRP	Ή															
Increation Location	Maii Trac		Yard	Stat	tion	00	сс	RTA Facility	FTA Office	Track Tures	At-grade	e Tu	nnel	Ele	evated	N/A	
Inspection Location	x									Track Type			х		х		
Lino(a)	C Track 1							Chain Mar			From				То		
Line(s)	Number			er	and/			and/or Sta	/or Station(s) Pentagon City			(C08) Natio			onal Airport (C10)		
Mahtaha a	Hea	ıd Car	Number		Numb	per of	Cars			N1/A							
Vehicles	N/A N/A Equipment N/A																
		_									Number	of Defect	s			0	
Description		TRST 5 provided a comprehensive job safety briefing to the work gang prior to accessing the right of way (ROW) at Pentagon City. The briefing outlined the work limits of the inspection, the protection that would be used (Train Approach										ended Fi		No			
												l Action F		No			
	(PPE),	, a revi	iew of hots	pots,	and a	revie	w of h	azards that		ve Equipment acountered on sure all	Recommended Reinspection?					No	

Inspector in Charge - Signature WINSLOW L. POWEL	Digitally signed by WINSLOW L. POWELL DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FTAHQ, cn=WINSLOW L. POWELL Date: 2016.12.06 13:18:56-05'00'	Date
Inspector in Charge – Name Winslow Powell	Inspection Team Chad Broski, Mike Vitale	



Remedial Action N/A Inspection Activity # 2 Inspection Subject Remedial Action Verification Activity Code TRK WI PI Job Briefings Employce Name/Title TRST 5 Accompanied inspector? Yes Out Brief Conducted No Time 1100- 1220 Outside No Related Reports N/A Related CAPS / Findings N/A Related Rules of SOP Standards, or Other N/A Related Rules of SOP Standards, or Other No Time 1100- 1220 Outside No Inspection Location Main Track Yard Station OCC RTA Facility FTA Facility FTA Office Track Type At grade Tunnel Elevated N/A Uine(s) C Track Number of Cars Inspection Cars Equipment N/A National Airport (C10) Vehicles Head Car Number Number of Cars Equipment N/A Recommended Finding? Yes • FWSO Discover on stable to close remedial action 879, which required MAIA to repair compromised from the proviso SafeTack sugar. Number of Defects 2 • FWSO Closed remedial action 879, which required MAIA to repair compromised from the proviso SafeTack sugar. Number of Defects 2 • FWSO Closed remedial action 879, which required MAIA to repair compromised from		-	PPE was in pla en with the bri			RWP tr	aining was	current. No	exceptions							
Lob Briefing Employee Name/Title Tist 5 Accompanied Inspector? Yes Out Brief Conducted No Time 1100- 1230 Dutside Shift No Related Roports N/A Related CAPS / Findings N/A NA Related CAPS / Findings N/A Related Rules, SOPs, Standards, or Other Ref Rule or SOP Standard Other / Title Checklist Reference NMSRPH Main Yard Station OCC RTA FTA Checklist Reference N/A Main Yard Station OCC RTA FTA Checklist Reference N/A Inspection Location Track Yard Station OCC RTA PTA At grade Tunnel Elevated N/A Une(s) C Track Number of Cars Equipment N/A N/A X	Remedial Action	N/A														
Employe TST 5 Accompand percent Yes Out Frier Out Frier No No Time 110.0- 1230 Outside Shift No Related Routs, SDPs, Standards, or Other Track N/A Rele or SDP Standard V/A Other / Title Checklist Reference Main Track Yard Station OCC RTA Pacinity FTA Pacinity Office Track Type At-grade Tunnel Elevated N/A Imspection Location C Track Number of Cars OCC RTA Pacinity Price Track Type At-grade Tunnel Elevated N/A Vehicles C Track Number of Cars 1 Chain Marker and/or Station(S) From To To Vehicles Head Car Number Number of Cars Equipment N/A N/A Equipment N/A FWSO performed a track inspection from Pentagon City (COS) to National Airport (C10) to follow up on open remedial actions from the previous Saffrack surge. Compromised third rail section between chain marker C1 302+85 and 302+97. N/A Z FWSO also was able to close remedial action 873, which required WMATA to repair compromised grout pads from C1303+98 to 312+10. FWSO also was able to close remedial action 874, which required Yes FWSO performed a track is reserved or ophysics speed restriction, WMATA to repair compromised grout pads from C1303+98 to	Inspection Activity #	2 Ins	pection Subje	ect	Remedia	al Actio	n Verificati	on		Activity Co	de	TR	RK	WI	PI	
Related Rules, SOPs, Standards, or Other Ref Rule or SOP Standards Other / Title Checklist Reference Inspection Location Main Track Yard Station OCC RTA Facility FTA Office Track Type At-grade Tunnel Elevated N/A Line(s) C Track Number Number of Cars Equipment N/A N/A N/A Vehicles N/A N/A N/A Equipment N/A N/A FWSO performed a track inspection from Pentagon City (C08) to National Airport (C10) to follow up on open remedial action 876, which required WAATA to replace a 302+97. FWSO also was able to close remedial action 873, which required WMATA to replace compromised group task from C1 303+98 to 121-10. Number of Defects 2 Pescription FWSO losed remedial action 890, which required WMATA to replace a 302+97. FWSO also was able to close remedial action 874, which required WMATA to replace compromised group task from C1 303+98 to 121-10. Recommended Reinspection? Recommended Reinspection? PWSO WAG To replace compromised group task from C1 303+98 to 132+10. FWSO Recording a specific striction, WMATA to replace adfective fastener underneath the third rail end approach at C1 357-951. FWSO Noted there expansion cables that were secured to a fiberglas	Employee	TRST 5		- Yes				No	Time				No			
Related Rules, SOPs, Standards, or Other MWPM Marker RTA FTA Office Track Type At-grade Tunnel Elevated N/A inspection Location Track Yard Station OCC RTA FTA Office Track Type At-grade Tunnel Elevated N/A tine(s) C Track N/A Chain Marker Track Type To To Vehicles Head Car Number Number of Cars Equipment N/A Stational Airport (C10) N/A N/A Stational Airport (C10) N/A Stational Airport (S10) N/A <td></td> <td>N/A</td> <td></td> <td></td> <td></td> <td>Relate</td> <td>ed CAPS /</td> <td>Findings</td> <td>N/A</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>		N/A				Relate	ed CAPS /	Findings	N/A							
Standards, or Other NWP-M Image: Constraint of the standards of	Palatad Bulas, CODs	Ref Rule or SOP Standard Other / Title Checklist									list Refer	ence				
Main Track Yard Station OCC RTA Facility FTA Office Track Type At-grade Tunnel Elevated N/A tine(s) C Track Number 1 Chain Marker and/or Station(s) Track Type X X X Vehicles		RWPM														
Inspection Location Track Yard Station OCC Facility Office Track Type Af-grade Tunnel Elevated N/A Line(s) C Track Varid I Image: Comparison of the second																
X Track Number 1 Chain Marker and/or Station(s) From X X Une(s) C Track Number 1 Chain Marker and/or Station(s) From To Vehicles Head Car Number Number of Cars Equipment N/A N/A FWSO performed a track inspection from Pentagon City (C08) to National Airport (C10) to follow up on open remedial actions from the previous SafeTrack surge. compromised third rail section between chain markers C1 302+85 and 302+97. Number of Defects 2 FWSO losed remedial action 850, which required WMATA to replace a compromised third rail section between chain markers C1 317+75 to C1 330+35. Number of Dafects 2 Percedual Action 860, which required WMATA to replace a defective fastener underneath the third rail and approach at C1 355+00. Stense remedial action 873, which required WMATA to replace a defective fastener underneath the third rail and approach at C1 355+00. FWSO was not able to close remedial action 874, which requires WMATA to repair compromised grout pads from C1 303+98 to 312+10. FWSO noted three expansion cables that were secured to rails scalar ba our new grout pads still in place without new materials poured in them. While inspectors did not note a condition requiring a speed restriction, WMATA should return to this area to complete this work. Recommended Reinspection? Additional observations: • FWSO noted three expansion cables that were secured to rails and Airpot (C10). These bolts, located at chain marker 361-00, wer			Yard	Static	on C	СС				At-grade	e Tu	nnel	Elev	ated	N/A	
Line(s) C Number 1 Induct Station(s) Pentagon City (C08) National Airport (C10) Vehicles Vehicles N/A N/A Equipment N/A FWSO performed a track inspection from Pentagon City (C08) to National Airport (C10) to follow up on open remedial actions from the previous SafeTrack surge. N/A N/A Recommended Finding? Yes FWSO closed remedial action 856, which required WMATA to replace a compromised third rail section between chain markers C1 302+85 and 302+97. Number of Defects 2 Remedial Action 876, which required WMATA to replace a defective fastener underneath the third rail end approach at C1 355+00. Finally, FWSO closed remedial action 873, which required WMATA to replace a defective fastener underneath the third rail end approach at C1 355+00. FWSO was not able to close remedial action 874, which required WMATA to replace a defective fastener underneath the third rail end approach at C1 355+00. FWSO inspectors observed wooden forms used to pour new grout pads from C1 303+98 to 312+10. Recommended Reinspection? Recommended Reinspection? OVEND of a complicity of this required optical action 874, which required to the complicity of the spect restriction, WMATA should return to this area to complete this work. FWSO Noted three expansion cables that were secured to a fiberglass cham at 312+95. 1 of 4 cables are secured to a fiberglass cham at 312+95. 1 of 4 cables ar	Inspection Location	x							Track Type		x x			×		
Number Number and/or Station(s) Pentagon City (C08) National Airport (C10) Vehicles Head Car Number Number of Cars Equipment N/A N/A FWSO performed a track inspection from Pentagon City (C08) to National Airport (C10) to follow up on open remedial actions from the previous SafeTrack surge. N/A Recommended Finding? Yes FWSO closed remedial action 896, which required WMATA to replace a compromised third rail section between chain markers C1 302+85 and 302+97. FWSO also was able to close remedial action 873, which required WMATA to replace a defective fastener underneath the third rail end approach at C1 35+00. FWSO losed remedial action 850, which required WMATA to replace a defective fastener underneath the third rail end approach at C1 35+00. FWSO inspectors observed wooden forms used to pour new grout pads still in place without new materials poured in them. While inspectors did not note a condition requiring a speed restriction, WMATA hourd a fiberglass kindoff strut using zip ties, rather than the standard fiberglass clama at 312+95. 1 of 4 cables are secured to a fiberglass kindorff strut using zip ties, rather than the standard fiberglass clama at 312+95. 1 of 4 cables are secured correctly in the picture below. Recommended Reinspection? FWSO noted three expansion cables that were secured to a fiberglass kindorff strut using zip ties, rather than the standard fiberglass clama at 312+95. 1 of 4 cables are secured correctly in the picture below. FWSO noted several stud bolts not installed to the required depth at the crossover tracks leading into the pocket tra	Line(s)	C	Track		1					From			•	То		
Vehicles N/A N/A Equipment N/A FWS0 performed a track inspection from Pentagon City (C08) to National Airport (C10) to follow up on open remedial actions from the previous SafeTrack surge. Number of Defects 2 FWS0 closed remedial action 850, which required WMATA to replace a compromised third rail section between chain markers C1 302+85 and 302+97. Number of Defects 2 FWS0 also was able to close remedial action 873, which required WMATA to repair compromised grout pads from chain marker C1 317+75 to C1 330+35. Remedial Action Required? Yes Obscription FWS0 bays was able to close remedial action 870, which required WMATA to repair compromised grout pads from chain marker C1 317+75 to C1 330+35. Finally, FWS0 closed remedial action 874, which requires WMATA to repair compromised grout pads from C1 303+98 to 312+10. FWS0 posteors observed wooden forms used to pour new grout pads still in place without new materials poured in them. While inspectors did not note a condition requiring a speed restriction, WMATA should return to this area to complete this work. Recommended Reinspection? Additional observations: FWS0 noted three expansion cables that were secured to a fiberglass kindorff strut using zip ties, rather than the standard fiberglass clamp at 312+95. 1 of 4 cables are secured correctly in the picture below. FWS0 noted several stud bolts not installed to the required depth at the crossover tracks leading into the pocket track at National Airport (120). These bolts, located at chain marker 361-00, were installed with as	Line(s)		Number	r	<u> </u>		and/or St	ation(s)	Pentagon Cit	y (C08)		Natio	onal Airp	ort (C10)		
FWSO performed a track inspection from Pentagon City (C08) to National Airport (C10) to follow up on open remedial actions from the previous SafeTrack surge. Recommended Finding? Yes FWSO closed remedial actions 896, which required WMATA to replace a compromised third rail section between chain markers C1 302+85 and 302+97. Remedial Action Required? Yes FWSO also was able to close remedial action 873, which required WMATA to replace a defective fastener underneath the third rail end approach at C1 357+00. Yes FWSO inspectors observed wooden forms used to pour new grout pads from C1 303+98 to 312+10. FWSO inspectors observed wooden forms used to pour new grout pads still in place without new materials poured in them. While inspectors did not note a condition requiring a speed restriction, WMATA should return to this area to complete this work. Recommended Reinspection? Additional observations: FWSO noted three expansion cables that were secured to a fiberglass kindorff strut using zip ties, rather than the standard fiberglass clamp at 312+95. 1 of 4 cables are secured correctly in the picture below. Recommended Reinspection? FWSO noted several stud bolts not installed to the required depth at the crossover tracks leading into the pocket track at National Airport (C10). These bolts, located at chain marker 361+00, were installed with as	Vehicles			N			Equip	ment	N/A							
much as eight inches out of the invert, leaving just 3 of the 11 inches in the ground. While these studs were secure, the lack of depth of the stud could lead to premature failure of the stud. WMATA should revisit this	Description	Additiona	FWSO closed compromise 302+97. FWSO also w WMATA to r 317+75 to C Finally, FWS replace a de C1 355+00. FWSO was n WMATA to r FWSO inspe still in place not note a c return to thi l observations FWSO noted kindorff stru 312+95. 1 of FWSO noted crossover tra These bolts, much as eight	d reme d third vas ab repair of 1 3304 O close fective ot able repair of ctors of withou ondition s area s: I three t using f 4 cab d sever acks le locate ht inch	edial actic d rail sect alle to clos compron +35. sed remede e fastene le to closs compron observed ut new m on requir a to comp e expansin g zip ties, oles are se ral stud b eading int ed at chai nes out of these stu	on 896, tion bet e reme hised gr dial acti r under e remeo hised gr woode haterials ing a sp lete thi on cable rather ecured olts not co the p in mark f the inv uds wer	which req tween chai dial action rout pads f on 850, wh neath the dial action a rout pads f n forms us s poured ir beed restrict s work. es that we than the s correctly ir t installed f ocket tracl er 361+00, vert, leavin re secure, t	uired WMAT n markers C: 873, which r rom chain m nich required third rail end 874, which r rom C1 303+ ed to pour n them. While ction, WMAT re secured to tandard fiber tandard fiber the picture to the requir < at National were install g just 3 of th he lack of de	A to replace a 1 302+85 and equired arker C1 WMATA to l approach at equires 98 to 312+10. ew grout pads e inspectors did A should o a fiberglass rglass clamp at below. ed depth at the Airport (C10). ed with as e 11 inches in epth of the stud	Recommo						
1. WMATA must replace zip ties securing expansion cables to kindorff strut with fiberglass clamps.	Remedial Action	2.	WMATA mu chain marke			eplace s	studs not ir	nstalled to re	quired depth or	n the tracks le	eading in	to the p	oocket ti	rack from	track 1 a	



Photos:



High Studs found at C1 361+00





Expansion Cables improperly secured to fiberglass strut



FOIA Exemption: All (b)(6)

Agency/Department Inform	nation										
Inspection Date	YYYY	MM	DD	Report Number	20161130-WMATA-WP-2						
inspection Date	2016	11	30	Report Number							
Rail Agency Name	Washington Authority	Metropolitan A	Area Transit	Rail Agency Department	TRST	Sub- Dep	artment	Production			
		Name		Email	Office Phone		Ν	Nobile Phone			
Rail Agency Department											
Contact Information											
Inspection Location	Fort Totten,	Red Line, B-06									
Inspection Summary											

Inspection Activity # 4 6 1 2 3 5 **Activity Code** TRK-RWP-OBS TRK-RI-OBS Inspection Units 1 1 **Inspection Subunits** 8 2 **Defects** (Number) 0 2 **Recommended Finding** No No Remedial Action Required¹ No Yes **Recommended Reinspection** No Optional

Activity Summaries

Inspection Activity #	1	Inspection Sub	ject	Roadwa	ay Worke	er Protectio	on – Job Safe	ty Briefing	Activity Co	ode	TR	K	RWP	OBS
Job Briefing Employee Name/Title	TRST U	NIT 80			Accom Inspec	panied tor?	No	Out Brief Conducted	No	Time	220 060		Outside Shift	Yes
Related Reports					Relate	d CAPS / F	indings							
	Ref			Rule or S	OP		Standard		Other / T	ïtle		Check	list Refer	ence
Related Rules, SOPs, Standards, or Other	RWP													
	Main Track	Yard Sta		tion (220	RTA Facility	FTA Office		At-grade	e Tu	nnel	Elev	levated N/A	
Inspection Location		х						Track Type	x					
line(a)	Deditio	Track		1		Chain Ma	rker		From			То		
Line(s)	Red Line Number			1		and/or Sta	ation(s)	Red line inspe	ction Red			d line inspection		
	Head	Car Number		Number	of Cars									
Vehicles	N/A			N/A		Equipment		N/A						
					Number of Defects					0				
Description		o observation c efing was com				0	• •	Recommended Finding?					No	
	ine bli		piete		enelisive	e. ne meruu			Remedia	equire	d?		No	

¹ The rail transit agency must provide FTA with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing FTA verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge - Signature
WINSLOW L. POWELL

Digitally signed by WINSLOW L. POWELL DN: c=US, o=U.S. Government, ou=DOT Headquarters, ou=FTAHQ, cn=WINSLOW L. POWELL Date: 2016.12.06 13:22:07 -05'00' Date

Inspector in Charge – Name Winslow Powell Inspection Team Corwyn Foster, Al Nepa, Kevin McDonald



	check, type of protection, hospital locations and potential hazards. It included type of protection and procedures for when and if the TGV-01 car stops and roadway workers enter the roadway. There were no exceptions taken to this briefing.	Recommended Reinspection?	No
Remedial Action	N/A		

Inspection Activity #	2	Inspectio	on Subjeo	t	Track Ri	ding Ol	bservation			Activity Co	de	TF	RK	RI	OBS	
Job Briefing Employee Name/Title	N/A						mpanied ector?	N/A	Out Brief Conducted	N/A	Time	22 06		Outside Shift	Yes	
Related Reports						Relat	ed CAPS / I	Findings								
	Ref			R	ule or S	OP Standard				Other / Title Checkl				cklist Refer	ence	
Related Rules, SOPs, Standards, or Other	TRST 1	TRST 1000														
	Main Track	Va	Yard Station OC			осс	RTA Facility	FTA Office		At-grad	e Tunnel		Elevated		N/A	
Inspection Location	х)	ĸ	х					Track Type	x		Х	х			
Line(s)	Red Lir	ine Track Chain Marker								From				То		
Line(3)	Number I and/or Station(s) Shady Grove										Broo	kland S	Station			
Vehicles	Head	d Car Nun	nber	N	umber o	of Cars	Equip	mont	N/A							
venicles	TGV-0	1			N/A		Equip	inent								
							6 .1			Number	of Defect	s			2	
		team acc	•				Recommended Finding?					No				
		vehicle) perform rail and geometry testing between Shady Grove main line 1 to Brookland Station. The testing was primarily for rail defects and had to conducted										Remedial Action Required?				
		eds not to beed. Duri				-										
Description	1. TRST 1000, At CM 594+00 an unsecured fire extinguisher was observed lying in the walkway field side of the track. This condition was reported to a TRST work support group following TGV-01. Recommended Reinspection?													No		
	2	and t ½ an	the frog, d 55 ¾ ir	a tigh ches.	t gage c This res	onditio	on was dete	between the cted measur -service (OOS	ing between 55							
Remedial Action	N/A															

Photos:

